

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/07/2023

Submitted Date:

03/07/2023

Document Number:

702500962

FIELD INSPECTION FORM

Loc ID: 314607 Inspector Name: Burchett, Kirby On-Site Inspection: 2A Doc Num: _____

Status Summary:
 THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:
 6 Number of Comments
 1 Number of Corrective Actions
 Corrective Action Response Requested

Operator Information:
 OGCC Operator Number: 16700
 Name of Operator: CHEVRON USA INC
 Address: 760 HORIZON DRIVE STE 401
 City: GRAND JUNCTION State: CO Zip: 81506

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Kellerby, Shaun	(970) 712-1248	shaun.kellerby@state.co.us	
Sanford, Anita	(970) 551-8313	Anita.Sanford@scoutep.com	
Patterson, Chris		Chris.Patterson@scoutep.com	
Regulatory, Rangely		RangelyRegulatory@scoutep.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
229121	WELL	PR	02/01/2022	OW	103-06204	U P 12-27	PR

General Comment:

[COGCC Inspection Report Summary](#)

On Tuesday, 03/07/2023, Inspector Kirby Burchett, conducted a routine field inspection at Chevron U.S.A., Inc. (Scout Energy Partners) on the Union Pacific 12-27, Location #314607, in Rio Blanco County, Colorado. This location is within or in close proximity to a Parks and Wildlife (CPW) District with High Priority, NSO, and Density Habitat regulations.

Any Corrective Actions from previous Inspections are still applicable.

While there, I observed well has been shut in. Rod pump has been recently removed from well, shut in and equipment is moving off location. During this inspection the following compliance issues were observed:

- Continue moving equipment from location.

A follow up on this site inspection will be conducted to ensure all compliance issues have been corrected to comply with COGCC rules.

Location

Overall Good:

Signs/Marker:

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	911 / (970) 675-3700		
Corrective Action:		Date:	

Good Housekeeping:

Type	STORAGE OF SUPL		
Comment:	Maintenance just completed on well. Continue moving equipment from location.		
Corrective Action:	The storage, placement, or maintenance of equipment, vehicles, trailers, commercial products, chemicals, drums, totes, containers, materials, and all other supplies not necessary for use on an Oil and Gas Locations is prohibited.	Date:	03/27/2023

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

		#		corrective date
Type: Pump Jack		# 1		
Comment:				
Corrective Action:			Date:	
Type: Bradenhead		# 1		
Comment:	Valves are accessible. Gauge installed.			
Corrective Action:			Date:	
Type: Deadman # & Marked		# 3		
Comment:				
Corrective Action:			Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 229121 Type: WELL API Number: 103-06204 Status: PR Insp. Status: PR

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: Artificial lift removed. Well shut in.
Last production - 12/2022

Corrective Action: _____

Date: _____

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Ditches				
Ditches						
Berms						
		Berms				

Comment: Limited Stormwater inspection due to location being covered with snow.
 Sediment piles on edge of location due to snow removal.
 Oil and gas operators shall implement and maintain Best Management Practices (BMPs) at all oil and gas locations to control Stormwater runoff in a manner that minimizes erosion, transport of sediment offsite, and site degradation.
 Oil and gas operators shall implement and maintain vehicle tracking Best Management Practices (BMPs) to control potential sediment discharges from operational roads, well pads, and other unpaved surfaces.

Corrective Action: _____

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403339906	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6043491
702500963	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6043486