

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/09/2023

Submitted Date:

03/10/2023

Document Number:

690203959

**FIELD INSPECTION FORM**

Loc ID 309306 Inspector Name: COSTA, RYAN On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 10705  
Name of Operator: EVERGREEN NATURAL RESOURCES LLC  
Address: 1875 LAWRENCE ST STE 1150  
City: DENVER State: CO Zip: 80202

**Findings:**

- 7 Number of Comments
- 5 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Beardslee, Tom		tom.beardslee@state.co.us	
Pesicka, Conor		conor.pesicka@state.co.us	
Inspections, Evergreen		cogcc.evergreen@enrllc.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
291811	WELL	PR	08/09/2007	CBM	071-09369	STEPHEN 41-22	RI
301250	PIT	AC	12/23/2009		-	STEPHEN 41-22	AC

**General Comment:**

On 3/9/2023, Ryan Costa conducted a location and stormwater management inspection. See attached photos and additional details within this report.

**Location**

Overall Good:

**Signs/Marker:**

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

**Emergency Contact Number:**

Comment:	<input style="width: 95%;" type="text"/>		
Corrective Action:	<input style="width: 95%;" type="text"/>	Date:	<input style="width: 80%;" type="text"/>

**Good Housekeeping:**

Type	STORAGE OF SUPL		
Comment:	All equipment and supplies from recent operations will need to be removed.		
Corrective Action:		Date:	

Overall Good:

**Spills:**

Type	Area	Volume			
Other					
Comment:	There was frac sand observed spilled out over the ground that was not properly handled. Improper management of unused FRAC Sand.				
Corrective Action:	Immediately comply with material handling and guidance per MSDS or product data sheet. Submit document, procedures, and waste disposal manifest to COGCC field inspector. Notify area EPS within 24-hrs and report to other agencies as appropriate.				Date:
Comment:	There is oily fluid sprayed out at the wellhead onto the ground. There did not appear to be any active leak occurring during inspection.				
Corrective Action:	Immediately control and contain spills/releases and clean up per Rule 912.a.				Date:

In Containment: No

Comment:

Multiple Spills and Releases?

**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type			
Comment:			
Corrective Action:		Date:	

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
				Material Handling And Spill Prevention	Fail	

Comment: There were areas of oil stained soil from the equipment parked on location.

Corrective Action: Implement or modify BMPs for improved material handling and spill prevention. Immediate clean up, 10 days to implement improved procedures as long as no further spill or release of material.

Date: 03/20/2023

**Pits:**  NO SURFACE INDICATION OF PIT

Type: Produced Water Lined: YES Pit ID: 301250 Lat: 37.248300 Long: -104.975400

Reference Point: \_\_\_\_\_ Other: \_\_\_\_\_ Length: \_\_\_\_\_ Width: \_\_\_\_\_

**Lining:**

Liner Type: Plastic Liner Condition: Inadequate

Comment: The pit liner is degraded and inadequate and must be replaced. There was no water in the pit and pit was not in use at the time of inspection.

Corrective Action: Lack of pit liner or pit liner compromised. Comply with Rule 910. Contact COGCC EPS staff for directives.

Date: 03/13/2023

**Fencing:**

Fencing Type: Livestock Fencing Condition: Inadequate

Comment: The fence around the pit is not maintained.

Corrective Action: Comply with the fencing requirements per the 1002a rules

Date: 03/17/2023

**Netting:**

Netting Type: \_\_\_\_\_ Netting Condition: \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

Anchor Trench Present: \_\_\_\_\_ Oil Accumulation: NO 2+ feet Freeboard: YES

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403342791	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6046431">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6046431</a>
690203960	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6046430">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6046430</a>