

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/09/2023

Submitted Date:

03/10/2023

Document Number:

702500992

FIELD INSPECTION FORMLoc ID 315010 Inspector Name: Burchett, Kirby On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 10779

Name of Operator: SCOUT ENERGY MANAGEMENT LLC

Address: 13800 MONTFORT DRIVE SUITE 100

City: DALLAS State: TX Zip: 75240

Status Summary:☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

10 Number of Comments

2 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Patterson, Chris		Chris.Patterson@scoutep.com	
Sanford, Anita	(970) 551-8313	Anita.Sanford@scoutep.com	
Regulatory, Rangely		RangelyRegulatory@scoutep.com	
Kellerby, Shaun	(970) 712-1248	shaun.kellerby@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
230089	WELL	PR	10/01/2020	OW	103-07748	FEDERAL 1	PR

General Comment:**COGCC Inspection Report Summary**

On Thursday, 03/09/2023, Inspector Kirby Burchett, conducted a routine field inspection at Scout Energy Management LLC on the Federal 12-1, Location #315010, in Rio Blanco County, Colorado.

This location is within or in close proximity to a Parks and Wildlife (CPW) District with High Priority, NSO, and Density Habitat regulations.

Any Corrective Actions from previous Inspections are still applicable.

While there, observing normal operations the following compliance issues were found:

1. Well signs need updated.
 2. Chemical tank label faded and illegible.
- Refer to attached photograph for Corrective Action.

A follow up on this site inspection will be conducted to ensure all compliance issues have been corrected to comply with COGCC rules.

LocationOverall Good: ☐

Signs/Marker:			
Type	WELLHEAD		
Comment:	Well signs still identify Whiting Oil and Gas as the operator. Telephone number of current operator not displayed. Transfer of ownership was 7/15/22.		
Corrective Action:	When no associated Tank battery is present at the Oil and Gas Location, the following additional information is required on the Well sign: Name of the Operator; Telephone number at which the Operator can be reached at all times; Telephone number for local emergency services (911 where available); and The public road used to access the Well.	Date:	04/10/2023
Type	TANK LABELS/PLACARDS		
Comment:	Faded label on chemical tank. NFPA diamond is illegible.		
Corrective Action:	Containers that are used to store, treat, or otherwise handle a hazardous material and which are required to be marked, placarded, or labeled in accordance with the U.S. Department of Transportation's Hazardous Materials Regulations, will retain the markings, placards, and labels on the Container. Such markings, placards, and labels will be retained on the Container until it is sufficiently cleaned of residue and purged of vapors to remove any potential hazards.	Date:	05/15/2023

Emergency Contact Number:

Comment: 911 is the only valid number displayed.
Corrective Action addressed under Signs/Marker: Wellhead

Corrective Action: _____ Date: _____

Overall Good: ☐

Spills:			
Type	Area	Volume	
In Containment: No			
Comment: _____			
<input type="checkbox"/> Multiple Spills and Releases?			

Fencing/:			
Type	PUMP JACK		
Comment:	Expanded metal		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Square tubing		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	Valves are accessible. Gauge installed.		
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	

Type: Ancillary equipment	# 1		
Comment:	Chemical tank on plastic containment		
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	230089	Type:	WELL	API Number:	103-07748	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Rod lift Last Production - June/2022 Last Report - June/2022								
Corrective Action:								Date:	

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
				Material Handling And Spill Prevention		
		Culverts				
Gravel						
		Gravel				
		Ditches				
Ditches						
Berms						

Comment: Limited Stormwater inspection due to location being covered with snow.
Oil and gas operators shall implement and maintain Best Management Practices (BMPs) at all oil and gas locations to control Stormwater runoff in a manner that minimizes erosion, transport of sediment offsite, and site degradation.
Oil and gas operators shall implement and maintain vehicle tracking Best Management Practices (BMPs) to control potential sediment discharges from operational roads, well pads, and other unpaved surfaces.

Corrective Action:

Date: _____

Pits: ☒ NO SURFACE INDICATION OF PIT
Attached Documents
You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403343064	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6046744
702500993	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6046741