

COLORADO



99999999

ATION COMMISSION



FIELD INSPECTION REPORT

<input type="checkbox"/> NOTICE OF UNSATISFACTORY INSPECTION		1120 Lincoln Street, Suite 801 Denver, CO 80203 (303)894-2100	
<input checked="" type="checkbox"/> NOTICE OF SATISFACTORY INSPECTION			
API No. 05- <u>121 - 08626</u>		LEASE NAME: <u>Landaker</u>	
LOCATION: <u>SESW 21-35-55</u>		OPERATOR: <u>Ereter</u>	
DATE: <u>9-14-95</u>		INSPECTOR: <u>Ed Binkley (EBB)</u>	
Insp. Type: <u>SR</u>	Insp. Status: <u>DA</u>	PA: <u>Y</u> N	Pass/Fail: <u>P</u> F Viol.: Y <u>N</u> NOV: Y <u>N</u>

INSPECTION ITEM	COMMENTS	INPUT
Well ID Signs (Rule 210)		
Pits (Reserve/Production) (Rule 902, 903, 904)		
Fences (Rule 604.C.(3), 1003.A)		
Tank Battery Equipment (Rule 604)		
Fire Walls/Berms/Dikes (Rule 604)		
General Housekeeping (Rule 603.G)		
Spills (Oil/Water) (Rule 908)		
Bradenhead (Rule 207)		
Drilling Well/Workover (Rule 315)		
Surface Rehabilitation (Rule 317)	<u>Cathy</u>	
Miscellaneous		

CORRECTIVE ACTION REQUIRED:

Date Corrective Action Required By:

Date Remedied:

This report is a Notice of Inspection. The Commission requires that you correct any deficiencies shown on this report in a timely manner. Failure to comply may result in enforcement action by the Commission.

White - File Green - Operator Canary - Well Site



00416045