

FORM
INSPRev
X/20State of Colorado
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/21/2023

Submitted Date:

03/21/2023

Document Number:

702501018

FIELD INSPECTION FORM

 Loc ID 316241 Inspector Name: Burchett, Kirby On-Site Inspection 2A Doc Num: _____
Operator Information:OGCC Operator Number: 10775Name of Operator: KT RESOURCES LLCAddress: 3381 WESTBROOK LANECity: HIGHLANDS State: CO Zip: 80129**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:13 Number of Comments3 Number of Corrective Actions

-
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**Contact Information:**

Contact Name	Phone	Email	Comment
Boulger, Levin		levin@kt-res.com	
Adams, Karen	(303) 886-8733	adams@kt-res.com	
Kellerby, Shaun	(970) 712-1248	shaun.kellerby@state.co.us	
Gale, Tony	(303) 886-8733	tony@kt-res.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
259422	WELL	SI	08/01/2022	GW	103-10092	WRD WYATT 36-14	SI

General Comment:[COGCC Inspection Report Summary](#)

On Tuesday, 03/21/2023, Inspector Kirby Burchett, conducted a routine field inspection at KT Resources LLC on the WRD Wyatt 36-14, Location #316241, in Rio Blanco County, Colorado.

This location is within or in close proximity to Parks and Wildlife (CPW) High Priority/NSO/Density/Other Consultation Habitats. Any Corrective Actions from previous inspections are still applicable.

While there, observing normal operations the following compliance issues were found:

1. No labeling on chemical tank.
2. Tank containment full of liquid.
3. Stormwater BMPs lacking or not maintained.

Refer to attached photographs for Corrective Actions.

A follow up on this site inspection will be conducted to ensure all compliance issues have been corrected to comply with COGCC rules.

Location

Overall Good:

Signs/Marker:			
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	OTHER		
Comment:	Separator units include attached storage tanks. The sight glass located on the side of the unit indicates the storage tank is full of an unknown fluid. No form of labeling or markers are present to identify a potential hazard or the contents of the storage tank.		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Chemical tank labels peeled off and illegible		
Corrective Action:	Containers that are used to store, treat, or otherwise handle a hazardous material and which are required to be marked, placarded, or labeled in accordance with the U.S. Department of Transportation's Hazardous Materials Regulations, will retain the markings, placards, and labels on the Container. Such markings, placards, and labels will be retained on the Container until it is sufficiently cleaned of residue and purged of vapors to remove any potential hazards.	Date:	04/24/2023

Emergency Contact Number:	
Comment:	911 / (800) 288-0560
Corrective Action:	
	Date: _____

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No
 Comment: _____

Multiple Spills and Releases?

Equipment:			corrective date
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 2		
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 1		
Comment:	Single well		
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:	Calibration card indicates annual calibration has been done in the last year.		

Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	Valve is accessible. Bullplug installed.		
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Chemical tank on plastic containment. Containment is full. Oil and gas operators shall implement and maintain Best Management Practices (BMPs) at all oil and gas locations for materials handling and spill prevention procedures and practices implemented for material handling and spill prevention of materials used, stored, or disposed of that could result in discharges causing pollution of surface waters.		
Corrective Action:	Remove and properly dispose of liquid. Provide proper BMPs for spill prevention, handling and maintenance of equipment.		Date: 03/29/2023
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	300 BBLs	HEATED STEEL AST		
Comment:	Loadline has plug in place.				
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Other	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:	Metal with earth berm on one corner			
Corrective Action:				Date:

Venting:

Yes/No	NO
Comment:	
Corrective Action:	Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities

Facility ID: 259422 Type: WELL API Number: 103-10092 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment:

Corrective Action:

Date: _____

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Ditches						
				Material Handling And Spill Prevention	Fail	Containment full
Berms						
		Gravel				
		Ditches				
Check Dams						
		Compaction				

Comment: Location lacks stabilization. Insufficient tracking BMP at entrance to location. Oil and gas operators shall implement and maintain Best Management Practices (BMPs) at all oil and gas locations to control Stormwater runoff in a manner that minimizes erosion, transport of sediment offsite, and site degradation. Oil and gas operators shall implement and maintain vehicle tracking Best Management Practices (BMPs) to control potential sediment discharges from operational roads, well pads, and other unpaved surfaces.

Corrective Action: Provide proper BMPs to prevent sediment migration from location and lease road.

Date: 04/10/2023

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
702501019	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6058117