



Union Texas Petroleum Division
Suite 1122 Lincoln Tower
Denver, Colorado 80203

RECEIVED

AUG 19 1976

COLORADO OIL & GAS CONSERVATION COMMISSION

August 17, 1976

Colorado Oil and Gas Conservation Commission
Room 602, State Centennial Building
1313 Sherman Street
Denver, Colorado 80203

Re: MacNeill No. 2-R
SE NE Section 2-T3S-R56W
Ring Field
Washington County, Colorado

Gentlemen:

The enclosed Application for Permit to Drill the subject well as a replacement for the MacNeill No. 2 is submitted for your approval. The MacNeill No. 2 well developed a casing leak in July, 1976. We repaired the casing leak, but seriously impaired the productivity of the well. Therefore, we would appreciate your expeditious handling of this Application to Drill so that we may maintain the present lease status.

Also enclosed is a copy of the survey plat, showing this proposed well to be 100 feet south of the original MacNeill No. 2 well. Our lease consists of the following:

E/2 NE/4, SE/4, E/2 SW/4, SE/4 NW/4 Section 2
W/2 SW/4 Section 1
Township 3 South, Range 56 West, Washington County, Colorado

This new well will be 660 feet from the nearest lease line. We will begin drilling operations very shortly after receipt of your approval. We are also enclosing our check No. 12212 covering the filing and service fee.

Yours very truly,

DONALD B. WELLS
Assistant District Production Manager