



Spill to Groundwater

Graber - DNR, Nikki <nikki.graber@state.co.us>

Fri, Mar 24, 2023 at 4:19 PM

To: Craig Meis <cmeis@kpk.com>

Cc: Greg Deranleau <greg.deranleau@state.co.us>, "Leonard - DNR, Mike" <mike.leonard@state.co.us>

Bcc: Caitlin Stafford <Caitlin.Stafford@coag.gov>

Craig,

I stopped at the Sack 44-31 spill today to check on progress. The line had recently been stung with access points to the north and south. The access point to the south had groundwater at the bottom of the excavation with a visible sheen present and recently excavated heavily saturated soils that smelled heavily of hydrocarbons. Photos attached.

Based on this, the recent stinging operations have impacted groundwater. Please submit a COGCC Spill/Release Report, Form 19 with the Initial Report information as soon as practicable but not later than 72 hours per Rule 912.b.

Nikki

Sent from phone. Please excuse any typos.

3 attachments



20230324_155411.jpg
3438K



IMG_20230324_155459.jpg
1943K



IMG_20230324_152231.jpg
4054K