

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

403358835

Date Received:

03/28/2023

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 46685

Name of Operator: KINDER MORGAN CO2 CO LP

Address: 1001 LOUISIANA ST SUITE 1000

City: HOUSTON State: TX Zip: 77002

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Adamczyk, Megan

megan.adamczyk@state.co.us

General

CO2Source_Regulatory@kindermorgan.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 700300494

Inspection Date: 11/02/2022

FIR Submit Date: 11/08/2022

FIR Status: _____

Inspected Operator Information:

Company Name: KINDER MORGAN CO2 CO LP

Company Number: 46685

Address: 1001 LOUISIANA ST SUITE 1000

City: HOUSTON State: TX Zip: 77002

LOCATION - Location ID: 313575

Location Name: YC-N37N18W Number: 19SWSE County: MONTEZUMA

Qtrqr: SWSE Sec: 19 Twp: 37N Range: 18W Meridian: N

Latitude: 37.443902 Longitude: -108.871818

FACILITY - API Number: 05-083- -00 Facility ID: 224519

Facility Name: YC Number: 4

Qtrqr: SWSE Sec: 19 Twp: 37N Range: 18W Meridian: N

Latitude: 37.443902 Longitude: -108.871818

CORRECTIVE ACTIONS:

1 ☒ CA# 166007

Corrective Action: repair/maintain to comply with 1002.f (extended CA date for seasonal limitations)

Date: 04/01/2023

Response: CA COMPLETED

Date of Completion: 03/28/2023

Operator Comment: The lease road near the YC-2 and YC-4 locations has been repaired. A road grader was used to repair the subject section of road by deepening and re-establishing the ditches, which will keep runoff from crossing the road. Road base was pulled from the ditches and used to fill in the erosional scar observed during the inspection. See attached photolog.

COGCC Decision: Approved pending re-inspection

COGCC Representative: operator submitted photos show recent work, repair of erosion gully across road

COGCC Supervisor: may still need compaction/stabilization

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: JENNA EMERICK

Signed: _____

Title: EHS Specialist

Date: 3/28/2023 4:57:18 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
403358835	FIR RESOLUTION SUBMITTED
403358911	Photolog

Total Attach: 2 Files