

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

403342745

Date Received:

03/10/2023

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed  
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10651

Name of Operator: VERDAD RESOURCES LLC

Address: 1125 17TH STREET SUITE 550

City: DENVER State: CO Zip: 80202

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_

Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name

Michael Cugnetti

Phone

7208456901

Email

mcugnetti@verdadresources.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 696105732

Inspection Date: 02/10/2023

FIR Submit Date: 02/10/2023

FIR Status: \_\_\_\_\_

Inspected Operator Information:

Company Name: VERDAD RESOURCES LLC

Company Number: 10651

Address: 1125 17TH STREET SUITE 550

City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 432694

Location Name: Shull Number: 1-35-9-60 County: \_\_\_\_\_  
PAD

Qtrqtr: NENE Sec: 35 Twp: 9N Range: 60W Meridian: 6

Latitude: 40.713140 Longitude: -104.054300

FACILITY - API Number: 05-123- -00 Facility ID: 432694

Facility Name: Shull Number: 1-35-9-60  
PAD

Qtrqtr: NENE Sec: 35 Twp: 9N Range: 60W Meridian: 6

Latitude: 40.713140 Longitude: -104.054300

CORRECTIVE ACTIONS:

1 ☒ CA# 167373

Corrective Action: Control and contain spills/releases and clean up per Rule 912.a. Operator shall include photo documentation when submitting the FIRR.

Date: 02/11/2023

Response: CA COMPLETED

Date of Completion: 02/10/2023

Operator Comment: Antifreeze removed from engine containment. Rags placed in containment to absorb any free liquid that may pool. See attachments for photo documentation of Corrective Action.

COGCC Decision: Approved pending re-inspection

COGCC Representative: Approved pending re-inspection. Based on photo documentation provided, work to address the corrective action appears to have been performed. A field inspection will be conducted at a future date to evaluate compliance with COGCC rules.

2 ☒ CA# 167374

Corrective Action: Install or repair wildlife protection equipment per Rule 902.b. Operator shall install temporary exclusion devices (e.g. snow fence or similar) to exclude wildlife from coming in contact with antifreeze immediately and consider a more permanent exclusion device to prevent future contact. Operator shall include photo documentation when submitting the FIRR.

Date: 02/11/2023

Response: CA COMPLETED

Date of Completion: 02/10/2023

Operator Comment: Wildlife protection replaced on engine building. See attachments for photo documentation of Corrective Action.

COGCC Decision: Approved pending re-inspection

COGCC Representative: Approved pending re-inspection. Based on photo documentation provided, work to address the corrective action appears to have been performed. A field inspection will be conducted at a future date to evaluate compliance with COGCC rules.

#### OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Michael Cugnetti

Signed: \_\_\_\_\_

Title: Director of EHS&R

Date: 3/10/2023 9:52:16 AM

### ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
403342745	FIR RESOLUTION SUBMITTED
403342767	Corrective Action Photo Documentation
403342769	Corrective Action Photo Documentation
403342771	Corrective Action Photo Documentation
403342772	Corrective Action Photo Documentation
403342773	Corrective Action Photo Documentation
403342775	Corrective Action Photo Documentation

Total Attach: 7 Files