


# Storm Water Management and Erosion control

**Location Name: TEP ROCKY MOUNTAIN LLC BATTLEMENT MESA-67S95W /5NWSE**

**Location #: 334825**



**Location Overview**

**Section/Township/Range:**

## Storm water Management and Erosion control

**Location Name: TEP ROCKY MOUNTAIN LLC BATTLEMENT MESA-67S95W /5NWSE**

**Location #: 334825**



**North West corner of location.**



**North East corner of location.**



**South West corner of location.**



**South East corner of location.**



**Storm water Management and Erosion control**  
**Location Name: TEP ROCKY MOUNTAIN LLC BATTLEMENT MESA-67S95W /5NWSE**  
**Location #: 334825**



**Photo #9346 location lacks stabilization.**



**Photo #9437 Location lacks stabilization.**



**Storm water Management and Erosion control**  
**Location Name: TEP ROCKY MOUNTAIN LLC BATTLEMENT MESA-67S95W /5NWSE**  
**Location #: 334825**



**Photo #9440 Location lacks stabilization.**



**Photo #9446 Location lacks stabilization.**



**Storm water Management and Erosion control**  
**Location Name: TEP ROCKY MOUNTAIN LLC BATTLEMENT MESA-67S95W /5NWSE**  
**Location #: 334825**



**Photo #9448 Location lacks stabilization.**



**Photo #9453 Insufficient tracking BMP at entrance to location.**