

FORM
INSPRev
X/20State of Colorado
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/04/2023

Submitted Date:

04/04/2023

Document Number:

702501061

FIELD INSPECTION FORM

 Loc ID 315254 Inspector Name: Burchett, Kirby On-Site Inspection 2A Doc Num: _____
Operator Information:
 OGCC Operator Number: 16700
 Name of Operator: CHEVRON USA INC
 Address: 760 HORIZON DRIVE STE 401
 City: GRAND JUNCTION State: CO Zip: 81506
Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

5 Number of Comments

0 Number of Corrective Actions

Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Sanford, Anita	(970) 551-8313	Anita.Sanford@scoutep.com	
Kellerby, Shaun	(970) 712-1248	shaun.kellerby@state.co.us	
Patterson, Chris		Chris.Patterson@scoutep.com	
Regulatory, Rangely		RangelyRegulatory@scoutep.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
230503	WELL	PR	11/01/2022	OW	103-08170	AC MCLAUGHLIN 67X	PR

General Comment:[COGCC Inspection Report Summary](#)

On Tuesday, 04/04/2023, Inspector Kirby Burchett, conducted a routine field inspection at Chevron USA Inc. (Scout Energy Partners) on the A.C. McLaughlin 67X, Location #315254, in Rio Blanco County, Colorado.

This location is within or in close proximity to a Parks and Wildlife (CPW) District with High Priority and Density Habitats.

Any Corrective Actions from previous Inspections are still applicable.

While there, I observed normal production operations. During this inspection no compliance issue were observed.

No follow up inspection is required.

Location

Overall Good:

Signs/Marker:

	Type WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	911 / (970) 675-3700		
Corrective Action:		Date:	

Overall Good:

Spills:

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

					corrective date
Type: Deadman # & Marked	# 4				
Comment:					
Corrective Action:		Date:			
Type: Bradenhead	# 1				
Comment:	Valve is accessible. Gauge installed.				
Corrective Action:		Date:			

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 230503 Type: WELL API Number: 103-08170 Status: PR Insp. Status: PR

Producing Well

Comment: [Free flow](#)

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Gravel				
		Ditches				
Berms						
		Culverts				

Comment: Periodic road maintenance pulls loose sediment on to roadway creating vehicle tracking issues during wet conditions.

Oil and gas operators shall implement and maintain Best Management Practices (BMPs) at all oil and gas locations to control Stormwater runoff in a manner that minimizes erosion, transport of sediment offsite, and site degradation.

Oil and gas operators shall implement and maintain vehicle tracking Best Management Practices (BMPs) to control potential sediment discharges from operational roads, well pads, and other unpaved surfaces.

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
702501062	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6072346