

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
403370792

Date Received:
04/12/2023

FIR RESOLUTION FORM

Overall Status:

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 16700

Name of Operator: CHEVRON USA INC

Address: 760 HORIZON DRIVE STE 401

City: GRAND JUNCTION State: CO Zip: 81506

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
Katz, Aaron	(970) 765-6300	aaron.katz@state.co.us
Sanford, Anita	(970) 551-8313	Anita.Sanford@scoutep.com
Patterson, Chris		Chris.Patterson@scoutep.com
Burger, Craig	(970) 319-4194	craig.burger@state.co.us
Regulatory, Rangely		RangelyRegulatory@scoutep.com
Kellerby, Shaun	(970) 712-1248	shaun.kellerby@state.co.us

COGCC INSPECTION SUMMARY:

FIR Document Number: 702501107

Inspection Date: 04/06/2023

FIR Submit Date: 04/06/2023

FIR Status: _____

Inspected Operator Information:

Company Name: CHEVRON USA INC

Company Number: 16700

Address: 760 HORIZON DRIVE STE 401

City: GRAND JUNCTION State: CO Zip: 81506

LOCATION - Location ID: 315317

Location Name: LN HAGOOD-62N103W Number: 23NWNE County: RIO BLANCO

Qtrqr: NWNE Sec: 23 Twp: 2N Range: 103W Meridian: 6

Latitude: 40.135380 Longitude: -108.918900

FACILITY - API Number: 05-103-00 Facility ID: 230625

Facility Name: LN HAGOOD Number: A-15X

Qtrqr: NWNE Sec: 23 Twp: 2N Range: 103W Meridian: 6

Latitude: 40.135380 Longitude: -108.918900

CORRECTIVE ACTIONS:

1 CA# 169142

Corrective Action:

Date: 05/08/2023

Produce well after performing successful mechanical integrity test per Rule 417 or plug well. To maintain shut-in status, the well must be able to demonstrate ability to produce without mechanical intervention.

Response: CA COMPLETED

Date of Completion: 04/11/2023

Operator Comment: Well was returned to service prior to the MIT Requirement. Per Document # 403328762 the well was returned to production. Production Accounting has submitted the Form 7 which is currently in process to make the correction.

COGCC Decision: _____

COGCC Representative: _____

2 CA# 169143

Corrective Action: Provide proper BMPs to prevent sediment migration from location and lease road.

Date: 04/17/2023

Response: CA COMPLETED

Date of Completion: 04/11/2023

Operator Comment: Location and lease road have been repaired. See attached pictures.

COGCC Decision: _____

COGCC Representative: _____

OPERATOR COMMENT AND SUBMITTAL

Comment: _____

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Anita Sanford

Signed: _____

Title: Regulatory Analyst

Date: 4/12/2023 7:35:27 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

403370794	Pictures
-----------	----------

Total Attach: 1 Files