

# Storm Water Management and Erosion control

## Location Name: TEP ROCKY MOUNTAIN LLC KNIGHT-67S95W /5NENE


### Location #: 334626



**Location Overview: Location is located approximately 240 yards from the Colorado River.**  
**Section/Township/Range: 5 7S95W**

# Storm Water Management and Erosion control

Location Name: TEP ROCKY MOUNTAIN LLC KNIGHT-67S95W /5NENE  
 Location #: 334626



Location Overview: Location is located in a 411 a. internal buffer zone.

Section/Township/Range: 5 7S95W

**Storm water Management and Erosion control**  
**Location Name:TEP ROCKY MOUNTAIN LLC KNIGHT-67S95W /5NENE.**  
**Location #: 334626**



**North West corner of location.**



**North East corner of location.**



**South West corner of location.**



**South East corner of location.**

**Storm water Management and Erosion control**  
**Location Name: TEP ROCKY MOUNTAIN LLC KNIGHT-67S95W /5NENE.**  
**Location #: 334626**



**Photo #9597 Location lacks stabilization.**



**Photo #9598 Location lacks stabilization.**

**Storm water Management and Erosion control**  
**Location Name: TEP ROCKY MOUNTAIN LLC KNIGHT-67S95W /5NENE.**  
**Location #: 334626**

Network: Apr 7, 2023 at 11:56:33 AM M



**Photo #9601 Insufficient tracking BMP at entrance to location.**