

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/06/2023

Submitted Date:

04/06/2023

Document Number:

702501109

**FIELD INSPECTION FORM**

Loc ID 316358	Inspector Name: Burchett, Kirby	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____	<b>Status Summary:</b> <input type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input checked="" type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED
<b>Operator Information:</b> OGCC Operator Number: 16700 Name of Operator: CHEVRON USA INC Address: 760 HORIZON DRIVE STE 401 City: GRAND JUNCTION State: CO Zip: 81506				<b>Findings:</b> 6 Number of Comments 1 Number of Corrective Actions <input checked="" type="checkbox"/> Corrective Action Response Requested
				<b>ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE</b>

**Contact Information:**

Contact Name	Phone	Email	Comment
Sanford, Anita	(970) 551-8313	Anita.Sanford@scoutep.com	
Patterson, Chris		Chris.Patterson@scoutep.com	
Regulatory, Rangely		RangelyRegulatory@scoutep.com	
Kellerby, Shaun	(970) 712-1248	shaun.kellerby@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
268941	WELL	SI	12/01/2021	OW	103-10360	GRAY B 22X	PR

**General Comment:****COGCC Inspection Report Summary**

On Thursday, 04/06/2023, Inspector Kirby Burchett, conducted a routine field inspection at Chevron USA Inc. on the Gray B 22X, Location #316358, in Rio Blanco County, Colorado.

This location is within or in close proximity to a Parks and Wildlife (CPW) District with High Priority and Density Habitats.

Any Corrective Actions from previous Inspections are still applicable.

While there during normal production operations the following compliance issues were observed:

1. Stormwater BMP implementation and maintenance.

A follow up on this site inspection will be conducted to ensure all compliance issues have been corrected to comply with COGCC rules.

**Location**Overall Good: ☐**Signs/Marker:**

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 911 / (970) 675-3700

Corrective Action:

Date: \_\_\_\_\_

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

Type: Deadman # & Marked	# 4		corrective date
Comment:			
Corrective Action:		Date:	
Type: Submersible Pump	# 1		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Chemical tank on plastic containment		
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	Accessible		
Corrective Action:		Date:	

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	268941	Type:	WELL	API Number:	103-10360	Status:	SI	Insp. Status:	PR
Producing Well									
Comment:	Submersible pump. Well is on Production. Last Production - November 2021 Last Report - January 2023								
Corrective Action:						Date:			

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
				Material Handling And Spill Prevention		
		Culverts				
Ditches						
Berms						
		Ditches				

Comment: Location and lease roads lack stabilization. Insufficient BMPs to control vehicle tracking.

Oil and gas operators shall implement and maintain Best Management Practices (BMPs) at all oil and gas locations to control Stormwater runoff in a manner that minimizes erosion, transport of sediment offsite, and site degradation.

Oil and gas operators shall implement and maintain vehicle tracking Best Management Practices (BMPs) to control potential sediment discharges from operational roads, well pads, and other unpaved surfaces.

Corrective Action: Provide proper BMPs to prevent sediment migration from location and lease road.

Date: 04/24/2023

Pits: ☒ NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403367706	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6074865">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6074865</a>
702501110	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6074856">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6074856</a>