

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
403360166

Date Received:
03/30/2023

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

2 of 4 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 16700

Name of Operator: CHEVRON USA INC

Address: 760 HORIZON DRIVE STE 401

City: GRAND JUNCTION State: CO Zip: 81506

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
		Chris.Patterson@scoutep.com
		Anita.Sanford@scoutep.com
		andrewolson@chevron.com
		RangelyRegulatory@scoutep.com
		dnr_cogccenforcement@state.co.us

COGCC INSPECTION SUMMARY:

FIR Document Number: 696204791

Inspection Date: 03/24/2023

FIR Submit Date: 03/27/2023

FIR Status: _____

Inspected Operator Information:

Company Name: CHEVRON USA INC

Company Number: 16700

Address: 760 HORIZON DRIVE STE 401

City: GRAND JUNCTION State: CO Zip: 81506

LOCATION - Location ID: 314696

Location Name: MCLAUGHLIN, A C-62N103W Number: 14SWSW County: _____

Qtrqr: SWS Sec: 14 Twp: 2N Range: 103W Meridian: 6
W

Latitude: 40.136290 Longitude: -108.932740

FACILITY - API Number: 05-103-00 Facility ID: 314696

Facility Name: MCLAUGHLIN, A C-62N103W Number: 14SWSW

Qtrqr: SWS Sec: 14 Twp: 2N Range: 103W Meridian: 6
W

Latitude: 40.136290 Longitude: -108.932740

CORRECTIVE ACTIONS:

1 CA# 168593

Corrective Action: Clean up/remove stained soils per Rule 912.a and submit documentation of cleanup/disposal.

Date: 04/13/2023

Response: CA COMPLETED

Date of Completion: 03/29/2023

Operator Comment: Removed stained soil and leveled up area with gravel.

COGCC Decision: Approved pending re-inspection

COGCC Representative: Approved pending re-inspection of this FIR resolution acknowledges the document was received. It is not an acknowledgement that the corrective action has been passed. A field inspection will be conducted at a future date to evaluate compliance with COGCC rules.

4 CA# 168596

Corrective Action: Install or repair required BMPs per Rule 1002.f.(2)

Date: 03/13/2023

Response: CA COMPLETED

Date of Completion: 03/29/2023

Operator Comment: Brought in material and compaction equipment to help minimize degradation, tracking and off-site sediment transport, soils brought back into bermed area. Have closed access from Highway until conditions improve.

COGCC Decision: Approved pending re-inspection

COGCC Representative: Approved pending re-inspection of this FIR resolution acknowledges the document was received. It is not an acknowledgement that the corrective action has been passed. A field inspection will be conducted at a future date to evaluate compliance with COGCC rules.

OPERATOR COMMENT AND SUBMITTAL

Comment: Please see attachments

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Chris Patterson

Signed: _____

Title: Sr. HSE Coordinator

Date: 3/30/2023 6:37:43 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
403360166	FIR RESOLUTION SUBMITTED
403360167	PIC
403360169	PIC
403360170	PIC
403360171	PIC

Total Attach: 5 Files