

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/10/2023

Submitted Date:

04/10/2023

Document Number:

702501123

FIELD INSPECTION FORMLoc ID 336019 Inspector Name: Burchett, Kirby On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 10456

Name of Operator: CAERUS PICEANCE LLC

Address: 1001 17TH STREET #1600

City: DENVER State: CO Zip: 80202

Status Summary:☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

4 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, Caerus	(970) 285-2600	COGCC.inspections@caerus oilandgas.com	
Kellerby, Shaun	(970) 712-1248	shaun.kellerby@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
294557	WELL	DG	05/14/2013	GW	103-11193	FREEDOM UNIT 297-8B8	DG

General Comment:**COGCC Inspection Report Summary**

On Monday, 04/10/2023, Inspector Kirby Burchett, conducted a routine field inspection at Caerus Piceance LLC on the FRU 297-8B8 well, Location #336019, in Rio Blanco County, Colorado.
This location is within or in close proximity to a Parks and Wildlife (CPW) District Wildlife Management Plan with Black Bear, High Priority, NSO, and Density Habitats.

Any Corrective Actions from previous Inspections are still applicable.

While there during normal drilling operations the following compliance issue was observed:

1. Liquid chemicals not in secondary containment.

A follow up on this site inspection will be conducted to ensure all compliance issues have been corrected to comply with COGCC rules.

LocationOverall Good: ☐

Signs/Marker:			
Type	DRILLING/RECOMP		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 911 / (970) 285-2615

Corrective Action:

Date: _____

Overall Good: ☐

Spills:				
Type	Area	Volume		

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected FacilitiesFacility ID: 294557 Type: WELL API Number: 103-11193 Status: DG Insp. Status: DG**Well Drilling**

Rig: Rig Name: Nabors Pusher/Rig Manager: _____
Permit Posted: SATISFACTORY Access Sign: SATISFACTORY

Well Control Equipment:

Pipe Ram: YES Blind Ram: YES Hydril Type: YES
Pressure Test BOP: Pass Test Pressure PSI: 5000 Safety Plan: YES

Drill Fluids**Management:**

Lined Pit: _____ Unlined Pit: _____ Closed Loop: YES Semi-Closed Loop: _____
Multi-Well: YES Disposal Location: County Landfill

Comment: _____

Corrective Action: _____ Date: _____

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms						
		Gravel				
		Ditches				
				Material Handling And Spill Prevention		Drig Rep ordered containments to be delivered.
Ditches						
Gravel						

Comment: No secondary containment under liquid mud chemicals.
Oil and gas operators shall implement and maintain Best Management Practices (BMPs) at all oil and gas locations for materials handling and spill prevention procedures and practices implemented for material handling and spill prevention of materials used, stored, or disposed of that could result in discharges causing pollution of surface waters.

Insufficient BMPs to control vehicle tracking.
Oil and gas operators shall implement and maintain vehicle tracking Best Management Practices (BMPs) to control potential sediment discharges from operational roads, well pads, and other unpaved surfaces.

Corrective Action: Provide proper BMPs for spill prevention, handling and maintenance of equipment.
Provide proper BMPs to prevent sediment migration from location and lease road.

Date: 04/26/2023

Pits: ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403369707	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6077523
702501124	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6077521