

**State of Colorado**  
**Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109



**Document Number:**

**402890516**

**Receive Date:**

**12/07/2021**

**TRANSFER OF OPERATORSHIP**

A Selling Operator will notify the Commission about the transfer of any Transferable Item associated with its Oil and Gas Operations to a Buying Operator by filing a Form 9, Transfer of Operatorship – Intent, with the Commission at least 30 days, or as soon as practicable, before the anticipated transfer date. (Rule 218.b.) When a transaction subject to a Form 9 – Intent becomes final, the Buying Operator will submit a Form 9 – Subsequent within 7 days of closing. (Rule 218.d.(1).)

**Type of Form 9, Transfer of Operatorship:**  Intent  Subsequent Intent # 402847273

**OPERATOR INFORMATION**

**SELLING OPERATOR INFORMATION**

OGCC Operator Number: 16700 Contact Name and Telephone:  
Name of Operator: CHEVRON USA INC Name: Jimmy Lozano  
Address: 100 CHEVRON ROAD Phone: (432) 687-7696  
City: RANGELY State: CO Zip: 81648 Email: jimmy.lozano@chevron.com

**BUYING OPERATOR INFORMATION**

OGCC Operator Number: 10779 Contact Name and Telephone:  
Name of Operator: SCOUT ENERGY MANAGEMENT LLC Name: Tee Brown  
Address: 13800 MONTFORT DRIVE SUITE 100 Phone: (972) 325-1027  
City: DALLAS State: TX Zip: 75240 Email: tbrown@scoutep.com

**TRANSFER INFO**

**Transfer Dates**

Form 9 Intent - Anticipated Date of Transfer: 12/01/2021

Form 9 Subsequent - Effective Date of Transfer: s12/01/2021

**Confidentiality**

Transfer is Confidential: No

**Financial Assurance**

Form 9 Intent - Estimated amount of Financial Assurance the Buying Operator will submit prior to anticipated date of transfer:\$ 100,000

Form 9 Subsequent - The Buying Operator's Financial Assurance:

Surety ID	Bond Type	Amount
20210101	PLUGGING	100,000
20210103	PLUGGING	3,500,000
20210100	SURFACE	25,000

**SUBSEQUENT LIABILITY**

**Rule 218.d.(1).D.i.**

"For Transferable Items listed in Rule 218.d.(1).B.i an acknowledgment that upon the effective date of transfer, that the Buying Operator assumes all responsibility for compliance with the Act, the Commission's Rules, and all terms and conditions of existing Permits and Commission orders for the Transferable Items."

In checking this box the Buying Operator's acknowledges the subsequent liability pursuant to Rule 218.d.(1).D.i.

**Rule 218.d.(1).D.ii.**

"For Transferable Items listed in Rule 218.d.(1).B.ii or iii, an acknowledgment that the Buying Operator may be or may become responsible for compliance with the Act, the Commission's Rules, and all terms and conditions of existing Permits and Commission orders if the Buying Operator takes any action, or fails to take any action, that would cause such Transferable Item to be out of compliance with the Act, the Commission's Rules, and all terms and conditions of existing Permits and Commission orders."

In checking this box the Buying Operator's acknowledges the subsequent liability pursuant to Rule 218.d.(1).D.ii.

**Rule 218.d.(1).D.iii.**

"For Transferable Items not listed in Rule 218.d.(1).B.i-iii but Related in the Commission's records, an acknowledgment that the Commission will presume that the Transferable Item was transferred, and that the Buying Operator is responsible for compliance with the Act, the Commission's Rules, and all terms and conditions of existing Permits and Commission orders for the Transferable Items."

In checking this box the Buying Operator's acknowledges the subsequent liability pursuant to Rule 218.d.(1).D.iii.

**SUBMITTAL**

**OPERATOR COMMENT AND SUBMITTAL**

I hereby certify all statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Tee Brown Email: tbrown@scoutep.com

Signature: \_\_\_\_\_ Title: Regulatory Manager Date: 12/07/2021

**Wells & Facilities Transferred Summary**

1	Facility Type	API	Facility ID	Location ID	Facility Name	QtrQtr	Sec	Twp	Rng
	LOCATION	-	314635	314635	EMERALD-62N102W #31SWNW	SWNW	31	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO		16700	CHEVRON USA INC					
2	Facility Type	API	Facility ID	Location ID	Facility Name	QtrQtr	Sec	Twp	Rng
	WELL	103-06254	229169	314635	EMERALD #22	SWNW	31	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO	FEE	16700	CHEVRON USA INC					
3	Facility Type	API	Facility ID	Location ID	Facility Name	QtrQtr	Sec	Twp	Rng
	LOCATION	-	314636	314636	FEE-62N102W #31NESW	NESW	31	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO		16700	CHEVRON USA INC					
4	Facility Type	API	Facility ID	Location ID	Facility Name	QtrQtr	Sec	Twp	Rng
	WELL	103-06255	229170	314636	FEE #38	NESW	31	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO	FEE	16700	CHEVRON USA INC					
5	Facility Type	API	Facility ID	Location ID	Facility Name	QtrQtr	Sec	Twp	Rng
	LOCATION	-	314637	314637	FEE-62N102W #31SESW	SESW	31	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO		16700	CHEVRON USA INC					
6	Facility Type	API	Facility ID	Location ID	Facility Name	QtrQtr	Sec	Twp	Rng
	WELL	103-06256	229171	314637	FEE #69	SESW	31	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO	FEE	16700	CHEVRON USA INC					
7	Facility Type	API	Facility ID	Location ID	Facility Name	QtrQtr	Sec	Twp	Rng
	WELL	103-06257	229172	314638	RAVEN #A-2	NWNE	31	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO	FEE	16700	CHEVRON USA INC					
8	Facility Type	API	Facility ID	Location ID	Facility Name	QtrQtr	Sec	Twp	Rng
	LOCATION	-	314639	314639	RAVEN-62N102W #31SWNE	SWNE	31	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO		16700	CHEVRON USA INC					
9	Facility Type	API	Facility ID	Location ID	Facility Name	QtrQtr	Sec	Twp	Rng
	LOCATION	-	314640	314640	FEE-62N102W #31NWSE	NWSE	31	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO		16700	CHEVRON USA INC					

10	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	WELL	103-06259	229174	314640	FEE #48	NWSE	31	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO	FEE	16700	CHEVRON USA INC					
11	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	LOCATION	-	314641	314641	UNION PACIFIC-62N102W #31NENE	NENE	31	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO		16700	CHEVRON USA INC					
12	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	WELL	103-06261	229176	314641	UNION PACIFIC #26-31	NENE	31	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO	FEE	16700	CHEVRON USA INC					
13	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	LOCATION	-	314642	314642	UNION PACIFIC-62N102W #32SWNW	SWNW	32	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO		16700	CHEVRON USA INC					
14	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	WELL	103-06266	229181	314642	UNION PACIFIC #33-32	SWNW	32	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO	FEE	16700	CHEVRON USA INC					
15	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	LOCATION	-	314643	314643	UNION PACIFIC-62N102W #32SEnw	SEnw	32	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO		16700	CHEVRON USA INC					
16	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	WELL	103-06269	229184	314643	UNION PACIFIC #23-32	SEnw	32	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO	FEE	16700	CHEVRON USA INC					
17	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	LOCATION	-	314644	314644	SHARPLES-MC LAUGHLIN-62N102W #32SWNE	SWNE	32	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO		16700	CHEVRON USA INC					
18	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	WELL	103-06270	229185	314644	SHARPLES-MC LAUGHLIN #3-32	SWNE	32	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO	FEE	16700	CHEVRON USA INC					

19	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	LOCATION	-	314645	314645	SHARPLES-MCLAUGHLIN-62N102W #32NENE	NENE	32	2N	102W
	<u>County</u>	<u>Min.Owner.Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO		16700	CHEVRON USA INC					
20	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	WELL	103-06273	229188	314645	SHARPLES-MCLAUGHLIN #2-32	NENE	32	2N	102W
	<u>County</u>	<u>Min.Owner.Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO	FEE	16700	CHEVRON USA INC					
21	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	LOCATION	-	314646	314646	UNION PACIFIC-62N102W #32NESE	NESE	32	2N	102W
	<u>County</u>	<u>Min.Owner.Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO		16700	CHEVRON USA INC					
22	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	PIT	-	102564	314646	RANGLEY WEBER MAIN WTR PLANT #	NESE	32	2N	102W
	<u>County</u>	<u>Min.Owner.Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO		16700	CHEVRON USA INC					
23	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	PIT	-	102565	314646	RANGLEY WEBER MAIN WTR PLANT #	NESE	32	2N	102W
	<u>County</u>	<u>Min.Owner.Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO		16700	CHEVRON USA INC					
24	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	PIT	-	117221	314646	RANGELY WEBER SAND UNIT #	NESE	32	2N	102W
	<u>County</u>	<u>Min.Owner.Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO		16700	CHEVRON USA INC					
25	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	PIT	-	117222	314646	RANGELY WEBER SAND UNIT #	NESE	32	2N	102W
	<u>County</u>	<u>Min.Owner.Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO		16700	CHEVRON USA INC					
26	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	WELL	103-06275	229190	314646	UNION PACIFIC #22-32	NESE	32	2N	102W
	<u>County</u>	<u>Min.Owner.Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO	FEE	16700	CHEVRON USA INC					
27	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	LOCATION	-	314647	314647	UNION PACIFIC-62N102W #32SESE	SESE	32	2N	102W
	<u>County</u>	<u>Min.Owner.Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					

	RIO BLANCO		16700	CHEVRON USA INC					
28	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	WELL	103-06276	229191	314647	UNION PACIFIC #53-32	SESE	32	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO	FEE	16700	CHEVRON USA INC					
29	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	LOCATION	-	314648	314648	MCLAUGHLIN, S W (SIDETRACK)-62N102W #33SESW	SESW	33	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO		16700	CHEVRON USA INC					
30	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	WELL	103-06278	229193	314648	MCLAUGHLIN, S W (SIDETRACK) #6	SESW	33	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO	FEE	16700	CHEVRON USA INC					
31	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	LOCATION	-	314649	314649	S W MCLAUGHLIN-62N102W #33SWSE	SWSE	33	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO		16700	CHEVRON USA INC					
32	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	WELL	103-06279	229194	314649	S W MCLAUGHLIN #5	SWSE	33	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO	FEE	16700	CHEVRON USA INC					
33	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	LOCATION	-	314652	314652	LEVISON-62N102W #26SWNW	SWNW	26	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO		16700	CHEVRON USA INC					
34	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	WELL	103-06286	229199	314652	LEVISON #9	SWNW	26	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO	FEDERAL	16700	CHEVRON USA INC					
35	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	LOCATION	-	314653	314653	SHARPLES MCLAUGHLIN-62N102W #33NWNW	NWNW	33	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO		16700	CHEVRON USA INC					
36	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	WELL	103-06288	229201	314653	SHARPLES MCLAUGHLIN #6-33	NWNW	33	2N	102W

	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO	FEDERAL	16700	CHEVRON USA INC					
37	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	LOCATION	-	314654	314654	S. MCLAUGHLIN-62N102W #33NESE	NESE	33	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO		16700	CHEVRON USA INC					
38	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	WELL	103-06290	229203	314654	S. MCLAUGHLIN #3-33	NESE	33	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO	FEE	16700	CHEVRON USA INC					
39	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	LOCATION	-	314655	314655	SHARPLES-MCLAUGHLIN-62N102W #33SESE	SESE	33	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO		16700	CHEVRON USA INC					
40	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	WELL	103-06291	229204	314655	SHARPLES-MCLAUGHLIN #4-33	SESE	33	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO	FEE	16700	CHEVRON USA INC					
41	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	LOCATION	-	314656	314656	C T CARNEY-62N102W #35NWNW	NWNW	35	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO		16700	CHEVRON USA INC					
42	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	WELL	103-06293	229206	314656	C T CARNEY #7-35	NWNW	35	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO	FEE	16700	CHEVRON USA INC					
43	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	LOCATION	-	314657	314657	CARNEY C T-62N102W #35SENE	SENE	35	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO		16700	CHEVRON USA INC					
44	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	WELL	103-06295	229208	314657	CARNEY C T #18-35	SENE	35	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO	FEDERAL	16700	CHEVRON USA INC					
45	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	LOCATION	-	314658	314658	LARSON, F V-62N102W #35SENE	SENE	35	2N	102W

	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO		16700	CHEVRON USA INC					
46	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	WELL	103-06296	229209	314658	LARSON, F V #B-1	SENE	35	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO	FEDERAL	16700	CHEVRON USA INC					
47	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	LOCATION	-	314659	314659	LARSON, F V-62N102W #36NWNW	NWNW	36	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO		16700	CHEVRON USA INC					
48	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	WELL	103-06298	229210	314659	LARSON, F V #B-4	NWNW	36	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO	FEDERAL	16700	CHEVRON USA INC					
49	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	LOCATION	-	314660	314660	LARSON, F V-62N102W #36SWNW	SWNW	36	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO		16700	CHEVRON USA INC					
50	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	WELL	103-06299	229211	314660	LARSON, F V #B-10	SWNW	36	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO	FEDERAL	16700	CHEVRON USA INC					
51	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	LOCATION	-	314661	314661	LARSON, F V-62N102W #36SENV	SENV	36	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO		16700	CHEVRON USA INC					
52	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	WELL	103-06301	229213	314661	LARSON, F V #B-5	SENV	36	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO	FEDERAL	16700	CHEVRON USA INC					
53	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	LOCATION	-	314662	314662	LARSON, F V-62N102W #36NESW	NESW	36	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO		16700	CHEVRON USA INC					
54	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	WELL	103-06302	229214	314662	LARSON, F V #B-11	NESW	36	2N	102W

	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO	FEDERAL	16700	CHEVRON USA INC					
55	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	LOCATION	-	314663	314663	LARSON, F V-62N102W #36NWSW	NWSW	36	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO		16700	CHEVRON USA INC					
56	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	WELL	103-06303	229215	314663	LARSON, F V #B-6	NWSW	36	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO	FEDERAL	16700	CHEVRON USA INC					
57	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	LOCATION	-	314664	314664	LARSON, F V-62N102W #36NWSE	NWSE	36	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO		16700	CHEVRON USA INC					
58	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	WELL	103-06305	229217	314664	LARSON, F V #B-3	NWSE	36	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO	FEDERAL	16700	CHEVRON USA INC					
59	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	LOCATION	-	314665	314665	WEYRAUCH-62N102W #36NWNE	NWNE	36	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO		16700	CHEVRON USA INC					
60	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	WELL	103-06306	229218	314665	WEYRAUCH #2-36	NWNE	36	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO	FEDERAL	16700	CHEVRON USA INC					
61	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	LOCATION	-	314666	314666	WEYRAUCH-62N102W #36SWNE	SWNE	36	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO		16700	CHEVRON USA INC					
62	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	WELL	103-06307	229219	314666	WEYRAUCH #1-36	SWNE	36	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO	FEDERAL	16700	CHEVRON USA INC					
63	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	LOCATION	-	314667	314667	MCLAUGHLIN, A C-62N103W #11SWSW	SWSW	11	2N	103W

	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO		16700	CHEVRON USA INC					
64	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	WELL	103-06315	229225	314667	MCLAUGHLIN, A C #33	SWSW	11	2N	103W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO	FEDERAL	16700	CHEVRON USA INC					
65	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	LOCATION	-	314668	314668	MCLAUGHLIN, A C-62N103W #11SWSE	SWSE	11	2N	103W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO		16700	CHEVRON USA INC					
66	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	WELL	103-06317	229227	314668	MCLAUGHLIN, A C #17	SWSE	11	2N	103W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO	FEE	16700	CHEVRON USA INC					
67	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	LOCATION	-	314669	314669	MCLAUGHLIN, A C-62N103W #14NWSW	NWSW	14	2N	103W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO		16700	CHEVRON USA INC					
68	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	WELL	103-06320	229229	314669	MCLAUGHLIN, A C #40	NWSW	14	2N	103W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO	FEDERAL	16700	CHEVRON USA INC					
69	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	LOCATION	-	314670	314670	A C MCLAUGHLIN-62N103W #14N2SE	N2SE	14	2N	103W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO		16700	CHEVRON USA INC					
70	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	WELL	103-06321	229230	314670	A C MCLAUGHLIN #50X	N2SE	14	2N	103W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO	FEDERAL	16700	CHEVRON USA INC					
71	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	LOCATION	-	314671	314671	A C MCLAUGHLIN-62N103W #14NESW	NESW	14	2N	103W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO		16700	CHEVRON USA INC					
72	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	WELL	103-06322	229231	314671	A C MCLAUGHLIN #38	NESW	14	2N	103W

	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO	FEDERAL	16700	CHEVRON USA INC					
73	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	LOCATION	-	314672	314672	MCLAUGHLIN, A C-62N103W #14SEW	SEW	14	2N	103W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO		16700	CHEVRON USA INC					
74	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	WELL	103-06323	229232	314672	MCLAUGHLIN, A C #46	SEW	14	2N	103W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO	FEDERAL	16700	CHEVRON USA INC					
75	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	LOCATION	-	314673	314673	MCLAUGHLIN, A C-62N103W #14NWSE	NWSE	14	2N	103W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO		16700	CHEVRON USA INC					
76	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	WELL	103-06324	229233	314673	MCLAUGHLIN, A C #43	NWSE	14	2N	103W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO	FEDERAL	16700	CHEVRON USA INC					
77	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	LOCATION	-	314674	314674	HAGOOD M C-62N103W #15NWNW	NWNW	15	2N	103W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO		16700	CHEVRON USA INC					
78	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	WELL	103-06325	229234	314674	HAGOOD M C #A-8	NWNW	15	2N	103W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO	FEDERAL	16700	CHEVRON USA INC					
79	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	LOCATION	-	314675	314675	HAGOOD M C-62N103W #15NENW	NENW	15	2N	103W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO		16700	CHEVRON USA INC					
80	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	WELL	103-06326	229235	314675	HAGOOD M C #A-4	NENW	15	2N	103W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO	FEDERAL	16700	CHEVRON USA INC					
81	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	LOCATION	-	314676	314676	M C HAGOOD A-62N103W #15SWNE	SWNE	15	2N	103W

	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO		16700	CHEVRON USA INC					
82	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	PIT	-	117218	314676	RANGELY WEBER SAND UNIT 1 #	SENW	15	2N	103W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO		16700	CHEVRON USA INC					
83	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	WELL	103-06327	229236	314676	M C HAGOOD A #9	SWNE	15	2N	103W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO	FEDERAL	16700	CHEVRON USA INC					
84	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	LOCATION	-	314677	314677	HAGOOD M C-62N103W #15NESW	NESW	15	2N	103W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO		16700	CHEVRON USA INC					
85	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	WELL	103-06328	229237	314677	HAGOOD M C #A-1	NESW	15	2N	103W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO	FEDERAL	16700	CHEVRON USA INC					
86	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	LOCATION	-	314678	314678	HAGOOD M C-62N103W #15NWNE	NWNE	15	2N	103W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO		16700	CHEVRON USA INC					
87	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	WELL	103-06330	229239	314678	HAGOOD M C #A-3	NWNE	15	2N	103W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO	FEDERAL	16700	CHEVRON USA INC					
88	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	LOCATION	-	314679	314679	HAGOOD M C-62N103W #15NWSE	NWSE	15	2N	103W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO		16700	CHEVRON USA INC					
89	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	WELL	103-06331	229240	314679	HAGOOD M C #5	NWSE	15	2N	103W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO	FEDERAL	16700	CHEVRON USA INC					
90	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	LOCATION	-	314680	314680	LARSON, M B-62N103W #15SWSE	SWSE	15	2N	103W

	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO		16700	CHEVRON USA INC					
91	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	WELL	103-06332	229241	314680	LARSON, M B #A-2	SWSE	15	2N	103W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO	FEDERAL	16700	CHEVRON USA INC					
92	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	LOCATION	-	314681	314681	A C MCLAUGHLIN-62N103W #15NESE	NESE	15	2N	103W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO		16700	CHEVRON USA INC					
93	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	WELL	103-06333	229242	314681	A C MCLAUGHLIN #37	NESE	15	2N	103W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO	FEE	16700	CHEVRON USA INC					
94	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	LOCATION	-	314684	314684	EMERALD-62N103W #36NWSE	NWSE	36	2N	103W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO		16700	CHEVRON USA INC					
95	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	UIC DISPOSAL	-	159117	314684	EMERALD 42 #	NWSE	36	2N	103W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO		16700	CHEVRON USA INC					
96	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	WELL	103-06340	229247	314684	EMERALD #42	NWSE	36	2N	103W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO	FEDERAL	16700	CHEVRON USA INC					
97	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	LOCATION	-	314692	314692	GRAY B-62N102W #18SWSW	SWSW	18	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO		16700	CHEVRON USA INC					
98	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	WELL	103-06386	229288	314692	GRAY B #18X	SWSW	18	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO	FEE	16700	CHEVRON USA INC					
99	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	LOCATION	-	314693	314693	F V LARSON-62N102W #35NESE	NESE	35	2N	102W

	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO		16700	CHEVRON USA INC					
100	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	WELL	103-06414	229314	314693	F V LARSON #B-14X	NESE	35	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO	FEE	16700	CHEVRON USA INC					
101	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	LOCATION	-	314694	314694	MCLAUGHLIN, A C-62N103W #13NWSW	NWSW	13	2N	103W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO		16700	CHEVRON USA INC					
102	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	WELL	103-06417	229316	314694	MCLAUGHLIN, A C #49X	NWSW	13	2N	103W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO	FEDERAL	16700	CHEVRON USA INC					
103	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	LOCATION	-	314695	314695	A C MCLAUGHLIN-62N103W #13SEW	SEW	13	2N	103W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO		16700	CHEVRON USA INC					
104	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	WELL	103-06418	229317	314695	A C MCLAUGHLIN #51X	SEW	13	2N	103W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO	FEE	16700	CHEVRON USA INC					
105	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	LOCATION	-	314696	314696	MCLAUGHLIN, A C-62N103W #14SWSW	SWSW	14	2N	103W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO		16700	CHEVRON USA INC					
106	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	WELL	103-06419	229318	314696	MCLAUGHLIN, A C #55X	SWSW	14	2N	103W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO	FEDERAL	16700	CHEVRON USA INC					
107	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	LOCATION	-	314697	314697	MCLAUGHLIN, A C-62N103W #14SEW	SEW	14	2N	103W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO		16700	CHEVRON USA INC					
108	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	WELL	103-06420	229319	314697	MCLAUGHLIN, A C #56X	SEW	14	2N	103W

	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO	FEDERAL	16700	CHEVRON USA INC					
109	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	LOCATION	-	314698	314698	MCLAUGHLIN, A C-62N103W #23SWNW	SWNW	23	2N	103W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO		16700	CHEVRON USA INC					
110	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	WELL	103-06425	229324	314698	MCLAUGHLIN, A C #52X	SWNW	23	2N	103W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO	FEDERAL	16700	CHEVRON USA INC					
111	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	LOCATION	-	314699	314699	MCLAUGHLIN A C-62N103W #23NESW	NESW	23	2N	103W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO		16700	CHEVRON USA INC					
112	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	WELL	103-06426	229325	314699	MCLAUGHLIN A C #54X	NESW	23	2N	103W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO	FEDERAL	16700	CHEVRON USA INC					
113	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	LOCATION	-	314702	314702	A C MCLAUGHLIN-62N103W #14SWNE	SWNE	14	2N	103W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO		16700	CHEVRON USA INC					
114	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	WELL	103-07010	229356	314702	A C MCLAUGHLIN #57-X	SWNE	14	2N	103W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO	FEDERAL	16700	CHEVRON USA INC					
115	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	LOCATION	-	314704	314704	AC MCLAUGHLIN GOV D 03267-62N103W #13NESW	NESW	13	2N	103W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO		16700	CHEVRON USA INC					
116	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	WELL	103-07014	229360	314704	AC MCLAUGHLIN GOV D 03267 #5 58-X	NESW	13	2N	103W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO	FEDERAL	16700	CHEVRON USA INC					
117	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	LOCATION	-	314706	314706	HAGOOD L N-62N103W #23SWSE	SWSE	23	2N	103W

	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO		16700	CHEVRON USA INC					
118	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	WELL	103-07022	229367	314706	HAGOOD L N #A-9X	SWSE	23	2N	103W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO	FEDERAL	16700	CHEVRON USA INC					
119	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	LOCATION	-	314707	314707	F V LARSON B-62N102W #26SESE	SESE	26	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO		16700	CHEVRON USA INC					
120	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	WELL	103-07024	229369	314707	F V LARSON B #16-X	SESE	26	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO	FEDERAL	16700	CHEVRON USA INC					
121	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	LOCATION	-	314712	314712	CARNEY C T-62N102W #35CNW	CNW	35	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO		16700	CHEVRON USA INC					
122	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	WELL	103-07033	229378	314712	CARNEY C T #21 X 35	CNW	35	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO	FEDERAL	16700	CHEVRON USA INC					
123	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	LOCATION	-	314714	314714	E RECTOR-62N102W #34SESE	SESE	34	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO		16700	CHEVRON USA INC					
124	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	WELL	103-07043	229388	314714	E RECTOR #8X	SESE	34	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO	FEE	16700	CHEVRON USA INC					
125	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	LOCATION	-	314718	314718	J E COLTHARP-62N102W #35SESE	SESE	35	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO		16700	CHEVRON USA INC					
126	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	WELL	103-07057	229402	314718	J E COLTHARP #5X	SESE	35	2N	102W

	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO	FEE	16700	CHEVRON USA INC					
127	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	LOCATION	-	314726	314726	WEYRAUCH-62N102W #36SWNE	SWNE	36	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO		16700	CHEVRON USA INC					
128	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	WELL	103-07072	229417	314726	WEYRAUCH #4 X36	SWNE	36	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO	FEE	16700	CHEVRON USA INC					
129	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	LOCATION	-	314727	314727	F V LARSON-62N102W #35NENE	NENE	35	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO		16700	CHEVRON USA INC					
130	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	WELL	103-07078	229423	314727	F V LARSON #B-17X	NENE	35	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO	FEDERAL	16700	CHEVRON USA INC					
131	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	LOCATION	-	314728	314728	F V LARSON-62N102W #26NESE	NESE	26	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO		16700	CHEVRON USA INC					
132	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	WELL	103-07083	229428	314728	F V LARSON #B-18X	NESE	26	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO	FEDERAL	16700	CHEVRON USA INC					
133	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	LOCATION	-	314730	314730	LEVISON-62N102W #26NWNW	NWNW	26	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO		16700	CHEVRON USA INC					
134	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	WELL	103-07089	229434	314730	LEVISON #22X	NWNW	26	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO	FEE	16700	CHEVRON USA INC					
135	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	LOCATION	-	314733	314733	M B LARSON-62N102W #25SWSW	SWSW	25	2N	102W

	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO		16700	CHEVRON USA INC					
136	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	WELL	103-07093	229438	314733	M B LARSON #C8 X 25	SWSW	25	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO	FEE	16700	CHEVRON USA INC					
137	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	LOCATION	-	314735	314735	F V LARSON-GOV D 051900 B-62N102W #36SENV	SENV	36	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO		16700	CHEVRON USA INC					
138	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	WELL	103-07099	229443	314735	F V LARSON-GOV D 051900 B #-20-X	SENV	36	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO	FEDERAL	16700	CHEVRON USA INC					
139	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	LOCATION	-	314737	314737	F/V LARSON-62N102W #36NWSW	NWSW	36	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO		16700	CHEVRON USA INC					
140	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	WELL	103-07106	229450	314737	F/V LARSON #B-19X	NWSW	36	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO	FEDERAL	16700	CHEVRON USA INC					
141	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	LOCATION	-	314739	314739	M B LARSON-62N102W #26SENE	SENE	26	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO		16700	CHEVRON USA INC					
142	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	WELL	103-07110	229454	314739	M B LARSON #D3 X 26	SENE	26	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO	FEE	16700	CHEVRON USA INC					
143	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	LOCATION	-	314741	314741	LEVISON GOV-62N102W #26NWSW	NWSW	26	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO		16700	CHEVRON USA INC					
144	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	WELL	103-07114	229458	314741	LEVISON GOV #24X	NWSW	26	2N	102W

	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO	FEDERAL	16700	CHEVRON USA INC					
145	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	LOCATION	-	314744	314744	LEVISON-62N102W #26SWSE	SWSE	26	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO		16700	CHEVRON USA INC					
146	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	WELL	103-07123	229467	314744	LEVISON #23X	SWSE	26	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO	FEDERAL	16700	CHEVRON USA INC					
147	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	LOCATION	-	314748	314748	EMERALD-62N102W #30SWSW	SWSW	30	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO		16700	CHEVRON USA INC					
148	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	WELL	103-07130	229474	314748	EMERALD #46X	SWSW	30	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO	FEE	16700	CHEVRON USA INC					
149	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	LOCATION	-	314756	314756	RECTOR-61N102W #3NWNE	NWNE	3	1N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO		16700	CHEVRON USA INC					
150	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	WELL	103-07147	229491	314756	RECTOR #9X	NWNE	3	1N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO	FEE	16700	CHEVRON USA INC					

### Incidents Transferred Summary

	<u>Document Numbers</u>	<u>Incident Type</u>	<u>Incident Date</u>	<u>Current Op #</u>	<u>Current Op. Name</u>
1	679704776	UNRESOLVED FIELD INSPECTION REPORTS WITH OUTSTANDI	07/18/2019	16700	CHEVRON USA INC
2	679705393	UNRESOLVED FIELD INSPECTION REPORTS WITH OUTSTANDI	09/10/2019	16700	CHEVRON USA INC
3	679705601	UNRESOLVED FIELD INSPECTION REPORTS WITH OUTSTANDI	09/26/2019	16700	CHEVRON USA INC
4					

	679705702	UNRESOLVED FIELD INSPECTION REPORTS WITH OUTSTANDI	10/04/2019	16700	CHEVRON USA INC
5	<u>Document Numbers</u>	<u>Incident Type</u>	<u>Incident Date</u>	<u>Current Op #</u>	<u>Current Op. Name</u>
	679705704	UNRESOLVED FIELD INSPECTION REPORTS WITH OUTSTANDI	10/04/2019	16700	CHEVRON USA INC
6	<u>Document Numbers</u>	<u>Incident Type</u>	<u>Incident Date</u>	<u>Current Op #</u>	<u>Current Op. Name</u>
	679706734	UNRESOLVED FIELD INSPECTION REPORTS WITH OUTSTANDI	12/30/2019	16700	CHEVRON USA INC
7	<u>Document Numbers</u>	<u>Incident Type</u>	<u>Incident Date</u>	<u>Current Op #</u>	<u>Current Op. Name</u>
	679706806	UNRESOLVED FIELD INSPECTION REPORTS WITH OUTSTANDI	01/03/2020	16700	CHEVRON USA INC
8	<u>Document Numbers</u>	<u>Incident Type</u>	<u>Incident Date</u>	<u>Current Op #</u>	<u>Current Op. Name</u>
	679706810	UNRESOLVED FIELD INSPECTION REPORTS WITH OUTSTANDI	01/03/2020	16700	CHEVRON USA INC
9	<u>Document Numbers</u>	<u>Incident Type</u>	<u>Incident Date</u>	<u>Current Op #</u>	<u>Current Op. Name</u>
	679707104	UNRESOLVED FIELD INSPECTION REPORTS WITH OUTSTANDI	01/24/2020	16700	CHEVRON USA INC
10	<u>Document Numbers</u>	<u>Incident Type</u>	<u>Incident Date</u>	<u>Current Op #</u>	<u>Current Op. Name</u>
	680401597	UNRESOLVED FIELD INSPECTION REPORTS WITH OUTSTANDI	06/01/2017	16700	CHEVRON USA INC
11	<u>Document Numbers</u>	<u>Incident Type</u>	<u>Incident Date</u>	<u>Current Op #</u>	<u>Current Op. Name</u>
	696202354	UNRESOLVED FIELD INSPECTION REPORTS WITH OUTSTANDI	02/19/2021	16700	CHEVRON USA INC
12	<u>Document Numbers</u>	<u>Incident Type</u>	<u>Incident Date</u>	<u>Current Op #</u>	<u>Current Op. Name</u>
	696202356	UNRESOLVED FIELD INSPECTION REPORTS WITH OUTSTANDI	02/19/2021	16700	CHEVRON USA INC
13	<u>Document Numbers</u>	<u>Incident Type</u>	<u>Incident Date</u>	<u>Current Op #</u>	<u>Current Op. Name</u>
	696204063	UNRESOLVED FIELD INSPECTION REPORTS WITH OUTSTANDI	09/12/2022	16700	CHEVRON USA INC
14	<u>Document Numbers</u>	<u>Incident Type</u>	<u>Incident Date</u>	<u>Current Op #</u>	<u>Current Op. Name</u>
	696204073	UNRESOLVED FIELD INSPECTION REPORTS WITH OUTSTANDI	09/12/2022	16700	CHEVRON USA INC
15	<u>Document Numbers</u>	<u>Incident Type</u>	<u>Incident Date</u>	<u>Current Op #</u>	<u>Current Op. Name</u>
	696204090	UNRESOLVED FIELD INSPECTION REPORTS WITH OUTSTANDI	09/12/2022	16700	CHEVRON USA INC
16	<u>Document Numbers</u>	<u>Incident Type</u>	<u>Incident Date</u>	<u>Current Op #</u>	<u>Current Op. Name</u>
	700400180	UNRESOLVED FIELD INSPECTION REPORTS WITH OUTSTANDI	02/25/2020	16700	CHEVRON USA INC
17	<u>Document Numbers</u>	<u>Incident Type</u>	<u>Incident Date</u>	<u>Current Op #</u>	<u>Current Op. Name</u>

	700400188	UNRESOLVED FIELD INSPECTION REPORTS WITH OUTSTANDI	02/25/2020	16700	CHEVRON USA INC
18	<u>Document Numbers</u>	<u>Incident Type</u>	<u>Incident Date</u>	<u>Current Op #</u>	<u>Current Op. Name</u>
	700400413	UNRESOLVED FIELD INSPECTION REPORTS WITH OUTSTANDI	03/10/2020	16700	CHEVRON USA INC
19	<u>Document Numbers</u>	<u>Incident Type</u>	<u>Incident Date</u>	<u>Current Op #</u>	<u>Current Op. Name</u>
	700404659	UNRESOLVED FIELD INSPECTION REPORTS WITH OUTSTANDI	12/18/2020	16700	CHEVRON USA INC
20	<u>Document Numbers</u>	<u>Incident Type</u>	<u>Incident Date</u>	<u>Current Op #</u>	<u>Current Op. Name</u>
	700405416	UNRESOLVED FIELD INSPECTION REPORTS WITH OUTSTANDI	02/16/2021	16700	CHEVRON USA INC
21	<u>Document Numbers</u>	<u>Incident Type</u>	<u>Incident Date</u>	<u>Current Op #</u>	<u>Current Op. Name</u>
	701500041	UNRESOLVED FIELD INSPECTION REPORTS WITH OUTSTANDI	03/04/2021	16700	CHEVRON USA INC

**Related Wells & Facilities Not Transferred Summary**

< No row provided >

**Related Incidents Not Transferred Summary**

< No row provided >

**Wells & Facilities Proposed Not Transferred Summary**

< No row provided >

**Incidents Proposed Not Transferred Summary**

< No row provided >

## Attachment List

<b>Att Doc Num</b>	<b>Name</b>
1311260	CORRESPONDENCE
1311261	CORRESPONDENCE
1311262	BUYER NOTIFIED LOCAL GOVT ATTESTATION
402890516	Form 09 SUBMITTED
402890519	FORM 9 SUBSEQUENT ATTESTATION
403316084	EDD-S-INCIDENTS-TRANSFERRED
403316085	EDD-S-WELLS-FACILITIES-TRANSFERRED

Total Attach: 7 Files

**COA Type**

**Description**

0 COA

## General Comments

<u>User Group</u>	<u>Comment</u>	<u>Comment Date</u>
Financial Assurance	Both operators have resolved all issues and accepted the COAs. Form 9 approved	04/18/2023
Financial Assurance	<p>Here is where we currently stand. It appears that the Spill or Releases are the issue. They need to be entered correctly on the spreadsheet.</p> <p>Chevron #40284700 to Scout #402887795</p> <p>· Location ID #311804 Union Pacific #34-31 Facility ID #444035 Spill or Release AC - 2/5/2021 This is an active Spill or Release and needs to be accounted for. The Facility Type in Column B is Spill or Release with the Facility ID and Location ID in columns E and F respectively.</p> <p>Chevron #402847248 to Scout #402890468</p> <p>· There is one Unaccounted For Facility (Location #314373, EMERALD #4 Facility # 480349 Emerald 4 Flowline spill - AC 8/2/2021) that needs to be accounted for. 2021 This is an active Spill or Release and needs to be accounted for. The Facility Type in Column B is Spill or Release with the Facility ID and Location ID in columns E and F respectively.</p> <p>Chevron #402847267 to Scout #402890493</p> <p>· There is one Unaccounted For Facility (Location #314622 FEE #19, Facility # 448608 SPILL/RELEASE POINT -AC 4/12/2021) that needs to be accounted for. The Facility Type in Column B is Spill or Release with the Facility ID and Location ID in columns E and F respectively.</p> <p>Chevron #402847273 to Scout #402890516</p> <p>· There is one Unaccounted For Facility (Location #314646 UNION PACIFIC #22-32 , Facility # 453683 Spill – AC 2-5-2021) that needs to be accounted for. The Facility Type in Column B is Spill or Release with the Facility ID and Location ID in columns E and F respectively.</p> <p>Chevron #402847276 to Scout #402890528</p> <p>· There is one Unaccounted For Spill or Release (Location #314763 (M B LARSON #C11 X 25 well P&amp;A 8/24/2021) location active open remediation , Facility # 481149 – SPILL satellite header 38 bulk line-AC 12/1/2021) that needs to be accounted for. The Facility Type in Column B is Spill or Release with the Facility ID and Location ID in columns E and F respectively.</p> <p>Chevron #402847277 to Scout #402891430</p> <p>There are two Unaccounted For Facilities that need to be accounted for as follows:            Location ID #314933 Facility ID #438685 Spill or Release            Location ID #314965 Facility ID #480932 Spill or Release</p> <p>The Facility Type in Column B is Spill or Release with the Facility ID and Location ID in columns E and F respectively.</p> <p>Chevron #402847282 to Scout #402891448</p> <p>There is one Unaccounted For Facility (Location #315324, Facility # 481858) that is a Spill and Release point that needs to be accounted for. The Facility Type in Column B is Spill or Release with the Facility ID and Location ID in columns E and F respectively.</p> <p>Chevron #402847287 to Scout #402891495</p> <p>There is one Unaccounted For Facility (Location #315740, Facility # 447266) that is a Spill and Release point that needs to be accounted for. The Facility Type in Column B is Spill or Release with the Facility ID and Location ID in columns E and F respectively.</p> <p>Chevron #402847293 to Scout #402891516</p>	02/08/2023

There is one Unaccounted For Facility (Location #316136, Facility # 446036) that is a Spill and Release point that needs to be accounted for. The Facility Type in Column B is Spill or Release with the Facility ID and Location ID in columns E and F respectively.

Chevron #402847328 to Scout #402891662

There are five Unaccounted For Facilities that need to be accounted for as follows:

- Location ID #413288 Facility ID #448925 Spill or Release
- Location ID #413288 Facility ID #457749 Spill or Release
- Location ID #426403 Facility ID #481872 Flowline System
- Location ID #426403 Facility ID #483023 Spill or Release
- Location ID #451320 Facility ID #451090 Spill or Release

The Facility Type in Column B is Spill or Release with the Facility ID and Location ID in columns E and F respectively. Instead of Location, Location ID 426403, Facility ID 481872 should have Flowline System as the Facility Type in Column B.

Assuming the other Form 9 requirements are met, all Form 9s shall now be passed with the following two COAs:

The Buying Operator must file a Form 3, Financial Assurance Plan within 10 business days of Form 9 approval. Per Rule 702, Buyer will then provide any required additional financial assurance as soon as practicable but no later than 90 days from the Commission's approval of the Form 3, Financial Assurance Plan.

The Selling Operator must file a Form 3, Financial Assurance Plan within 10 business days of Form 9 approval. Per Rule 702, Seller will then provide any required additional financial assurance as soon as practicable but no later than 90 days from the Commission's approval of the Form 3, Financial Assurance Plan.

Please note that each operator needs confirm that it will abide by the aforementioned COA by responding to this email. The correspondence will be uploaded to the form.

Please reach out with any questions.

Financial Assurance

I am reviewed the transfer again with the following issues noted below.

11/23/2022

Chevron #40284700 to Scout #402887795

· Buyer Notified Local Govt. Attestation – Please specify the individual contacted at Rio Blanco County and resubmit the attestation.

· There are two Unaccounted For Facilities that need to be accounted for as follows:

o Location ID #311804 Facility ID #444035 Spill or Release

o Location ID #314367 Facility ID #314367

If these facilities are to be transferred to Scout, then please add these facilities to the Wells and Facilities Transferred list.

If these facilities are to be retained by Chevron, then the facilities need to be added to a Wells Facilities – Not Transferred list. In addition to the list, a Seller retains responsibility Attestation must be submitted.

· There are 20 unaccounted for incidents related to this transfer. See Attached.

These corrective actions may or may not have been resolved. FIRs with outstanding corrective actions are transferable items that must be accounted for in the Form 9 in one or more of the following ways.

1. If the compliance responsibility for such an FIR transfers to the buyer include that FIR on a Related Incidents Transferred list.

2. If the compliance responsibility for such an FIR is retained by the seller include that FIR on a Related Incidents Not Transferred list and provide a Seller Retains Responsibility Attestation.

If the parties perform the research and determine that all corrective actions for a particular FIR have been resolved, that FIR does not need to be listed on the Form 9 but will be subject to Rule 218.d(1)D.iii.

Chevron #402847248 to Scout #402890468

· Buyer Notified Local Govt. Attestation – Please specify the individual contacted at Rio Blanco County and resubmit the attestation.

· There is one Unaccounted For Facility (Location #314373, Facility # 480349) that needs to be accounted for.

If these facilities are to be transferred to Scout, then please add these facilities to the Wells and Facilities Transferred list.

If these facilities are to be retained by Chevron, then the facilities need to be added to a Wells Facilities – Not Transferred list. In addition to the list, a Seller retains responsibility Attestation must be submitted.

· There are 19 unaccounted for incidents related to this transfer. See Attached.

These corrective actions may or may not have been resolved. FIRs with outstanding corrective actions are transferable items that must be accounted for in the Form 9 in one or more of the following ways.

If the compliance responsibility for such an FIR transfers to the buyer include that FIR on a Related Incidents Transferred list.

If the compliance responsibility for such an FIR is retained by the seller include that FIR on a Related Incidents Not Transferred list and provide a Seller Retains Responsibility Attestation.

If the parties perform the research and determine that all corrective actions for a particular FIR have been resolved, that FIR does not need to be listed on the Form 9 but will be subject to Rule 218.d(1)D.iii.

Chevron #402847259 to Scout #402890487

· Buyer Notified Local Govt. Attestation – Please specify the individual contacted at Rio Blanco County and resubmit the attestation.

· There are 25 unaccounted for incidents related to this transfer. See Attached.

These corrective actions may or may not have been resolved. FIRs with outstanding corrective actions are transferable items that must be accounted for in the Form 9 in one or more of the following ways.

If the compliance responsibility for such an FIR transfers to the buyer include that FIR on a Related Incidents Transferred list.

If the compliance responsibility for such an FIR is retained by the seller include that FIR on a Related Incidents Not Transferred list and provide a Seller Retains Responsibility Attestation.

If the parties perform the research and determine that all corrective actions for a particular FIR have been resolved, that FIR does not need to be listed on the Form 9 but will be subject to Rule 218.d(1)D.iii.

Chevron #402847267 to Scout #402890493

· Buyer Notified Local Govt. Attestation – Please specify the individual contacted at Rio Blanco County and resubmit the attestation.

· There is one Unaccounted For Facility (Location #314622, Facility # 448608) that needs to be accounted for.

If these facilities are to be transferred to Scout, then please add these facilities to the Wells and Facilities Transferred list.

If these facilities are to be retained by Chevron, then the facilities need to be added to a Wells Facilities – Not Transferred list. In addition to the list, a Seller retains responsibility Attestation must be submitted.

- There are 18 unaccounted for incidents related to this transfer. See Attached.

These corrective actions may or may not have been resolved. FIRs with outstanding corrective actions are transferable items that must be accounted for in the Form 9 in one or more of the following ways.

If the compliance responsibility for such an FIR transfers to the buyer include that FIR on a Related Incidents Transferred list.

If the compliance responsibility for such an FIR is retained by the seller include that FIR on a Related Incidents Not Transferred list and provide a Seller Retains Responsibility Attestation.

If the parties perform the research and determine that all corrective actions for a particular FIR have been resolved, that FIR does not need to be listed on the Form 9 but will be subject to Rule 218.d(1)D.iii.

Chevron #402847273 to Scout #402890516

- Buyer Notified Local Govt. Attestation – Please specify the individual contacted at Rio Blanco County and resubmit the attestation.

- There is one Unaccounted For Facility (Location #314646, Facility # 453683) that needs to be accounted for.

If these facilities are to be transferred to Scout, then please add these facilities to the Wells and Facilities Transferred list.

If these facilities are to be retained by Chevron, then the facilities need to be added to a Wells Facilities – Not Transferred list. In addition to the list, a Seller retains responsibility Attestation must be submitted.

- There are 21 unaccounted for incidents related to this transfer. See Attached.

These corrective actions may or may not have been resolved. FIRs with outstanding corrective actions are transferable items that must be accounted for in the Form 9 in one or more of the following ways.

If the compliance responsibility for such an FIR transfers to the buyer include that FIR on a Related Incidents Transferred list.

If the compliance responsibility for such an FIR is retained by the seller include that FIR on a Related Incidents Not Transferred list and provide a Seller Retains Responsibility Attestation.

If the parties perform the research and determine that all corrective actions for a particular FIR have been resolved, that FIR does not need to be listed on the Form 9 but will be subject to Rule 218.d(1)D.iii.

Chevron #402847276 to Scout #402890528

- Buyer Notified Local Govt. Attestation – Please specify the individual contacted at Rio Blanco County and resubmit the attestation.

- There is one Unaccounted For Facility (Location #314763, Facility # 481149) that needs to be accounted for.

If these facilities are to be transferred to Scout, then please add these facilities to the Wells and Facilities Transferred list.

If these facilities are to be retained by Chevron, then the facilities need to be added to a Wells Facilities – Not Transferred list. In addition to the list, a Seller retains responsibility Attestation must be submitted.

- There are 40 unaccounted for incidents related to this transfer. See Attached.

These corrective actions may or may not have been resolved. FIRs with outstanding corrective actions are transferable items that must be accounted for in the Form 9 in one or more of the following ways.

If the compliance responsibility for such an FIR transfers to the buyer include that FIR on a Related Incidents Transferred list.

If the compliance responsibility for such an FIR is retained by the seller include that FIR on a Related Incidents Not Transferred list and provide a Seller Retains Responsibility Attestation.

If the parties perform the research and determine that all corrective actions for a particular FIR have been resolved, that FIR does not need to be listed on the Form 9 but will be subject to Rule 218.d(1)D.iii.

Chevron #402847277 to Scout #402891430

- Buyer Notified Local Govt. Attestation – Please specify the individual contacted at Rio Blanco County and resubmit the attestation.

- There are two Unaccounted For Facilities that need to be accounted for as follows:

- o Location ID #314933 Facility ID #438685 Spill or Release

- o Location ID #314965 Facility ID #480932 Spill or Release

If these facilities are to be transferred to Scout, then please add these facilities to the Wells and Facilities Transferred list.

If these facilities are to be retained by Chevron, then the facilities need to be added to a Wells Facilities – Not Transferred list. In addition to the list, a Seller retains responsibility Attestation must be submitted.

- There are 26 unaccounted for incidents related to this transfer. See Attached.

These corrective actions may or may not have been resolved. FIRs with outstanding corrective actions are transferable items that must be accounted for in the Form 9 in one or more of the following ways.

If the compliance responsibility for such an FIR transfers to the buyer include that FIR on a Related Incidents Transferred list.

If the compliance responsibility for such an FIR is retained by the seller include that FIR on a Related Incidents Not Transferred list and provide a Seller Retains Responsibility Attestation.

If the parties perform the research and determine that all corrective actions for a particular FIR have been resolved, that FIR does not need to be listed on the Form 9 but will be subject to Rule 218.d(1)D.iii.

Chevron #402847282 to Scout #402891448

- Buyer Notified Local Govt. Attestation – Please specify the individual contacted at Rio Blanco County and resubmit the attestation.

- There is one Unaccounted For Facility (Location #315324, Facility # 481858) that needs to be accounted for.

If these facilities are to be transferred to Scout, then please add these facilities to the Wells and Facilities Transferred list.

If these facilities are to be retained by Chevron, then the facilities need to be added to a Wells Facilities – Not Transferred list. In addition to the list, a Seller retains responsibility Attestation must be submitted.

- There are 29 unaccounted for incidents related to this transfer. See Attached.

These corrective actions may or may not have been resolved. FIRs with outstanding corrective actions are transferable items that must be accounted for in the Form 9 in one or more of the following ways.

If the compliance responsibility for such an FIR transfers to the buyer include that FIR on a Related Incidents Transferred list.

If the compliance responsibility for such an FIR is retained by the seller include that FIR on a Related Incidents Not Transferred list and provide a Seller Retains Responsibility Attestation.

If the parties perform the research and determine that all corrective actions for a particular FIR have been resolved, that FIR does not need to be listed on the Form 9 but will be subject to Rule 218.d(1)D.iii.

Chevron #402847287 to Scout #402891495

- Buyer Notified Local Govt. Attestation – Please specify the individual contacted at Rio Blanco County and resubmit the attestation.

- There is one Unaccounted For Facility (Location #315740, Facility # 447266) that needs to be accounted for.

If these facilities are to be transferred to Scout, then please add these facilities to the Wells and Facilities Transferred list.

If these facilities are to be retained by Chevron, then the facilities need to be added to a Wells Facilities – Not Transferred list. In addition to the list, a Seller retains responsibility Attestation must be submitted.

- There are 25 unaccounted for incidents related to this transfer. See Attached.

These corrective actions may or may not have been resolved. FIRs with outstanding corrective actions are transferable items that must be accounted for in the Form 9 in one or more of the following ways.

If the compliance responsibility for such an FIR transfers to the buyer include that FIR on a Related Incidents Transferred list.

If the compliance responsibility for such an FIR is retained by the seller include that FIR on a Related Incidents Not Transferred list and provide a Seller Retains Responsibility Attestation.

If the parties perform the research and determine that all corrective actions for a particular FIR have been resolved, that FIR does not need to be listed on the Form 9 but will be subject to Rule 218.d(1)D.iii.

Chevron #402847293 to Scout #402891516

- Buyer Notified Local Govt. Attestation – Please specify the individual contacted at Rio Blanco County and resubmit the attestation.

- There is one Unaccounted For Facility (Location #316136, Facility # 446036) that needs to be accounted for.

If these facilities are to be transferred to Scout, then please add these facilities to the Wells and Facilities Transferred list.

If these facilities are to be retained by Chevron, then the facilities need to be added to a Wells Facilities – Not Transferred list. In addition to the list, a Seller retains responsibility Attestation must be submitted.

· There are 28 unaccounted for incidents related to this transfer. See Attached.

These corrective actions may or may not have been resolved. FIRs with outstanding corrective actions are transferable items that must be accounted for in the Form 9 in one or more of the following ways.

If the compliance responsibility for such an FIR transfers to the buyer include that FIR on a Related Incidents Transferred list.

If the compliance responsibility for such an FIR is retained by the seller include that FIR on a Related Incidents Not Transferred list and provide a Seller Retains Responsibility Attestation.

If the parties perform the research and determine that all corrective actions for a particular FIR have been resolved, that FIR does not need to be listed on the Form 9 but will be subject to Rule 218.d(1)D.iii.

Chevron #402847295 to Scout #402891587

· Buyer Notified Local Govt. Attestation – Please specify the individual contacted at Rio Blanco County and resubmit the attestation.

· There are 26 unaccounted for incidents related to this transfer. See Attached.

These corrective actions may or may not have been resolved. FIRs with outstanding corrective actions are transferable items that must be accounted for in the Form 9 in one or more of the following ways.

If the compliance responsibility for such an FIR transfers to the buyer include that FIR on a Related Incidents Transferred list.

If the compliance responsibility for such an FIR is retained by the seller include that FIR on a Related Incidents Not Transferred list and provide a Seller Retains Responsibility Attestation.

If the parties perform the research and determine that all corrective actions for a particular FIR have been resolved, that FIR does not need to be listed on the Form 9 but will be subject to Rule 218.d(1)D.iii.

Chevron #402847312 to Scout #402891604

· Buyer Notified Local Govt. Attestation – Please specify the individual contacted at Rio Blanco County and resubmit the attestation.

· There are 6 unaccounted for incidents related to this transfer. See Attached.

These corrective actions may or may not have been resolved. FIRs with outstanding corrective actions are transferable items that must be accounted for in the Form 9 in one or more of the following ways.

If the compliance responsibility for such an FIR transfers to the buyer include that FIR on a Related Incidents Transferred list.

If the compliance responsibility for such an FIR is retained by the seller include that FIR on a Related Incidents Not Transferred list and provide a Seller Retains Responsibility Attestation.

If the parties perform the research and determine that all corrective actions for a particular FIR have been resolved, that FIR does not need to be listed on the Form 9 but will be subject to Rule 218.d(1)D.iii.

Chevron #402847322 to Scout #402891631

· Buyer Notified Local Govt. Attestation – Please specify the individual contacted at Rio Blanco County and resubmit the attestation.

· There are 7 unaccounted for incidents related to this transfer. See Attached.

These corrective actions may or may not have been resolved. FIRs with outstanding corrective actions are transferable items that must be accounted for in the Form 9 in one or more of the following ways.

If the compliance responsibility for such an FIR transfers to the buyer include that FIR on a Related Incidents Transferred list.

If the compliance responsibility for such an FIR is retained by the seller include that FIR on a Related Incidents Not Transferred list and provide a Seller Retains Responsibility Attestation.

If the parties perform the research and determine that all corrective actions for a particular FIR have been resolved, that FIR does not need to be listed on the Form 9 but will be subject to Rule 218.d(1)D.iii.

Chevron #402847328 to Scout #402891662

· Buyer Notified Local Govt. Attestation – Please specify the individual contacted at Rio Blanco County and resubmit the attestation.

· There are five Unaccounted For Facilities that need to be accounted for as follows:

o Location ID #413288 Facility ID #448925 Spill or Release

o Location ID #413288 Facility ID #457749 Spill or Release

o Location ID #426403 Facility ID #481872 Flowline System

o Location ID #426403 Facility ID #483023 Spill or Release

o Location ID #451320 Facility ID #451090 Spill or Release

If these facilities are to be transferred to Scout, then please add these facilities to the Wells and Facilities Transferred list.

If these facilities are to be retained by Chevron, then the facilities need to be added to a Wells Facilities – Not Transferred list. In addition to the list, a Seller retains responsibility Attestation must be submitted.

· There are 19 unaccounted for incidents related to this transfer. See Attached.

These corrective actions may or may not have been resolved. FIRs with outstanding corrective actions are transferable items that must be accounted for in the Form 9 in one or more of the following ways.

If the compliance responsibility for such an FIR transfers to the buyer include that FIR on a Related Incidents Transferred list.

If the compliance responsibility for such an FIR is retained by the seller include that FIR on a Related Incidents Not Transferred list and provide a Seller Retains Responsibility Attestation.

If the parties perform the research and determine that all corrective actions for a particular FIR have been resolved, that FIR does not need to be listed on the Form 9 but will be subject to Rule 218.d(1)D.iii.

Chevron #402847336 to Scout #402891690

· Buyer Notified Local Govt. Attestation – Please specify the individual contacted at Rio Blanco County and resubmit the attestation.

Chevron #402847928 to Scout #402891710

· Buyer Notified Local Govt. Attestation – Please specify the individual contacted at Rio Blanco County and resubmit the attestation.

Chevron #402847952 to Scout #402891752

· Buyer Notified Local Govt. Attestation – Please specify the individual contacted at Rio Blanco County and resubmit the attestation.

Assuming the other Form 9 requirements are met, all Form 9s shall now be passed with the following two COAs:

The Buying Operator must file a Form 3, Financial Assurance Plan within 10 business days of Form 9 approval. Per Rule 702, Buyer will then provide any required additional financial assurance as soon as practicable but no later than 90 days from the Commission’s approval of the Form 3, Financial Assurance Plan.

The Selling Operator must file a Form 3, Financial Assurance Plan within 10 business days of Form 9 approval. Per Rule 702, Seller will then provide any required additional financial assurance as soon as practicable but no later than 90 days from the Commission’s approval of the Form 3, Financial Assurance Plan.

Please note that each operator needs confirm that it will abide by the aforementioned COA by responding to this email. The correspondence will be uploaded to the form.

If the operators have submitted a Form 3, please provide the following comment when submitting the revised Form 3.

Form 3 Document #\_\_\_\_ is submitted as a result of an approved Form 9 Transfer of Operatorship and it replaces Form 3 document # \_\_\_\_\_.

Please reach out with any questions.

Thanks,

Deb

Financial Assurance

I have reviewed all 17 pairs of Intent and Subsequent documents involved in your transfer. I have noted below some issues that will need to be resolved before we can approve the transfer.

04/01/2022

Problem 1: For the following 15 Subsequent documents (402887795, 402890468, 402890487, 402890493, 402890516, 402890528, 402891430, 402891448, 402891495, 402891516, 402891587, 402891604, 402891631, 402891662 and 402891690), the Wells and Facilities Transferred spreadsheets listed the current operator as Scout Energy Management LLC. This is incorrect since the transfer has not been approved.

Solution 1: Please resubmit all 15 of the Wells and Facilities Transferred spreadsheets listing the current operator reflected in COGIS.

Problem 2: For the last two Subsequent documents (402891710 and 402891752), the Incidents Transferred spreadsheets listed the current operator as Scout Energy Management LLC. This is incorrect since the transfer has not been approved.

Solution 2: Please resubmit both of the Incidents Transferred spreadsheets for subsequent document #402891710 and #402891751 listing the current operator reflected in COGIS.

Problem 3: There are Related Wells and Facilities that are not accounted for in the transfer.

Solution 3: I have attached a workbook that lists the Related Wells and Facilities that are not accounted for. In order for the transfer to be approved, the Related Wells and Facilities must be accounted for by one or a combination of the following options:

Solution 3a: Add the well and location to the Wells and Facilities Transferred list in the Subsequent.

Solution 3b: Generate and submit a Related Wells and Facilities – Not Transferred List. If

not transferring the wells and facilities, the COGCC will also require a Seller Retains Responsibility Attestation. Guidance for this attestation can also be found in the attachment.

Problem 4: In the same workbook as referenced in Problem 3, there is a list of Related Incidents that are not accounted for. Most of these incidents are Unresolved Field Inspections with Corrective Actions. These corrective actions may or may not have been resolved. FIRs with outstanding corrective actions are transferable items that must be accounted for in the Form 9 in one or both of the following ways.

Solution 4a: If the compliance responsibility for such an FIR transfers to the buyer include that FIR on a Related Incidents Transferred list.

Solution 4b: If the compliance responsibility for such an FIR is retained by the seller include that FIR on a Related Incidents Not Transferred list and provide a Seller Retains Responsibility Attestation.

If the parties perform the research and determine that all corrective actions for a particular FIR have been resolved, that FIR does not need to be listed on the Form 9 but will be subject to Rule 218.d(1)D.iii.

For both Problems 3 and 4 the lists include Unresolved Spill/Release. If the Spill/Release is closed, the COGCC does not require that the Spill/Release be transferred. It is up to the operators to determine whether or not they should be transferred. All revised and new documents can be emailed to me and I will upload them to Subsequent #402891752.

Please reach out with any questions.

Total: 4 comment(s)