

**State of Colorado**  
**Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109



**Document Number:**

**402890528**

**Receive Date:**

**12/07/2021**

**TRANSFER OF OPERATORSHIP**

A Selling Operator will notify the Commission about the transfer of any Transferable Item associated with its Oil and Gas Operations to a Buying Operator by filing a Form 9, Transfer of Operatorship – Intent, with the Commission at least 30 days, or as soon as practicable, before the anticipated transfer date. (Rule 218.b.) When a transaction subject to a Form 9 – Intent becomes final, the Buying Operator will submit a Form 9 – Subsequent within 7 days of closing. (Rule 218.d.(1).)

**Type of Form 9, Transfer of Operatorship:**  Intent  Subsequent Intent # 402847276

**OPERATOR INFORMATION**

**SELLING OPERATOR INFORMATION**

OGCC Operator Number: 16700 Contact Name and Telephone:  
 Name of Operator: CHEVRON USA INC Name: Jimmy Lozano  
 Address: 100 CHEVRON ROAD Phone: (432) 687-7696  
 City: RANGELY State: CO Zip: 81648 Email: jimmy.lozano@chevron.com

**BUYING OPERATOR INFORMATION**

OGCC Operator Number: 10779 Contact Name and Telephone:  
 Name of Operator: SCOUT ENERGY MANAGEMENT LLC Name: Tee Brown  
 Address: 13800 MONTFORT DRIVE SUITE 100 Phone: (972) 325-1027  
 City: DALLAS State: TX Zip: 75240 Email: tbrown@scoutep.com

**TRANSFER INFO**

**Transfer Dates**

Form 9 Intent - Anticipated Date of Transfer: 12/01/2021

Form 9 Subsequent - Effective Date of Transfer: s12/01/2021

**Confidentiality**

Transfer is Confidential: No

**Financial Assurance**

Form 9 Intent - Estimated amount of Financial Assurance the Buying Operator will submit prior to anticipated date of transfer:\$ 100,000

Form 9 Subsequent - The Buying Operator's Financial Assurance:

Surety ID	Bond Type	Amount
20210103	PLUGGING	3,500,000
20210101	PLUGGING	100,000
20210100	SURFACE	25,000

**SUBSEQUENT LIABILITY**

**Rule 218.d.(1).D.i.**

"For Transferable Items listed in Rule 218.d.(1).B.i an acknowledgment that upon the effective date of transfer, that the Buying Operator assumes all responsibility for compliance with the Act, the Commission's Rules, and all terms and conditions of existing Permits and Commission orders for the Transferable Items."

In checking this box the Buying Operator's acknowledges the subsequent liability pursuant to Rule 218.d.(1).D.i.

**Rule 218.d.(1).D.ii.**

"For Transferable Items listed in Rule 218.d.(1).B.ii or iii, an acknowledgment that the Buying Operator may be or may become responsible for compliance with the Act, the Commission's Rules, and all terms and conditions of existing Permits and Commission orders if the Buying Operator takes any action, or fails to take any action, that would cause such Transferable Item to be out of compliance with the Act, the Commission's Rules, and all terms and conditions of existing Permits and Commission orders."

In checking this box the Buying Operator's acknowledges the subsequent liability pursuant to Rule 218.d.(1).D.ii.

**Rule 218.d.(1).D.iii.**

"For Transferable Items not listed in Rule 218.d.(1).B.i-iii but Related in the Commission's records, an acknowledgment that the Commission will presume that the Transferable Item was transferred, and that the Buying Operator is responsible for compliance with the Act, the Commission's Rules, and all terms and conditions of existing Permits and Commission orders for the Transferable Items."

In checking this box the Buying Operator's acknowledges the subsequent liability pursuant to Rule 218.d.(1).D.iii.

**SUBMITTAL**

**OPERATOR COMMENT AND SUBMITTAL**

I hereby certify all statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Tee Brown Email: tbrown@scoutep.com

Signature: \_\_\_\_\_ Title: Regulatory Manager Date: 12/07/2021

**Wells & Facilities Transferred Summary**

1	Facility Type	API	Facility ID	Location ID	Facility Name	QtrQtr	Sec	Twp	Rng
	LOCATION	-	314757	314757	COLTHARP J E-61N102W #2NENW	NENW	2	1N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO		16700	CHEVRON USA INC					
2	Facility Type	API	Facility ID	Location ID	Facility Name	QtrQtr	Sec	Twp	Rng
	WELL	103-07148	229492	314757	COLTHARP J E #6X	LOT 2	2	1N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO	FEE	16700	CHEVRON USA INC					
3	Facility Type	API	Facility ID	Location ID	Facility Name	QtrQtr	Sec	Twp	Rng
	LOCATION	-	314760	314760	MB LARSON GOV-62N102W #25SESW	SESW	25	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO		16700	CHEVRON USA INC					
4	Facility Type	API	Facility ID	Location ID	Facility Name	QtrQtr	Sec	Twp	Rng
	WELL	103-07155	229499	314760	MB LARSON GOV #C9 X 25	SESW	25	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO	FEDERAL	16700	CHEVRON USA INC					
5	Facility Type	API	Facility ID	Location ID	Facility Name	QtrQtr	Sec	Twp	Rng
	LOCATION	-	314761	314761	M B LARSON-62N102W #25SWSW	SWSW	25	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO		16700	CHEVRON USA INC					
6	Facility Type	API	Facility ID	Location ID	Facility Name	QtrQtr	Sec	Twp	Rng
	WELL	103-07159	229503	314761	M B LARSON #C10 X 25	SWSW	25	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO	FEE	16700	CHEVRON USA INC					
7	Facility Type	API	Facility ID	Location ID	Facility Name	QtrQtr	Sec	Twp	Rng
	LOCATION	-	314762	314762	F V LARSON-62N102W #36NENW	NENW	36	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO		16700	CHEVRON USA INC					
8	Facility Type	API	Facility ID	Location ID	Facility Name	QtrQtr	Sec	Twp	Rng
	WELL	103-07165	229509	314762	F V LARSON #B-21X	NENW	36	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO	FEE	16700	CHEVRON USA INC					
9	Facility Type	API	Facility ID	Location ID	Facility Name	QtrQtr	Sec	Twp	Rng
	FLOWLINE SYSTEM	-	479406	314763	CS39 MULTI PHASE PRODUCTION #	SWSW	25	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					

	RIO BLANCO		16700	CHEVRON USA INC					
10	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	LOCATION	-	314763	314763	M B LARSON-62N102W #25SWSW	SWSW	25	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO		16700	CHEVRON USA INC					
11	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	WELL	103-07173	229517	314763	M B LARSON #C11 X 25	SWSW	25	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO	FEE	16700	CHEVRON USA INC					
12	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	LOCATION	-	314765	314765	M B LARSON-62N102W #26SENE	SENE	26	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO		16700	CHEVRON USA INC					
13	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	WELL	103-07177	229521	314765	M B LARSON #D4 X 26	SENE	26	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO	FEE	16700	CHEVRON USA INC					
14	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	LOCATION	-	314767	314767	FEE-62N102W #29SWSE	SWSE	29	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO		16700	CHEVRON USA INC					
15	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	WELL	103-07180	229524	314767	FEE #72X	SWSE	29	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO	FEE	16700	CHEVRON USA INC					
16	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	LOCATION	-	314771	314771	RAVEN (RE-ENTRY)-62N102W #31SWNE	SWNE	31	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO		16700	CHEVRON USA INC					
17	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	WELL	103-07188	229532	314771	RAVEN (RE-ENTRY) #A-5X	SWNE	31	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO	FEE	16700	CHEVRON USA INC					
18	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	LOCATION	-	314772	314772	CARNEY UNIT-61N102W #4NENE	NENE	4	1N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					

	RIO BLANCO		16700	CHEVRON USA INC					
19	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	WELL	103-07191	229535	314772	CARNEY UNIT #2X	NENE	4	1N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO	FEE	16700	CHEVRON USA INC					
20	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	LOCATION	-	314773	314773	HEFLEY, M E-61N102W #2SENV	SENV	2	1N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO		16700	CHEVRON USA INC					
21	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	WELL	103-07196	229540	314773	HEFLEY, M E #5X	SENV	2	1N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO	FEE	16700	CHEVRON USA INC					
22	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	LOCATION	-	314774	314774	EMERALD (RE-ENTRY)-62N102W #30SESW	SESW	30	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO		16700	CHEVRON USA INC					
23	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	WELL	103-07201	229544	314774	EMERALD (RE-ENTRY) #47X	SESW	30	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO	FEE	16700	CHEVRON USA INC					
24	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	LOCATION	-	314780	314780	LARSON, F V-62N102W #34SWSE	SWSE	34	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO		16700	CHEVRON USA INC					
25	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	WELL	103-07216	229559	314780	LARSON, F V #A-2X	SWSE	34	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO	FEDERAL	16700	CHEVRON USA INC					
26	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	LOCATION	-	314782	314782	LEVISON-62N102W #26NWSW	NWSW	26	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO		16700	CHEVRON USA INC					
27	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	WELL	103-07222	229565	314782	LEVISON #25X	NWSW	26	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					

	RIO BLANCO	FEE	16700	CHEVRON USA INC					
28	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	LOCATION	-	314785	314785	F V LARSON-62N102W #36SEW	SEW	36	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO		16700	CHEVRON USA INC					
29	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	WELL	103-07227	229570	314785	F V LARSON #B-22X	SEW	36	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO	FEE	16700	CHEVRON USA INC					
30	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	LOCATION	-	314788	314788	F V LARSON-62N102W #35NESW	NESW	35	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO		16700	CHEVRON USA INC					
31	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	WELL	103-07242	229585	314788	F V LARSON #B-23X	NESW	35	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO	FEE	16700	CHEVRON USA INC					
32	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	LOCATION	-	314789	314789	CARNEY-62N102W #35SWNE	SWNE	35	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO		16700	CHEVRON USA INC					
33	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	WELL	103-07245	229588	314789	CARNEY #22 X 35	SWNE	35	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO	FEDERAL	16700	CHEVRON USA INC					
34	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	LOCATION	-	314793	314793	EMERALD-62N102W #30SWSW	SWSW	30	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO		16700	CHEVRON USA INC					
35	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	WELL	103-07257	229600	314793	EMERALD #48X	SWSW	30	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO	FEE	16700	CHEVRON USA INC					
36	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	LOCATION	-	314795	314795	CARNEY C T-62N102W #35SWNW	SWNW	35	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					

	RIO BLANCO		16700	CHEVRON USA INC					
37	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	WELL	103-07262	229605	314795	CARNEY C T #23X-35	SWNW	35	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO	FEDERAL	16700	CHEVRON USA INC					
38	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	LOCATION	-	314798	314798	LEVISON-62N102W #26NESW	NESW	26	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO		16700	CHEVRON USA INC					
39	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	WELL	103-07267	229610	314798	LEVISON #26X	NESW	26	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO	FEDERAL	16700	CHEVRON USA INC					
40	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	LOCATION	-	314799	314799	M B LARSON-62N102W #25SWNW	SWNW	25	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO		16700	CHEVRON USA INC					
41	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	WELL	103-07270	229613	314799	M B LARSON #C12 X 25	SWNW	25	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO	FEE	16700	CHEVRON USA INC					
42	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	LOCATION	-	314801	314801	FEE-62N102W #22SWSW	SWSW	22	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO		16700	CHEVRON USA INC					
43	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	WELL	103-07274	229617	314801	FEE #73X	SWSW	22	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO	FEE	16700	CHEVRON USA INC					
44	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	LOCATION	-	314802	314802	UNION PACIFIC-62N102W #31SENE	SENE	31	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO		16700	CHEVRON USA INC					
45	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	WELL	103-07276	229619	314802	UNION PACIFIC #71 X 31	SENE	31	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO	FEE	16700	CHEVRON USA INC					

46	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	LOCATION	-	314803	314803	J E COLTHARP-62N102W #36SESE	SESE	36	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO		16700	CHEVRON USA INC					
47	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	WELL	103-07279	229622	314803	J E COLTHARP #7X	SESE	36	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO	FEE	16700	CHEVRON USA INC					
48	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	LOCATION	-	314804	314804	CARNEY C T-62N102W #35NWNE	NWNE	35	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO		16700	CHEVRON USA INC					
49	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	WELL	103-07283	229626	314804	CARNEY C T #24X35	NWNE	35	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO	FEDERAL	16700	CHEVRON USA INC					
50	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	LOCATION	-	314806	314806	LEVISON-62N102W #27SESE	SESE	27	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO		16700	CHEVRON USA INC					
51	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	WELL	103-07289	229632	314806	LEVISON #27X	SESE	27	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO	FEDERAL	16700	CHEVRON USA INC					
52	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	LOCATION	-	314808	314808	HEFLEY, M E-61N102W #3NENE	NENE	3	1N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO		16700	CHEVRON USA INC					
53	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	WELL	103-07293	229636	314808	HEFLEY, M E #6X	NENE	3	1N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO	FEE	16700	CHEVRON USA INC					
54	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	LOCATION	-	314810	314810	EMERALD-62N103W #25NWSE	NWSE	25	2N	103W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO		16700	CHEVRON USA INC					

55	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	WELL	103-07296	229639	314810	EMERALD #49X	NWSE	25	2N	103W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO	FEE	16700	CHEVRON USA INC					
56	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	LOCATION	-	314815	314815	FEE-62N102W #30SESE	SESE	30	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO		16700	CHEVRON USA INC					
57	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	WELL	103-07307	229650	314815	FEE #74X	SESE	30	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO	FEE	16700	CHEVRON USA INC					
58	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	LOCATION	-	314817	314817	LEVISON-62N102W #27NENE	NENE	27	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO		16700	CHEVRON USA INC					
59	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	WELL	103-07316	229659	314817	LEVISON #28X	NENE	27	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO	FEE	16700	CHEVRON USA INC					
60	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	LOCATION	-	314820	314820	LEVISON-62N102W #26NESW	NESW	26	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO		16700	CHEVRON USA INC					
61	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	WELL	103-07320	229663	314820	LEVISON #29X	NESW	26	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO	FEDERAL	16700	CHEVRON USA INC					
62	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	LOCATION	-	314825	314825	FEE-62N102W #27NWNE	NWNE	27	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO		16700	CHEVRON USA INC					
63	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	WELL	103-07326	229669	314825	FEE #75X	NWNE	27	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO	FEE	16700	CHEVRON USA INC					
64	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>

	LOCATION	-	314827	314827	EMERALD-62N103W #25SWSE	SWSE	25	2N	103W
	<u>County</u>	<u>Min.Owner. Type</u>		<u>Current Operator Num</u>	<u>Current Operator Name</u>				
	RIO BLANCO			16700	CHEVRON USA INC				
65	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	WELL	103-07331	229674	314827	EMERALD #50X	SWSE	25	2N	103W
	<u>County</u>	<u>Min.Owner. Type</u>		<u>Current Operator Num</u>	<u>Current Operator Name</u>				
	RIO BLANCO	FEE		16700	CHEVRON USA INC				
66	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	LOCATION	-	314828	314828	EMERALD-62N102W #31SWNW	SWNW	31	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>		<u>Current Operator Num</u>	<u>Current Operator Name</u>				
	RIO BLANCO			16700	CHEVRON USA INC				
67	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	WELL	103-07333	229676	314828	EMERALD #51X	SWNW	31	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>		<u>Current Operator Num</u>	<u>Current Operator Name</u>				
	RIO BLANCO	FEE		16700	CHEVRON USA INC				
68	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	LOCATION	-	314830	314830	CHEVRON FEE (RE- ENTRY-62N102W #30SESE	SESE	30	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>		<u>Current Operator Num</u>	<u>Current Operator Name</u>				
	RIO BLANCO			16700	CHEVRON USA INC				
69	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	WELL	103-07339	229682	314830	CHEVRON FEE (RE- ENTRY #76X	SESE	30	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>		<u>Current Operator Num</u>	<u>Current Operator Name</u>				
	RIO BLANCO	FEE		16700	CHEVRON USA INC				
70	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	LOCATION	-	314834	314834	LEVISON-62N102W #27SENE	SENE	27	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>		<u>Current Operator Num</u>	<u>Current Operator Name</u>				
	RIO BLANCO			16700	CHEVRON USA INC				
71	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	WELL	103-07351	229694	314834	LEVISON #30X	SENE	27	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>		<u>Current Operator Num</u>	<u>Current Operator Name</u>				
	RIO BLANCO	FEDERAL		16700	CHEVRON USA INC				
72	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	LOCATION	-	314835	314835	LEVISON-62N102W #26NWNW	NWNW	26	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>		<u>Current Operator Num</u>	<u>Current Operator Name</u>				
	RIO BLANCO			16700	CHEVRON USA INC				

73	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	WELL	103-07353	229696	314835	LEVISON #31X	NWNW	26	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO	FEDERAL	16700	CHEVRON USA INC					
74	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	LOCATION	-	314838	314838	U P-62N102W #31SENE	SENE	31	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO		16700	CHEVRON USA INC					
75	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	WELL	103-07364	229707	314838	U P #72 X 31	SENE	31	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO	FEE	16700	CHEVRON USA INC					
76	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	LOCATION	-	314840	314840	EMERALD-62N102W #31NENW	NENW	31	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO		16700	CHEVRON USA INC					
77	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	WELL	103-07371	229714	314840	EMERALD #52X	NENW	31	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO	FEE	16700	CHEVRON USA INC					
78	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	LOCATION	-	314841	314841	EMERALD-62N103W #25SESW	SESW	25	2N	103W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO		16700	CHEVRON USA INC					
79	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	WELL	103-07376	229719	314841	EMERALD #53X	SESW	25	2N	103W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO	FEE	16700	CHEVRON USA INC					
80	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	LOCATION	-	314843	314843	UPRR (RE-ENTRY)-62N102W #29SWSW	SWSW	29	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO		16700	CHEVRON USA INC					
81	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	WELL	103-07386	229729	314843	UPRR (RE-ENTRY) #73X-29	SWSW	29	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO	FEE	16700	CHEVRON USA INC					

82	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	LOCATION	-	314847	314847	UNION PACIFIC-62N102W #32SESE	SESE	32	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO		16700	CHEVRON USA INC					
83	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	WELL	103-07402	229745	314847	UNION PACIFIC #75 X 32	SESE	32	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO	FEE	16700	CHEVRON USA INC					
84	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	LOCATION	-	314852	314852	CARNEY C T-62N102W #34NENE	NENE	34	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO		16700	CHEVRON USA INC					
85	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	WELL	103-07415	229758	314852	CARNEY C T #25 X 34	NENE	34	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO	FEDERAL	16700	CHEVRON USA INC					
86	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	LOCATION	-	314853	314853	UNION PACIFIC-62N102W #27NWSW	NWSW	27	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO		16700	CHEVRON USA INC					
87	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	WELL	103-07416	229759	314853	UNION PACIFIC #74 X 27	NWSW	27	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO	FEE	16700	CHEVRON USA INC					
88	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	LOCATION	-	314855	314855	UNION PACIFIC-62N102W #21SWSE	SWSE	21	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO		16700	CHEVRON USA INC					
89	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	WELL	103-07421	229764	314855	UNION PACIFIC #76 X 21	SWSE	21	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO	FEE	16700	CHEVRON USA INC					
90	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	LOCATION	-	314856	314856	FEE-62N102W #29SESE	SESE	29	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO		16700	CHEVRON USA INC					

91	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	WELL	103-07424	229767	314856	FEE #79X	SESE	29	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO	FEE		16700	CHEVRON USA INC				
92	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	LOCATION	-	314857	314857	UNION PACIFIC-62N102W #21SWSE	SWSE	21	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO			16700	CHEVRON USA INC				
93	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	WELL	103-07426	229769	314857	UNION PACIFIC #78X-21	SWSE	21	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO	FEE		16700	CHEVRON USA INC				
94	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	LOCATION	-	314859	314859	FEE-62N102W #28SWNE	SWNE	28	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO			16700	CHEVRON USA INC				
95	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	WELL	103-07434	229777	314859	FEE #78X	SWNE	28	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO	FEE		16700	CHEVRON USA INC				
96	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	LOCATION	-	314862	314862	UNION PACIFIC-62N102W #34NWSW	NWSW	34	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO			16700	CHEVRON USA INC				
97	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	WELL	103-07440	229783	314862	UNION PACIFIC #B3 X 34	NWSW	34	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO	FEE		16700	CHEVRON USA INC				
98	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	LOCATION	-	314863	314863	GENTRY-61N102W #3SENE	SENE	3	1N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO			16700	CHEVRON USA INC				
99	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	WELL	103-07442	229785	314863	GENTRY #6X	SENE	3	1N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO	FEE		16700	CHEVRON USA INC				
100	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>

	LOCATION	-	314865	314865	COLTHARP, W H-61N102W #2NENW	NENW	2	1N	102W
	<u>County</u>	<u>Min.Owner. Type</u>		<u>Current Operator Num</u>	<u>Current Operator Name</u>				
	RIO BLANCO			16700	CHEVRON USA INC				
101	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	WELL	103-07447	229790	314865	COLTHARP, W H #A-6X	NENW	2	1N	102W
	<u>County</u>	<u>Min.Owner. Type</u>		<u>Current Operator Num</u>	<u>Current Operator Name</u>				
	RIO BLANCO	FEE		16700	CHEVRON USA INC				
102	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	LOCATION	-	314866	314866	UNION PACIFIC-62N102W #32SWSE	SWSE	32	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>		<u>Current Operator Num</u>	<u>Current Operator Name</u>				
	RIO BLANCO			16700	CHEVRON USA INC				
103	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	TANK BATTERY	-	462174	314866	CS 19 #	SWSE	32	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>		<u>Current Operator Num</u>	<u>Current Operator Name</u>				
	RIO BLANCO			16700	CHEVRON USA INC				
104	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	WELL	103-07448	229791	314866	UNION PACIFIC #79X-32	SWSE	32	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>		<u>Current Operator Num</u>	<u>Current Operator Name</u>				
	RIO BLANCO	FEE		16700	CHEVRON USA INC				
105	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	LOCATION	-	314869	314869	UNION PACIFIC-62N102W #32NENW	NENW	32	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>		<u>Current Operator Num</u>	<u>Current Operator Name</u>				
	RIO BLANCO			16700	CHEVRON USA INC				
106	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	WELL	103-07454	229797	314869	UNION PACIFIC #77 X 32	NENW	32	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>		<u>Current Operator Num</u>	<u>Current Operator Name</u>				
	RIO BLANCO	FEE		16700	CHEVRON USA INC				
107	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	LOCATION	-	314872	314872	UNION PACIFIC-62N102W #28NWSW	NWSW	28	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>		<u>Current Operator Num</u>	<u>Current Operator Name</u>				
	RIO BLANCO			16700	CHEVRON USA INC				
108	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	WELL	103-07460	229803	314872	UNION PACIFIC #80X-28	NWSW	28	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>		<u>Current Operator Num</u>	<u>Current Operator Name</u>				
	RIO BLANCO	FEE		16700	CHEVRON USA INC				
109	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>

	LOCATION	-	314873	314873	S W MCLAUGHLIN-62N102W #33NWSW	NWSW	33	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>		<u>Current Operator Num</u>	<u>Current Operator Name</u>				
	RIO BLANCO			16700	CHEVRON USA INC				
110	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	NONFACILITY	-	436525	314873	S W MCLAUGHLIN 7X SPILL #	NWSW	33	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>		<u>Current Operator Num</u>	<u>Current Operator Name</u>				
	RIO BLANCO			16700	CHEVRON USA INC				
111	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	WELL	103-07461	229804	314873	S W MCLAUGHLIN #7X	NWSW	33	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>		<u>Current Operator Num</u>	<u>Current Operator Name</u>				
	RIO BLANCO	FEE		16700	CHEVRON USA INC				
112	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	LOCATION	-	314875	314875	MCLAUGHLIN-62N102W #33NESE	NESE	33	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>		<u>Current Operator Num</u>	<u>Current Operator Name</u>				
	RIO BLANCO			16700	CHEVRON USA INC				
113	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	WELL	103-07465	229808	314875	MCLAUGHLIN #9 X 33	NESE	33	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>		<u>Current Operator Num</u>	<u>Current Operator Name</u>				
	RIO BLANCO	FEE		16700	CHEVRON USA INC				
114	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	LOCATION	-	314876	314876	CARNEY C T-62N102W #34NESW	NESW	34	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>		<u>Current Operator Num</u>	<u>Current Operator Name</u>				
	RIO BLANCO			16700	CHEVRON USA INC				
115	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	WELL	103-07466	229809	314876	CARNEY C T #27X- 34	NESW	34	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>		<u>Current Operator Num</u>	<u>Current Operator Name</u>				
	RIO BLANCO	FEE		16700	CHEVRON USA INC				
116	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	LOCATION	-	314879	314879	CARNEY C T-62N102W #34SENW	SENW	34	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>		<u>Current Operator Num</u>	<u>Current Operator Name</u>				
	RIO BLANCO			16700	CHEVRON USA INC				
117	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	WELL	103-07474	229817	314879	CARNEY C T #28X-34	SENW	34	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>		<u>Current Operator Num</u>	<u>Current Operator Name</u>				
	RIO BLANCO	FEDERAL		16700	CHEVRON USA INC				
118	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>

	LOCATION	-	314880	314880	LEVISON-62N102W #27SESE	SESE	27	2N	102W
	<u>County</u>	<u>Min.Owner.Type</u>		<u>Current Operator Num</u>	<u>Current Operator Name</u>				
	RIO BLANCO			16700	CHEVRON USA INC				
119	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	WELL	103-07475	229818	314880	LEVISON #32X	SESE	27	2N	102W
	<u>County</u>	<u>Min.Owner.Type</u>		<u>Current Operator Num</u>	<u>Current Operator Name</u>				
	RIO BLANCO	FEE		16700	CHEVRON USA INC				
120	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	WELL	103-07481	229824	314882	UNION PACIFIC #85X-34	NWNW	34	2N	102W
	<u>County</u>	<u>Min.Owner.Type</u>		<u>Current Operator Num</u>	<u>Current Operator Name</u>				
	RIO BLANCO	FEE		16700	CHEVRON USA INC				
121	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	LOCATION	-	314883	314883	UNION PACIFIC-62N102W #27NWSE	NWSE	27	2N	102W
	<u>County</u>	<u>Min.Owner.Type</u>		<u>Current Operator Num</u>	<u>Current Operator Name</u>				
	RIO BLANCO			16700	CHEVRON USA INC				
122	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	WELL	103-07482	229825	314883	UNION PACIFIC #86X-27	NWSE	27	2N	102W
	<u>County</u>	<u>Min.Owner.Type</u>		<u>Current Operator Num</u>	<u>Current Operator Name</u>				
	RIO BLANCO	FEE		16700	CHEVRON USA INC				
123	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	LOCATION	-	314889	314889	MCLAUGHLIN-62N102W #28SESW	SESW	28	2N	102W
	<u>County</u>	<u>Min.Owner.Type</u>		<u>Current Operator Num</u>	<u>Current Operator Name</u>				
	RIO BLANCO			16700	CHEVRON USA INC				
124	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	WELL	103-07490	229833	314889	MCLAUGHLIN #10 X 28	SESW	28	2N	102W
	<u>County</u>	<u>Min.Owner.Type</u>		<u>Current Operator Num</u>	<u>Current Operator Name</u>				
	RIO BLANCO	FEE		16700	CHEVRON USA INC				
125	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	LOCATION	-	314890	314890	FEE-62N102W #22SWSW	SWSW	22	2N	102W
	<u>County</u>	<u>Min.Owner.Type</u>		<u>Current Operator Num</u>	<u>Current Operator Name</u>				
	RIO BLANCO			16700	CHEVRON USA INC				
126	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	WELL	103-07491	229834	314890	FEE #80X	SWSW	22	2N	102W
	<u>County</u>	<u>Min.Owner.Type</u>		<u>Current Operator Num</u>	<u>Current Operator Name</u>				
	RIO BLANCO	FEE		16700	CHEVRON USA INC				
127	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>

	LOCATION	-	314892	314892	UNION PACIFIC-62N102W #28SWNW	SWNW	28	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>		<u>Current Operator Num</u>	<u>Current Operator Name</u>				
	RIO BLANCO			16700	CHEVRON USA INC				
128	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	WELL	103-07494	229837	314892	UNION PACIFIC #82 X 28	SWNW	28	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>		<u>Current Operator Num</u>	<u>Current Operator Name</u>				
	RIO BLANCO	FEE		16700	CHEVRON USA INC				
129	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	LOCATION	-	314893	314893	UNION PACIFIC-62N102W #28NESW	NESW	28	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>		<u>Current Operator Num</u>	<u>Current Operator Name</u>				
	RIO BLANCO			16700	CHEVRON USA INC				
130	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	WELL	103-07495	229838	314893	UNION PACIFIC #84 X 28	NESW	28	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>		<u>Current Operator Num</u>	<u>Current Operator Name</u>				
	RIO BLANCO	FEE		16700	CHEVRON USA INC				
131	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	LOCATION	-	314895	314895	UNION PACIFIC-62N102W #29NWSE	NWSE	29	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>		<u>Current Operator Num</u>	<u>Current Operator Name</u>				
	RIO BLANCO			16700	CHEVRON USA INC				
132	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	WELL	103-07499	229841	314895	UNION PACIFIC #81 X 29	NWSE	29	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>		<u>Current Operator Num</u>	<u>Current Operator Name</u>				
	RIO BLANCO	FEE		16700	CHEVRON USA INC				
133	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	LOCATION	-	314896	314896	UNION PACIFIC-62N102W #28NWNW	NWNW	28	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>		<u>Current Operator Num</u>	<u>Current Operator Name</u>				
	RIO BLANCO			16700	CHEVRON USA INC				
134	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	WELL	103-07500	229842	314896	UNION PACIFIC #83 X 28	NWNW	28	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>		<u>Current Operator Num</u>	<u>Current Operator Name</u>				
	RIO BLANCO	FEE		16700	CHEVRON USA INC				
135	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	LOCATION	-	314900	314900	UNION PACIFIC-62N102W #29SESW	SESW	29	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>		<u>Current Operator Num</u>	<u>Current Operator Name</u>				
	RIO BLANCO			16700	CHEVRON USA INC				
136	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>

	WELL	103-07509	229851	314900	UNION PACIFIC #87 X 29	SESW	29	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>		<u>Current Operator Num</u>	<u>Current Operator Name</u>				
	RIO BLANCO	FEE		16700	CHEVRON USA INC				
137	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	LOCATION	-	314903	314903	UNION PACIFIC-62N102W #21NWSE	NWSE	21	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>		<u>Current Operator Num</u>	<u>Current Operator Name</u>				
	RIO BLANCO			16700	CHEVRON USA INC				
138	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	WELL	103-07514	229856	314903	UNION PACIFIC #88 X 21	NWSE	21	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>		<u>Current Operator Num</u>	<u>Current Operator Name</u>				
	RIO BLANCO	FEE		16700	CHEVRON USA INC				
139	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	LOCATION	-	314904	314904	FEE-62N102W #27NWNW	NWNW	27	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>		<u>Current Operator Num</u>	<u>Current Operator Name</u>				
	RIO BLANCO			16700	CHEVRON USA INC				
140	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	WELL	103-07519	229861	314904	FEE #81X	NWNW	27	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>		<u>Current Operator Num</u>	<u>Current Operator Name</u>				
	RIO BLANCO	FEE		16700	CHEVRON USA INC				
141	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	LOCATION	-	314905	314905	LEVISON-62N102W #27NESE	NESE	27	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>		<u>Current Operator Num</u>	<u>Current Operator Name</u>				
	RIO BLANCO			16700	CHEVRON USA INC				
142	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	WELL	103-07521	229863	314905	LEVISON #33X	NESE	27	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>		<u>Current Operator Num</u>	<u>Current Operator Name</u>				
	RIO BLANCO	FEE		16700	CHEVRON USA INC				
143	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	LOCATION	-	314906	314906	CARNEY C T-62N102W #34SENE	SENE	34	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>		<u>Current Operator Num</u>	<u>Current Operator Name</u>				
	RIO BLANCO			16700	CHEVRON USA INC				
144	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	WELL	103-07526	229868	314906	CARNEY C T #30 X 34	SENE	34	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>		<u>Current Operator Num</u>	<u>Current Operator Name</u>				
	RIO BLANCO	FEDERAL		16700	CHEVRON USA INC				
145	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	LOCATION	-	314908	314908	FEE-62N102W #28NWSE	NWSE	28	2N	102W

	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO		16700	CHEVRON USA INC					
146	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	WELL	103-07529	229871	314908	FEE #82X	NWSE	28	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO	FEE	16700	CHEVRON USA INC					
147	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	LOCATION	-	314909	314909	MCLAUGHLIN, S W-62N102W #33SESW	SESW	33	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO		16700	CHEVRON USA INC					
148	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	WELL	103-07530	229872	314909	MCLAUGHLIN, S W #8X	SESW	33	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO	FEE	16700	CHEVRON USA INC					
149	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	LOCATION	-	314910	314910	MCLAUGHLIN, S W-62N102W #33SESW	SESW	33	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO		16700	CHEVRON USA INC					
150	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	WELL	103-07535	229877	314910	MCLAUGHLIN, S W #9X	SESW	33	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO	FEE	16700	CHEVRON USA INC					

### Incidents Transferred Summary

	<u>Document Numbers</u>	<u>Incident Type</u>	<u>Incident Date</u>	<u>Current Op #</u>	<u>Current Op. Name</u>
1	402878930	UNRESOLVED SPILL AND RELEASES	11/22/2021	16700	CHEVRON USA INC
2	679704070	UNRESOLVED FIELD INSPECTION REPORTS WITH OUSTANDIN	05/15/2019	16700	CHEVRON USA INC
3	679704641	UNRESOLVED FIELD INSPECTION REPORTS WITH OUSTANDIN	06/27/2019	16700	CHEVRON USA INC
4	679705184	UNRESOLVED FIELD INSPECTION REPORTS WITH OUSTANDIN	08/22/2019	16700	CHEVRON USA INC
5	679706790	UNRESOLVED FIELD INSPECTION REPORTS WITH OUSTANDIN	01/03/2020	16700	CHEVRON USA INC

6	<u>Document Numbers</u>	<u>Incident Type</u>	<u>Incident Date</u>	<u>Current Op #</u>	<u>Current Op. Name</u>
	679706792	UNRESOLVED FIELD INSPECTION REPORTS WITH OUSTANDIN	01/03/2020	16700	CHEVRON USA INC
7	<u>Document Numbers</u>	<u>Incident Type</u>	<u>Incident Date</u>	<u>Current Op #</u>	<u>Current Op. Name</u>
	679706794	UNRESOLVED FIELD INSPECTION REPORTS WITH OUSTANDIN	01/03/2020	16700	CHEVRON USA INC
8	<u>Document Numbers</u>	<u>Incident Type</u>	<u>Incident Date</u>	<u>Current Op #</u>	<u>Current Op. Name</u>
	679706817	UNRESOLVED FIELD INSPECTION REPORTS WITH OUSTANDIN	01/03/2020	16700	CHEVRON USA INC
9	<u>Document Numbers</u>	<u>Incident Type</u>	<u>Incident Date</u>	<u>Current Op #</u>	<u>Current Op. Name</u>
	679707056	UNRESOLVED FIELD INSPECTION REPORTS WITH OUSTANDIN	01/23/2020	16700	CHEVRON USA INC
10	<u>Document Numbers</u>	<u>Incident Type</u>	<u>Incident Date</u>	<u>Current Op #</u>	<u>Current Op. Name</u>
	685100057	UNRESOLVED FIELD INSPECTION REPORTS WITH OUSTANDIN	08/23/2016	16700	CHEVRON USA INC
11	<u>Document Numbers</u>	<u>Incident Type</u>	<u>Incident Date</u>	<u>Current Op #</u>	<u>Current Op. Name</u>
	693800343	UNRESOLVED FIELD INSPECTION REPORTS WITH OUSTANDIN	05/29/2019	16700	CHEVRON USA INC
12	<u>Document Numbers</u>	<u>Incident Type</u>	<u>Incident Date</u>	<u>Current Op #</u>	<u>Current Op. Name</u>
	693800785	UNRESOLVED FIELD INSPECTION REPORTS WITH OUSTANDIN	07/02/2019	16700	CHEVRON USA INC
13	<u>Document Numbers</u>	<u>Incident Type</u>	<u>Incident Date</u>	<u>Current Op #</u>	<u>Current Op. Name</u>
	696201060	UNRESOLVED FIELD INSPECTION REPORTS WITH OUSTANDIN	02/28/2020	16700	CHEVRON USA INC
14	<u>Document Numbers</u>	<u>Incident Type</u>	<u>Incident Date</u>	<u>Current Op #</u>	<u>Current Op. Name</u>
	696202348	UNRESOLVED FIELD INSPECTION REPORTS WITH OUSTANDIN	02/19/2021	16700	CHEVRON USA INC
15	<u>Document Numbers</u>	<u>Incident Type</u>	<u>Incident Date</u>	<u>Current Op #</u>	<u>Current Op. Name</u>
	696204078	UNRESOLVED FIELD INSPECTION REPORTS WITH OUSTANDIN	09/12/2022	16700	CHEVRON USA INC
16	<u>Document Numbers</u>	<u>Incident Type</u>	<u>Incident Date</u>	<u>Current Op #</u>	<u>Current Op. Name</u>
	700400158	UNRESOLVED FIELD INSPECTION REPORTS WITH OUSTANDIN	02/24/2020	16700	CHEVRON USA INC
17	<u>Document Numbers</u>	<u>Incident Type</u>	<u>Incident Date</u>	<u>Current Op #</u>	<u>Current Op. Name</u>
	700401654	UNRESOLVED FIELD INSPECTION REPORTS WITH OUSTANDIN	05/22/2020	16700	CHEVRON USA INC
18	<u>Document Numbers</u>	<u>Incident Type</u>	<u>Incident Date</u>	<u>Current Op #</u>	<u>Current Op. Name</u>
	700401660	UNRESOLVED FIELD INSPECTION REPORTS WITH OUSTANDIN	05/22/2020	16700	CHEVRON USA INC

19	<u>Document Numbers</u>	<u>Incident Type</u>	<u>Incident Date</u>	<u>Current Op #</u>	<u>Current Op. Name</u>
	700401953	UNRESOLVED FIELD INSPECTION REPORTS WITH OUSTANDIN	06/15/2020	16700	CHEVRON USA INC
20	<u>Document Numbers</u>	<u>Incident Type</u>	<u>Incident Date</u>	<u>Current Op #</u>	<u>Current Op. Name</u>
	700402100	UNRESOLVED FIELD INSPECTION REPORTS WITH OUSTANDIN	06/23/2020	16700	CHEVRON USA INC
21	<u>Document Numbers</u>	<u>Incident Type</u>	<u>Incident Date</u>	<u>Current Op #</u>	<u>Current Op. Name</u>
	700402112	UNRESOLVED FIELD INSPECTION REPORTS WITH OUSTANDIN	06/23/2020	16700	CHEVRON USA INC
22	<u>Document Numbers</u>	<u>Incident Type</u>	<u>Incident Date</u>	<u>Current Op #</u>	<u>Current Op. Name</u>
	700402272	UNRESOLVED FIELD INSPECTION REPORTS WITH OUSTANDIN	07/06/2020	16700	CHEVRON USA INC
23	<u>Document Numbers</u>	<u>Incident Type</u>	<u>Incident Date</u>	<u>Current Op #</u>	<u>Current Op. Name</u>
	700403541	UNRESOLVED FIELD INSPECTION REPORTS WITH OUSTANDIN	09/22/2020	16700	CHEVRON USA INC
24	<u>Document Numbers</u>	<u>Incident Type</u>	<u>Incident Date</u>	<u>Current Op #</u>	<u>Current Op. Name</u>
	700403916	UNRESOLVED FIELD INSPECTION REPORTS WITH OUSTANDIN	10/27/2020	16700	CHEVRON USA INC
25	<u>Document Numbers</u>	<u>Incident Type</u>	<u>Incident Date</u>	<u>Current Op #</u>	<u>Current Op. Name</u>
	700403920	UNRESOLVED FIELD INSPECTION REPORTS WITH OUSTANDIN	10/27/2020	16700	CHEVRON USA INC
26	<u>Document Numbers</u>	<u>Incident Type</u>	<u>Incident Date</u>	<u>Current Op #</u>	<u>Current Op. Name</u>
	700404657	UNRESOLVED FIELD INSPECTION REPORTS WITH OUSTANDIN	12/18/2020	16700	CHEVRON USA INC
27	<u>Document Numbers</u>	<u>Incident Type</u>	<u>Incident Date</u>	<u>Current Op #</u>	<u>Current Op. Name</u>
	700405315	UNRESOLVED FIELD INSPECTION REPORTS WITH OUSTANDIN	02/03/2021	16700	CHEVRON USA INC
28	<u>Document Numbers</u>	<u>Incident Type</u>	<u>Incident Date</u>	<u>Current Op #</u>	<u>Current Op. Name</u>
	700405414	UNRESOLVED FIELD INSPECTION REPORTS WITH OUSTANDIN	02/16/2021	16700	CHEVRON USA INC
29	<u>Document Numbers</u>	<u>Incident Type</u>	<u>Incident Date</u>	<u>Current Op #</u>	<u>Current Op. Name</u>
	700405420	UNRESOLVED FIELD INSPECTION REPORTS WITH OUSTANDIN	02/16/2021	16700	CHEVRON USA INC
30	<u>Document Numbers</u>	<u>Incident Type</u>	<u>Incident Date</u>	<u>Current Op #</u>	<u>Current Op. Name</u>
	700405524	UNRESOLVED FIELD INSPECTION REPORTS WITH OUSTANDIN	02/23/2021	16700	CHEVRON USA INC
31	<u>Document Numbers</u>	<u>Incident Type</u>	<u>Incident Date</u>	<u>Current Op #</u>	<u>Current Op. Name</u>
	700405533	UNRESOLVED FIELD INSPECTION REPORTS WITH OUSTANDIN	02/23/2021	16700	CHEVRON USA INC

32	<u>Document Numbers</u>	<u>Incident Type</u>	<u>Incident Date</u>	<u>Current Op #</u>	<u>Current Op. Name</u>
	701102421	UNRESOLVED FIELD INSPECTION REPORTS WITH OUSTANDIN	01/04/2022	16700	CHEVRON USA INC
33	<u>Document Numbers</u>	<u>Incident Type</u>	<u>Incident Date</u>	<u>Current Op #</u>	<u>Current Op. Name</u>
	701103165	UNRESOLVED FIELD INSPECTION REPORTS WITH OUSTANDIN	05/19/2022	16700	CHEVRON USA INC
34	<u>Document Numbers</u>	<u>Incident Type</u>	<u>Incident Date</u>	<u>Current Op #</u>	<u>Current Op. Name</u>
	701103504	UNRESOLVED FIELD INSPECTION REPORTS WITH OUSTANDIN	08/30/2022	16700	CHEVRON USA INC
35	<u>Document Numbers</u>	<u>Incident Type</u>	<u>Incident Date</u>	<u>Current Op #</u>	<u>Current Op. Name</u>
	701500049	UNRESOLVED FIELD INSPECTION REPORTS WITH OUSTANDIN	03/05/2021	16700	CHEVRON USA INC
36	<u>Document Numbers</u>	<u>Incident Type</u>	<u>Incident Date</u>	<u>Current Op #</u>	<u>Current Op. Name</u>
	701500057	UNRESOLVED FIELD INSPECTION REPORTS WITH OUSTANDIN	03/17/2021	16700	CHEVRON USA INC
37	<u>Document Numbers</u>	<u>Incident Type</u>	<u>Incident Date</u>	<u>Current Op #</u>	<u>Current Op. Name</u>
	701500061	UNRESOLVED FIELD INSPECTION REPORTS WITH OUSTANDIN	03/17/2021	16700	CHEVRON USA INC
38	<u>Document Numbers</u>	<u>Incident Type</u>	<u>Incident Date</u>	<u>Current Op #</u>	<u>Current Op. Name</u>
	701500084	UNRESOLVED FIELD INSPECTION REPORTS WITH OUSTANDIN	03/19/2021	16700	CHEVRON USA INC
39	<u>Document Numbers</u>	<u>Incident Type</u>	<u>Incident Date</u>	<u>Current Op #</u>	<u>Current Op. Name</u>
	701500192	UNRESOLVED FIELD INSPECTION REPORTS WITH OUSTANDIN	04/02/2021	16700	CHEVRON USA INC
40	<u>Document Numbers</u>	<u>Incident Type</u>	<u>Incident Date</u>	<u>Current Op #</u>	<u>Current Op. Name</u>
	701500519	UNRESOLVED FIELD INSPECTION REPORTS WITH OUSTANDIN	04/28/2021	16700	CHEVRON USA INC

**Related Wells & Facilities Not Transferred Summary**

< No row provided >

**Related Incidents Not Transferred Summary**

< No row provided >

**Wells & Facilities Proposed Not Transferred Summary**

< No row provided >

**Incidents Proposed Not Transferred Summary**

< No row provided >

## Attachment List

<b>Att Doc Num</b>	<b>Name</b>
1311290	BUYER NOTIFIED LOCAL GOVT ATTESTATION
1311291	CORRESPONDENCE
1311292	CORRESPONDENCE
402890528	Form 09 SUBMITTED
402891427	FORM 9 SUBSEQUENT ATTESTATION
403316097	EDD-S-INCIDENTS-TRANSFERRED
403316190	EDD-S-WELLS-FACILITIES-TRANSFERRED

Total Attach: 7 Files

**COA Type**

**Description**

0 COA

## General Comments

<u>User Group</u>	<u>Comment</u>	<u>Comment Date</u>
Financial Assurance	Both Operators have resolved all issues and accepted the COAs. Form 9 approved.	04/18/2023
Financial Assurance	<p>Here is where we currently stand. It appears that the Spill or Releases are the issue. They need to be entered correctly on the spreadsheet.</p> <p>Chevron #40284700 to Scout #402887795</p> <p>· Location ID #311804 Union Pacific #34-31 Facility ID #444035 Spill or Release AC - 2/5/2021 This is an active Spill or Release and needs to be accounted for. The Facility Type in Column B is Spill or Release with the Facility ID and Location ID in columns E and F respectively.</p> <p>Chevron #402847248 to Scout #402890468</p> <p>· There is one Unaccounted For Facility (Location #314373, EMERALD #4 Facility # 480349 Emerald 4 Flowline spill - AC 8/2/2021) that needs to be accounted for. 2021 This is an active Spill or Release and needs to be accounted for. The Facility Type in Column B is Spill or Release with the Facility ID and Location ID in columns E and F respectively.</p> <p>Chevron #402847267 to Scout #402890493</p> <p>· There is one Unaccounted For Facility (Location #314622 FEE #19, Facility # 448608 SPILL/RELEASE POINT -AC 4/12/2021) that needs to be accounted for. The Facility Type in Column B is Spill or Release with the Facility ID and Location ID in columns E and F respectively.</p> <p>Chevron #402847273 to Scout #402890516</p> <p>· There is one Unaccounted For Facility (Location #314646 UNION PACIFIC #22-32 , Facility # 453683 Spill – AC 2-5-2021) that needs to be accounted for. The Facility Type in Column B is Spill or Release with the Facility ID and Location ID in columns E and F respectively.</p> <p>Chevron #402847276 to Scout #402890528</p> <p>· There is one Unaccounted For Spill or Release (Location #314763 (M B LARSON #C11 X 25 well P&amp;A 8/24/2021) location active open remediation , Facility # 481149 – SPILL satellite header 38 bulk line-AC 12/1/2021) that needs to be accounted for. The Facility Type in Column B is Spill or Release with the Facility ID and Location ID in columns E and F respectively.</p> <p>Chevron #402847277 to Scout #402891430</p> <p>There are two Unaccounted For Facilities that need to be accounted for as follows:            Location ID #314933 Facility ID #438685 Spill or Release            Location ID #314965 Facility ID #480932 Spill or Release</p> <p>The Facility Type in Column B is Spill or Release with the Facility ID and Location ID in columns E and F respectively.</p> <p>Chevron #402847282 to Scout #402891448</p> <p>There is one Unaccounted For Facility (Location #315324, Facility # 481858) that is a Spill and Release point that needs to be accounted for. The Facility Type in Column B is Spill or Release with the Facility ID and Location ID in columns E and F respectively.</p> <p>Chevron #402847287 to Scout #402891495</p> <p>There is one Unaccounted For Facility (Location #315740, Facility # 447266) that is a Spill and Release point that needs to be accounted for. The Facility Type in Column B is Spill or Release with the Facility ID and Location ID in columns E and F respectively.</p> <p>Chevron #402847293 to Scout #402891516</p>	02/08/2023

There is one Unaccounted For Facility (Location #316136, Facility # 446036) that is a Spill and Release point that needs to be accounted for. The Facility Type in Column B is Spill or Release with the Facility ID and Location ID in columns E and F respectively.

Chevron #402847328 to Scout #402891662

There are five Unaccounted For Facilities that need to be accounted for as follows:

- Location ID #413288 Facility ID #448925 Spill or Release
- Location ID #413288 Facility ID #457749 Spill or Release
- Location ID #426403 Facility ID #481872 Flowline System
- Location ID #426403 Facility ID #483023 Spill or Release
- Location ID #451320 Facility ID #451090 Spill or Release

The Facility Type in Column B is Spill or Release with the Facility ID and Location ID in columns E and F respectively. Instead of Location, Location ID 426403, Facility ID 481872 should have Flowline System as the Facility Type in Column B.

Assuming the other Form 9 requirements are met, all Form 9s shall now be passed with the following two COAs:

The Buying Operator must file a Form 3, Financial Assurance Plan within 10 business days of Form 9 approval. Per Rule 702, Buyer will then provide any required additional financial assurance as soon as practicable but no later than 90 days from the Commission's approval of the Form 3, Financial Assurance Plan.

The Selling Operator must file a Form 3, Financial Assurance Plan within 10 business days of Form 9 approval. Per Rule 702, Seller will then provide any required additional financial assurance as soon as practicable but no later than 90 days from the Commission's approval of the Form 3, Financial Assurance Plan.

Please note that each operator needs confirm that it will abide by the aforementioned COA by responding to this email. The correspondence will be uploaded to the form.

Please reach out with any questions.

Financial Assurance

I am reviewed the transfer again with the following issues noted below.

11/23/2022

Chevron #40284700 to Scout #402887795

· Buyer Notified Local Govt. Attestation – Please specify the individual contacted at Rio Blanco County and resubmit the attestation.

· There are two Unaccounted For Facilities that need to be accounted for as follows:

o Location ID #311804 Facility ID #444035 Spill or Release

o Location ID #314367 Facility ID #314367

If these facilities are to be transferred to Scout, then please add these facilities to the Wells and Facilities Transferred list.

If these facilities are to be retained by Chevron, then the facilities need to be added to a Wells Facilities – Not Transferred list. In addition to the list, a Seller retains responsibility Attestation must be submitted.

· There are 20 unaccounted for incidents related to this transfer. See Attached.

These corrective actions may or may not have been resolved. FIRs with outstanding corrective actions are transferable items that must be accounted for in the Form 9 in one or more of the following ways.

1. If the compliance responsibility for such an FIR transfers to the buyer include that FIR on a Related Incidents Transferred list.

2. If the compliance responsibility for such an FIR is retained by the seller include that FIR on a Related Incidents Not Transferred list and provide a Seller Retains Responsibility Attestation.

If the parties perform the research and determine that all corrective actions for a particular FIR have been resolved, that FIR does not need to be listed on the Form 9 but will be subject to Rule 218.d(1)D.iii.

Chevron #402847248 to Scout #402890468

· Buyer Notified Local Govt. Attestation – Please specify the individual contacted at Rio Blanco County and resubmit the attestation.

· There is one Unaccounted For Facility (Location #314373, Facility # 480349) that needs to be accounted for.

If these facilities are to be transferred to Scout, then please add these facilities to the Wells and Facilities Transferred list.

If these facilities are to be retained by Chevron, then the facilities need to be added to a Wells Facilities – Not Transferred list. In addition to the list, a Seller retains responsibility Attestation must be submitted.

· There are 19 unaccounted for incidents related to this transfer. See Attached.

These corrective actions may or may not have been resolved. FIRs with outstanding corrective actions are transferable items that must be accounted for in the Form 9 in one or more of the following ways.

If the compliance responsibility for such an FIR transfers to the buyer include that FIR on a Related Incidents Transferred list.

If the compliance responsibility for such an FIR is retained by the seller include that FIR on a Related Incidents Not Transferred list and provide a Seller Retains Responsibility Attestation.

If the parties perform the research and determine that all corrective actions for a particular FIR have been resolved, that FIR does not need to be listed on the Form 9 but will be subject to Rule 218.d(1)D.iii.

Chevron #402847259 to Scout #402890487

· Buyer Notified Local Govt. Attestation – Please specify the individual contacted at Rio Blanco County and resubmit the attestation.

· There are 25 unaccounted for incidents related to this transfer. See Attached.

These corrective actions may or may not have been resolved. FIRs with outstanding corrective actions are transferable items that must be accounted for in the Form 9 in one or more of the following ways.

If the compliance responsibility for such an FIR transfers to the buyer include that FIR on a Related Incidents Transferred list.

If the compliance responsibility for such an FIR is retained by the seller include that FIR on a Related Incidents Not Transferred list and provide a Seller Retains Responsibility Attestation.

If the parties perform the research and determine that all corrective actions for a particular FIR have been resolved, that FIR does not need to be listed on the Form 9 but will be subject to Rule 218.d(1)D.iii.

Chevron #402847267 to Scout #402890493

· Buyer Notified Local Govt. Attestation – Please specify the individual contacted at Rio Blanco County and resubmit the attestation.

· There is one Unaccounted For Facility (Location #314622, Facility # 448608) that needs to be accounted for.

If these facilities are to be transferred to Scout, then please add these facilities to the Wells and Facilities Transferred list.

If these facilities are to be retained by Chevron, then the facilities need to be added to a Wells Facilities – Not Transferred list. In addition to the list, a Seller retains responsibility Attestation must be submitted.

- There are 18 unaccounted for incidents related to this transfer. See Attached.

These corrective actions may or may not have been resolved. FIRs with outstanding corrective actions are transferable items that must be accounted for in the Form 9 in one or more of the following ways.

If the compliance responsibility for such an FIR transfers to the buyer include that FIR on a Related Incidents Transferred list.

If the compliance responsibility for such an FIR is retained by the seller include that FIR on a Related Incidents Not Transferred list and provide a Seller Retains Responsibility Attestation.

If the parties perform the research and determine that all corrective actions for a particular FIR have been resolved, that FIR does not need to be listed on the Form 9 but will be subject to Rule 218.d(1)D.iii.

Chevron #402847273 to Scout #402890516

- Buyer Notified Local Govt. Attestation – Please specify the individual contacted at Rio Blanco County and resubmit the attestation.

- There is one Unaccounted For Facility (Location #314646, Facility # 453683) that needs to be accounted for.

If these facilities are to be transferred to Scout, then please add these facilities to the Wells and Facilities Transferred list.

If these facilities are to be retained by Chevron, then the facilities need to be added to a Wells Facilities – Not Transferred list. In addition to the list, a Seller retains responsibility Attestation must be submitted.

- There are 21 unaccounted for incidents related to this transfer. See Attached.

These corrective actions may or may not have been resolved. FIRs with outstanding corrective actions are transferable items that must be accounted for in the Form 9 in one or more of the following ways.

If the compliance responsibility for such an FIR transfers to the buyer include that FIR on a Related Incidents Transferred list.

If the compliance responsibility for such an FIR is retained by the seller include that FIR on a Related Incidents Not Transferred list and provide a Seller Retains Responsibility Attestation.

If the parties perform the research and determine that all corrective actions for a particular FIR have been resolved, that FIR does not need to be listed on the Form 9 but will be subject to Rule 218.d(1)D.iii.

Chevron #402847276 to Scout #402890528

- Buyer Notified Local Govt. Attestation – Please specify the individual contacted at Rio Blanco County and resubmit the attestation.

- There is one Unaccounted For Facility (Location #314763, Facility # 481149) that needs to be accounted for.

If these facilities are to be transferred to Scout, then please add these facilities to the Wells and Facilities Transferred list.

If these facilities are to be retained by Chevron, then the facilities need to be added to a Wells Facilities – Not Transferred list. In addition to the list, a Seller retains responsibility Attestation must be submitted.

- There are 40 unaccounted for incidents related to this transfer. See Attached.

These corrective actions may or may not have been resolved. FIRs with outstanding corrective actions are transferable items that must be accounted for in the Form 9 in one or more of the following ways.

If the compliance responsibility for such an FIR transfers to the buyer include that FIR on a Related Incidents Transferred list.

If the compliance responsibility for such an FIR is retained by the seller include that FIR on a Related Incidents Not Transferred list and provide a Seller Retains Responsibility Attestation.

If the parties perform the research and determine that all corrective actions for a particular FIR have been resolved, that FIR does not need to be listed on the Form 9 but will be subject to Rule 218.d(1)D.iii.

Chevron #402847277 to Scout #402891430

- Buyer Notified Local Govt. Attestation – Please specify the individual contacted at Rio Blanco County and resubmit the attestation.

- There are two Unaccounted For Facilities that need to be accounted for as follows:

- o Location ID #314933 Facility ID #438685 Spill or Release

- o Location ID #314965 Facility ID #480932 Spill or Release

If these facilities are to be transferred to Scout, then please add these facilities to the Wells and Facilities Transferred list.

If these facilities are to be retained by Chevron, then the facilities need to be added to a Wells Facilities – Not Transferred list. In addition to the list, a Seller retains responsibility Attestation must be submitted.

- There are 26 unaccounted for incidents related to this transfer. See Attached.

These corrective actions may or may not have been resolved. FIRs with outstanding corrective actions are transferable items that must be accounted for in the Form 9 in one or more of the following ways.

If the compliance responsibility for such an FIR transfers to the buyer include that FIR on a Related Incidents Transferred list.

If the compliance responsibility for such an FIR is retained by the seller include that FIR on a Related Incidents Not Transferred list and provide a Seller Retains Responsibility Attestation.

If the parties perform the research and determine that all corrective actions for a particular FIR have been resolved, that FIR does not need to be listed on the Form 9 but will be subject to Rule 218.d(1)D.iii.

Chevron #402847282 to Scout #402891448

- Buyer Notified Local Govt. Attestation – Please specify the individual contacted at Rio Blanco County and resubmit the attestation.

- There is one Unaccounted For Facility (Location #315324, Facility # 481858) that needs to be accounted for.

If these facilities are to be transferred to Scout, then please add these facilities to the Wells and Facilities Transferred list.

If these facilities are to be retained by Chevron, then the facilities need to be added to a Wells Facilities – Not Transferred list. In addition to the list, a Seller retains responsibility Attestation must be submitted.

· There are 29 unaccounted for incidents related to this transfer. See Attached.

These corrective actions may or may not have been resolved. FIRs with outstanding corrective actions are transferable items that must be accounted for in the Form 9 in one or more of the following ways.

If the compliance responsibility for such an FIR transfers to the buyer include that FIR on a Related Incidents Transferred list.

If the compliance responsibility for such an FIR is retained by the seller include that FIR on a Related Incidents Not Transferred list and provide a Seller Retains Responsibility Attestation.

If the parties perform the research and determine that all corrective actions for a particular FIR have been resolved, that FIR does not need to be listed on the Form 9 but will be subject to Rule 218.d(1)D.iii.

Chevron #402847287 to Scout #402891495

· Buyer Notified Local Govt. Attestation – Please specify the individual contacted at Rio Blanco County and resubmit the attestation.

· There is one Unaccounted For Facility (Location #315740, Facility # 447266) that needs to be accounted for.

If these facilities are to be transferred to Scout, then please add these facilities to the Wells and Facilities Transferred list.

If these facilities are to be retained by Chevron, then the facilities need to be added to a Wells Facilities – Not Transferred list. In addition to the list, a Seller retains responsibility Attestation must be submitted.

· There are 25 unaccounted for incidents related to this transfer. See Attached.

These corrective actions may or may not have been resolved. FIRs with outstanding corrective actions are transferable items that must be accounted for in the Form 9 in one or more of the following ways.

If the compliance responsibility for such an FIR transfers to the buyer include that FIR on a Related Incidents Transferred list.

If the compliance responsibility for such an FIR is retained by the seller include that FIR on a Related Incidents Not Transferred list and provide a Seller Retains Responsibility Attestation.

If the parties perform the research and determine that all corrective actions for a particular FIR have been resolved, that FIR does not need to be listed on the Form 9 but will be subject to Rule 218.d(1)D.iii.

Chevron #402847293 to Scout #402891516

· Buyer Notified Local Govt. Attestation – Please specify the individual contacted at Rio Blanco County and resubmit the attestation.

· There is one Unaccounted For Facility (Location #316136, Facility # 446036) that needs to be accounted for.

If these facilities are to be transferred to Scout, then please add these facilities to the Wells and Facilities Transferred list.

If these facilities are to be retained by Chevron, then the facilities need to be added to a Wells Facilities – Not Transferred list. In addition to the list, a Seller retains responsibility Attestation must be submitted.

· There are 28 unaccounted for incidents related to this transfer. See Attached.

These corrective actions may or may not have been resolved. FIRs with outstanding corrective actions are transferable items that must be accounted for in the Form 9 in one or more of the following ways.

If the compliance responsibility for such an FIR transfers to the buyer include that FIR on a Related Incidents Transferred list.

If the compliance responsibility for such an FIR is retained by the seller include that FIR on a Related Incidents Not Transferred list and provide a Seller Retains Responsibility Attestation.

If the parties perform the research and determine that all corrective actions for a particular FIR have been resolved, that FIR does not need to be listed on the Form 9 but will be subject to Rule 218.d(1)D.iii.

Chevron #402847295 to Scout #402891587

· Buyer Notified Local Govt. Attestation – Please specify the individual contacted at Rio Blanco County and resubmit the attestation.

· There are 26 unaccounted for incidents related to this transfer. See Attached.

These corrective actions may or may not have been resolved. FIRs with outstanding corrective actions are transferable items that must be accounted for in the Form 9 in one or more of the following ways.

If the compliance responsibility for such an FIR transfers to the buyer include that FIR on a Related Incidents Transferred list.

If the compliance responsibility for such an FIR is retained by the seller include that FIR on a Related Incidents Not Transferred list and provide a Seller Retains Responsibility Attestation.

If the parties perform the research and determine that all corrective actions for a particular FIR have been resolved, that FIR does not need to be listed on the Form 9 but will be subject to Rule 218.d(1)D.iii.

Chevron #402847312 to Scout #402891604

· Buyer Notified Local Govt. Attestation – Please specify the individual contacted at Rio Blanco County and resubmit the attestation.

· There are 6 unaccounted for incidents related to this transfer. See Attached.

These corrective actions may or may not have been resolved. FIRs with outstanding corrective actions are transferable items that must be accounted for in the Form 9 in one or more of the following ways.

If the compliance responsibility for such an FIR transfers to the buyer include that FIR on a Related Incidents Transferred list.

If the compliance responsibility for such an FIR is retained by the seller include that FIR on a Related Incidents Not Transferred list and provide a Seller Retains Responsibility Attestation.

If the parties perform the research and determine that all corrective actions for a particular FIR have been resolved, that FIR does not need to be listed on the Form 9 but will be subject to Rule 218.d(1)D.iii.

Chevron #402847322 to Scout #402891631

· Buyer Notified Local Govt. Attestation – Please specify the individual contacted at Rio Blanco County and resubmit the attestation.

· There are 7 unaccounted for incidents related to this transfer. See Attached.

These corrective actions may or may not have been resolved. FIRs with outstanding corrective actions are transferable items that must be accounted for in the Form 9 in one or more of the following ways.

If the compliance responsibility for such an FIR transfers to the buyer include that FIR on a Related Incidents Transferred list.

If the compliance responsibility for such an FIR is retained by the seller include that FIR on a Related Incidents Not Transferred list and provide a Seller Retains Responsibility Attestation.

If the parties perform the research and determine that all corrective actions for a particular FIR have been resolved, that FIR does not need to be listed on the Form 9 but will be subject to Rule 218.d(1)D.iii.

Chevron #402847328 to Scout #402891662

· Buyer Notified Local Govt. Attestation – Please specify the individual contacted at Rio Blanco County and resubmit the attestation.

· There are five Unaccounted For Facilities that need to be accounted for as follows:

o Location ID #413288 Facility ID #448925 Spill or Release

o Location ID #413288 Facility ID #457749 Spill or Release

o Location ID #426403 Facility ID #481872 Flowline System

o Location ID #426403 Facility ID #483023 Spill or Release

o Location ID #451320 Facility ID #451090 Spill or Release

If these facilities are to be transferred to Scout, then please add these facilities to the Wells and Facilities Transferred list.

If these facilities are to be retained by Chevron, then the facilities need to be added to a Wells Facilities – Not Transferred list. In addition to the list, a Seller retains responsibility Attestation must be submitted.

· There are 19 unaccounted for incidents related to this transfer. See Attached.

These corrective actions may or may not have been resolved. FIRs with outstanding corrective actions are transferable items that must be accounted for in the Form 9 in one or more of the following ways.

If the compliance responsibility for such an FIR transfers to the buyer include that FIR on a Related Incidents Transferred list.

If the compliance responsibility for such an FIR is retained by the seller include that FIR on a Related Incidents Not Transferred list and provide a Seller Retains Responsibility Attestation.

If the parties perform the research and determine that all corrective actions for a particular FIR have been resolved, that FIR does not need to be listed on the Form 9 but will be subject to Rule 218.d(1)D.iii.

Chevron #402847336 to Scout #402891690

· Buyer Notified Local Govt. Attestation – Please specify the individual contacted at Rio Blanco County and resubmit the attestation.

Chevron #402847928 to Scout #402891710

· Buyer Notified Local Govt. Attestation – Please specify the individual contacted at Rio Blanco County and resubmit the attestation.

Chevron #402847952 to Scout #402891752

· Buyer Notified Local Govt. Attestation – Please specify the individual contacted at Rio Blanco County and resubmit the attestation.

Assuming the other Form 9 requirements are met, all Form 9s shall now be passed with the following two COAs:

The Buying Operator must file a Form 3, Financial Assurance Plan within 10 business days of Form 9 approval. Per Rule 702, Buyer will then provide any required additional financial assurance as soon as practicable but no later than 90 days from the Commission’s approval of the Form 3, Financial Assurance Plan.

The Selling Operator must file a Form 3, Financial Assurance Plan within 10 business days of Form 9 approval. Per Rule 702, Seller will then provide any required additional financial assurance as soon as practicable but no later than 90 days from the Commission’s approval of the Form 3, Financial Assurance Plan.

Please note that each operator needs confirm that it will abide by the aforementioned COA by responding to this email. The correspondence will be uploaded to the form.

If the operators have submitted a Form 3, please provide the following comment when submitting the revised Form 3.

Form 3 Document #\_\_\_\_ is submitted as a result of an approved Form 9 Transfer of Operatorship and it replaces Form 3 document # \_\_\_\_\_.

Please reach out with any questions.

Thanks,

Deb

Financial Assurance

I have reviewed all 17 pairs of Intent and Subsequent documents involved in your transfer. I have noted below some issues that will need to be resolved before we can approve the transfer.

04/01/2022

Problem 1: For the following 15 Subsequent documents (402887795, 402890468, 402890487, 402890493, 402890516, 402890528, 402891430, 402891448, 402891495, 402891516, 402891587, 402891604, 402891631, 402891662 and 402891690), the Wells and Facilities Transferred spreadsheets listed the current operator as Scout Energy Management LLC. This is incorrect since the transfer has not been approved.

Solution 1: Please resubmit all 15 of the Wells and Facilities Transferred spreadsheets listing the current operator reflected in COGIS.

Problem 2: For the last two Subsequent documents (402891710 and 402891752), the Incidents Transferred spreadsheets listed the current operator as Scout Energy Management LLC. This is incorrect since the transfer has not been approved.

Solution 2: Please resubmit both of the Incidents Transferred spreadsheets for subsequent document #402891710 and #402891751 listing the current operator reflected in COGIS.

Problem 3: There are Related Wells and Facilities that are not accounted for in the transfer.

Solution 3: I have attached a workbook that lists the Related Wells and Facilities that are not accounted for. In order for the transfer to be approved, the Related Wells and Facilities must be accounted for by one or a combination of the following options:

Solution 3a: Add the well and location to the Wells and Facilities Transferred list in the Subsequent.

Solution 3b: Generate and submit a Related Wells and Facilities – Not Transferred List. If

not transferring the wells and facilities, the COGCC will also require a Seller Retains Responsibility Attestation. Guidance for this attestation can also be found in the attachment.

Problem 4: In the same workbook as referenced in Problem 3, there is a list of Related Incidents that are not accounted for. Most of these incidents are Unresolved Field Inspections with Corrective Actions. These corrective actions may or may not have been resolved. FIRs with outstanding corrective actions are transferable items that must be accounted for in the Form 9 in one or both of the following ways.

Solution 4a: If the compliance responsibility for such an FIR transfers to the buyer include that FIR on a Related Incidents Transferred list.

Solution 4b: If the compliance responsibility for such an FIR is retained by the seller include that FIR on a Related Incidents Not Transferred list and provide a Seller Retains Responsibility Attestation.

If the parties perform the research and determine that all corrective actions for a particular FIR have been resolved, that FIR does not need to be listed on the Form 9 but will be subject to Rule 218.d(1)D.iii.

For both Problems 3 and 4 the lists include Unresolved Spill/Release. If the Spill/Release is closed, the COGCC does not require that the Spill/Release be transferred. It is up to the operators to determine whether or not they should be transferred. All revised and new documents can be emailed to me and I will upload them to Subsequent #402891752.

Please reach out with any questions.

Total: 4 comment(s)