

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

403382365

Date Received:

04/24/2023

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed  
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10177

Name of Operator: ENERPLUS RESOURCES (USA) CORPORATION

Address: 950 17TH STREET #2200

City: DENVER State: CO Zip: 80202

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_

Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name

Phone

Email

reed.wold@state.co.us

jeverhart@enerplus.com

SGibbs@enerplus.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 697504490

Inspection Date: 01/17/2023

FIR Submit Date: 01/24/2023

FIR Status: \_\_\_\_\_

Inspected Operator Information:

Company Name: ENERPLUS RESOURCES (USA) CORPORATION

Company Number: 10177

Address: 950 17TH STREET #2200

City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 450827

Location Name: IRISH PAD Number: N/A County: \_\_\_\_\_

Qtrqr: SWSE Sec: 26 Twp: 8N Range: 67W Meridian: 6

Latitude: 40.626117 Longitude: -104.858296

FACILITY - API Number: 05-123-00 Facility ID: 450827

Facility Name: IRISH PAD Number: N/A

Qtrqr: SWSE Sec: 26 Twp: 8N Range: 67W Meridian: 6

Latitude: 40.626117 Longitude: -104.858296

CORRECTIVE ACTIONS:

1 ☒ CA# 167143

Corrective Action: Comply with Rule 606 to remove weed debris.

Date: 01/17/2023

The corrective date is the date the location was observed out of compliance, as it should be in compliance at all times.

Response: CA COMPLETED

Date of Completion: 04/01/2023

weeds and debris removed 1-2 after inspection findings

Operator  
Comment:

COGCC Decision: Approved pending re-inspection

COGCC Representative: Approved pending re-inspection of this FIR resolution acknowledges the document was received. It is not an acknowledgement that the corrective action has been passed. A field inspection will be conducted at a future date to evaluate compliance with COGCC standards.

2 ☒ CA# 167144

Corrective Action: Best management practices to prevent weed establishment shall be implemented. Control, manage, and prevent weedy, annual vegetation on all topsoil stockpiles. If reseeded is an option for long-term protection and stabilization of topsoil, then the next favorable seeding opportunity shall be conducted.

Comply with Rule 1002.c. to prohibit vehicle traffic on the topsoil stockpile.

The corrective date is the date the location was observed out of compliance, as it should be in compliance at all times.

Date: 01/17/2023

Response: CA COMPLETED

Date of Completion: 04/01/2023

Operator  
Comment:

Reseeding performed on 4/1/23 to establish long term soil protection and stabilization

COGCC Decision: Approved pending re-inspection

COGCC Representative: Approved pending re-inspection of this FIR resolution acknowledges the document was received. It is not an acknowledgement that the corrective action has been passed. A field inspection will be conducted at a future date to evaluate compliance with COGCC standards.

#### OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Jacob Everhart

Signed: \_\_\_\_\_

Title: Regulatory Advisor

Date: 4/24/2023 1:35:38 PM

### ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

403382365	FIR RESOLUTION SUBMITTED
-----------	--------------------------

Total Attach: 1 Files