

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
403382385

Date Received:
04/24/2023

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10177

Name of Operator: ENERPLUS RESOURCES (USA) CORPORATION

Address: 950 17TH STREET #2200

City: DENVER State: CO Zip: 80202

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

SGibbs@enerplus.com

reed.wold@state.co.us

jeverhart@enerplus.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 697504488

Inspection Date: 01/17/2023

FIR Submit Date: 01/23/2023

FIR Status: _____

Inspected Operator Information:

Company Name: ENERPLUS RESOURCES (USA) CORPORATION

Company Number: 10177

Address: 950 17TH STREET #2200

City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 461838

Location Name: Colorado Rivers Pad Number: _____ County: _____

Qtrqr: NWN Sec: 33 Twp: 8N Range: 67W Meridian: 6

W

Latitude: 40.624170 Longitude: -104.903650

FACILITY - API Number: 05-123- -00 Facility ID: 461838

Facility Name: Colorado Rivers Pad Number: _____

Qtrqr: NWN Sec: 33 Twp: 8N Range: 67W Meridian: 6

W

Latitude: 40.624170 Longitude: -104.903650

CORRECTIVE ACTIONS:

1 ☒ CA# 167123

Corrective Action: Best management practices to prevent weed establishment shall be implemented. Control, manage, and prevent weedy, annual vegetation on all topsoil stockpiles. If reseeding is an option for long-term protection and stabilization of topsoil, then the next favorable seeding opportunity shall be conducted.

Date: 01/17/2023

The corrective date is the date the location was observed out of compliance.

Response: CA COMPLETED

Date of Completion: 04/01/2023

Operator Comment: weed debris cleaned up within 1-2 days of inspection finding

COGCC Decision: Approved pending re-inspection

COGCC Representative: Approved pending re-inspection of this FIR resolution acknowledges the document was received. It is not an acknowledgement that the corrective action has been passed. A field inspection will be conducted at a future date to evaluate compliance with COGCC standards.

2 ☒ CA# 167124

Corrective Action: Comply with Rule 1003. Reseed disturbance areas using a seed mixture requested by the surface owner, or a mixture prescribed by the local county NRCS. The corrective date is the date the location was observed out of compliance. Operator shall complete the corrective action as soon as environmental conditions will permit.

Date: 01/17/2023

Response: CA COMPLETED

Date of Completion: 04/01/2023

Operator Comment: Reseeding performed on 4/1/23 to establish long term soil protection and stabilization

COGCC Decision: Approved pending re-inspection

COGCC Representative: Approved pending re-inspection of this FIR resolution acknowledges the document was received. It is not an acknowledgement that the corrective action has been passed. A field inspection will be conducted at a future date to evaluate compliance with COGCC standards.

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: jacob everhart

Signed: _____

Title: regulatory advisor

Date: 4/24/2023 1:41:16 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

403382385	FIR RESOLUTION SUBMITTED
-----------	--------------------------

Total Attach: 1 Files