

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/01/2023

Submitted Date:

05/01/2023

Document Number:

699106670

**FIELD INSPECTION FORM**Loc ID 327801 Inspector Name: Burns, Adam On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 100322

Name of Operator: NOBLE ENERGY INC

Address: 2001 16TH STREET SUITE 900

City: DENVER State: CO Zip: 80202

**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

7 Number of Comments

2 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Silver, Randy		randy.silver@state.co.us	
Serna, Abe		abe.serna@state.co.us	
,		rbucogccinspectionreports@c hevron.onmicrosoft.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
247369	WELL	PR	04/04/2023	GW	123-15166	HSR-GARDNER 3-31A	TA

**General Comment:**[This is a inspection to the Subsequent Accident Report Form 22#403387780](#)

**Location**Overall Good: ☒

<b>Signs/Marker:</b>			
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: Adequate

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type	OTHER		
Comment:	Oily Waste appears to be around ECD needs to be removed for good housekeeping. See attached photo. Submit Photos with FIRR		
Corrective Action:	"Properly dispose of oily waste in accordance with 905.e."		Date: 05/22/2023

Overall Good: ☐

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?

<b>Equipment:</b>			corrective date
Type: Other	#		
Comment:	Equipment appears to need to be replaced or fixed for operation purposes. See attached photo. Submit Photos with FIRR		
Corrective Action:	Securely fasten all valves, pipes, fittings, and Production Facilities to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 608.e.		Date: 05/22/2023

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**Facility ID: 247369 Type: WELL API Number: 123-15166 Status: PR Insp. Status: TA**Idle Well**Purpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: \_\_\_\_\_Comment: T/A

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**BradenHead**Date of Last Brhd Test: 03/03/2023 Annual Brhd Completed? YesLast Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: NONEEnd Surf Csg Pressure: 0

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary</p> <p>On Monday 5/1/23 at approximately 1002hrs I, Inspector Adam Burns, Conducted an on-site inspection to the Subsequent Accident Report #403387780 at HSR-Gardner-64N65W 31NENW of Chevron</p> <p>Location ID #327801 in Weld County, Colorado.</p> <p>While there, I was observing the detailed description of the accident that Chevron submitted in the Form 22.</p> <p>During this inspection the following possible compliance issues were observed:</p> <p>Equipment appears to need to be replaced or fixed for operation purposes. Securely fasten all valves, pipes, fittings, and Production Facilities to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 608.e. With a Corrective Action date of 5/22/23</p> <p>Oily Waste appears to be around ECD needs to be removed for good housekeeping.</p> <p>"Properly dispose of oily waste in accordance with 905.e." With a Corrective Action date of 5/22/23</p> <p>Submit Photos with FIRR.</p> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.</p> <p>This is a summary of the inspection report.</p>	burnsa	05/01/2023

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699106671	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6099239">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6099239</a>