

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/25/2023

Submitted Date:

04/26/2023

Document Number:

697602066

FIELD INSPECTION FORMLoc ID 320179 Inspector Name: Ahmadian, Alexander On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 10651

Name of Operator: VERDAD RESOURCES LLC

Address: 1125 17TH STREET SUITE 550

City: DENVER State: CO Zip: 80202

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

5 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		Regulatory@verdadoil.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
202922	WELL	PA	05/12/2022	GW	001-08327	GREEN 1	EI
484200	SPILL OR RELEASE	AC	04/14/2023		-	Green 1	EI

General Comment:

This is an Environmental inspection. Any corrective actions from previous inspections or forms that have not been addressed are still applicable. There were no operator or contract environmental personnel on location at the time of this field inspection. Photos are attached to document site conditions.

Historic spill discovered during facility decommissioning. Well is P&A'd, all equipment off site. Large excavation has begun to address the historical spill.

LocationOverall Good: ☒

Emergency Contact Number:

Comment: None

Corrective Action:

Date: _____

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type	OTHER		
Comment:	Orange construction fencing has fallen all around the excavation.		
Corrective Action:	Fencing is not in compliance. The operator is to maintain best management practices to control and contain all spills/releases of E&P waste to protect the environment, public health, safety and welfare and the environment as required by rule 913.b(5)B.i which requires that Operators will fence or cover open remediation excavations to prevent access when sites are not attended.	Date:	05/03/2023

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities				
Facility ID: 202922	Type: WELL	API Number: 001-08327	Status: PA	Insp. Status: EI
Facility ID: 484200	Type: SPILL OR	API Number: -	Status: AC	Insp. Status: EI

Environmental**Waste Management:**

Type	Management	Condition	GPS (Lat)	(Long)
Oily Soil				
Comment:	Large impacted soil stockpile is onsite and has been bermed with soil. No liner under the stockpile has been observed.			
Corrective Action:				Date:

Spill/Remediation:

Comment:	Large excavation to address the spill is underway. Groundwater was observed at about 6 feet. No sheen was seen on the groundwater.			
Corrective Action:				Date:

Emission Control Burner (ECB):

Comment:

Pilot: Wildlife Protection Devices (fired vessels):

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403385873	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6094783
697602067	Photolog	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6094755