

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/26/2023

Submitted Date:

04/26/2023

Document Number:

702501199**FIELD INSPECTION FORM**Loc ID 314993 Inspector Name: Burchett, Kirby On-Site Inspection ☐ 2A Doc Num: ☐**Operator Information:**

OGCC Operator Number: 16700

Name of Operator: CHEVRON USA INC

Address: 760 HORIZON DRIVE STE 401

City: GRAND JUNCTION State: CO Zip: 81506

**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

7 Number of Comments

1 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Sanford, Anita	(970) 551-8313	Anita.Sanford@scoutep.com	
Patterson, Chris		Chris.Patterson@scoutep.com	
Regulatory, Rangely		RangelyRegulatory@scoutep.com	
Kellerby, Shaun	(970) 712-1248	shaun.kellerby@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
230056	WELL	PR	02/01/2022	OW	103-07715	A C MCLAUGHLIN 62X	PR

**General Comment:****COGCC Inspection Report Summary**

On Wednesday, 4/26/2023, Inspector Kirby Burchett, conducted a follow up field inspection at Scout Energy Management LLC on the A C McLaughlin 62X well, Location #314993, in Rio Blanco County, Colorado.

This location is within or in close proximity to a Parks and Wildlife (CPW) District with High Priority/Density Habitats.

Any Corrective Actions from previous Inspections are still applicable.

Follow up inspection in response to FIRR #403375445 submitted by Operator for Corrective Action from Inspection #702501088 on 4/5/23.

While there during normal production operations the following compliance issue was observed:

1. Blading of location and access roads does not address Stormwater BMPs needing to be implemented and maintained to control potential sediment discharges from operational roads, well pads, and other unpaved surfaces.
- Refer to Inspection Photos for observed compliance issues.

A follow up on this site inspection will be conducted to ensure all compliance issues have been corrected to comply with COGCC rules.

**Location**Overall Good: ☐**Signs/Marker:**

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 911 / (970) 675-3700

Corrective Action:

Date: \_\_\_\_\_

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

			corrective date
Type: Submersible Pump	# 1		
Comment:	Submersible pump		
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	Accessible with valve		
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Chemical tank on containment		
Corrective Action:		Date:	
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:		Date:	

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	230056	Type:	WELL	API Number:	103-07715	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Submersible pump								
Corrective Action:						Date:			

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
				Material Handling And Spill Prevention		
		Ditches				
Berms						
Ditches						
		Culverts				

Comment: Insufficient BMPs to prevent vehicle tracking and the control of potential sediment discharges from operational roads, well pads, and other unpaved surfaces.

Corrective Action: Provide proper BMPs to prevent vehicle tracking and to control sediment migration from location and lease road.

Date: 05/26/2023

**Pits:** ☒ NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403386029	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6094922">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6094922</a>
702501201	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6094914">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6094914</a>