

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

403377244

Date Received:

04/19/2023

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

2 of 3 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 16700

Name of Operator: CHEVRON USA INC

Address: 760 HORIZON DRIVE STE 401

City: GRAND JUNCTION State: CO Zip: 81506

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
<u>Sanford, Anita</u>	<u>(970) 551-8313</u>	<u>Anita.Sanford@scoutep.com</u>
<u>Kellerby, Shaun</u>	<u>(970) 712-1248</u>	<u>shaun.kellerby@state.co.us</u>
<u>Patterson, Chris</u>		<u>Chris.Patterson@scoutep.com</u>
<u>Regulatory, Rangely</u>		<u>RangelyRegulatory@scoutep.com</u>

COGCC INSPECTION SUMMARY:

FIR Document Number: 702501094

Inspection Date: 04/06/2023

FIR Submit Date: 04/06/2023

FIR Status: _____

Inspected Operator Information:

Company Name: CHEVRON USA INC

Company Number: 16700

Address: 760 HORIZON DRIVE STE 401

City: GRAND JUNCTION State: CO Zip: 81506

LOCATION - Location ID: 311854

Location Name: A.C.MCLAUGHLIN-62N103W Number: 11SESW County: RIO BLANCO

Qtrqr: SESW Sec: 11 Twp: 2N Range: 103W Meridian: 6

Latitude: 40.152429 Longitude: -108.926356

FACILITY - API Number: 05-103-00 Facility ID: 288281

Facility Name: A.C.MCLAUGHLIN Number: 44A

Qtrqr: SESW Sec: 11 Twp: 2N Range: 103W Meridian: 6

Latitude: 40.152429 Longitude: -108.926356

CORRECTIVE ACTIONS:

2 ☒ CA# 169131

Corrective Action: All guy line anchors left buried for future use will be identified by a marker of bright color not less than 4 feet in height and not greater than 1 foot east of the guy line anchor.

Date: 04/28/2023

Response: CA COMPLETED

Date of Completion: 04/18/2023

Operator
Comment: Guy line anchors marked. See attached pictures.

COGCC Decision: Approved pending re-inspection

COGCC
Representative:

3 ☒ CA# 169132

Corrective Action: Provide proper BMPs to prevent sediment migration from location and lease road.

Date: 04/24/2023

Response: CA COMPLETED

Date of Completion: 04/18/2023

Operator
Comment: Location and lease road have been repaired. Refer to attached pictures.

COGCC Decision: Approved pending re-inspection

COGCC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Anita Sanford

Signed: _____

Title: Regulatory Analyst

Date: 4/19/2023 6:32:14 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
403377244	FIR RESOLUTION SUBMITTED
403377246	Pictures

Total Attach: 2 Files