

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/03/2023

Submitted Date:

05/03/2023

Document Number:

702501256

FIELD INSPECTION FORM

Loc ID 311854 Inspector Name: Burchett, Kirby On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 16700
Name of Operator: CHEVRON USA INC
Address: 760 HORIZON DRIVE STE 401
City: GRAND JUNCTION State: CO Zip: 81506

Findings:

- 6 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Sanford, Anita	(970) 551-8313	Anita.Sanford@scoutep.com	
Regulatory, Rangely		RangelyRegulatory@scoutep.com	
Johnson, Mike		Mike.Johnson@scoutep.com	
Kellerby, Shaun	(970) 712-1248	shaun.kellerby@state.co.us	
Patterson, Chris		Chris.Patterson@scoutep.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
288281	WELL	PR	12/01/2021	OW	103-10961	A.C.MCLAUGHLIN 44A	PR

General Comment:

[COGCC Inspection Report Summary](#)

On Wednesday, 05/03/2023, Inspector Kirby Burchett, conducted a follow up field inspection at Scout Energy Management LLC on the A.C. McLaughlin 44A well, Location #311854, in Rio Blanco County, Colorado. This location is within or in close proximity to a Parks and Wildlife (CPW) District with High Priority/NSO/Density Habitat regulations.

Any Corrective Actions from previous Inspections are still applicable. Follow up inspection in response to FIRRs #403377244, #403377403 & #403377579 submitted by Operator for Corrective Actions from Inspection #702501094 on 4/6/23.

While there during normal production operations the following compliance issue was observed:
1. Insufficient BMPs to control vehicle tracking.
Refer to Inspection Photos for observed compliance issues.

A follow up on this site inspection will be conducted to ensure all compliance issues have been corrected to comply with COGCC rules.

Location

Overall Good:

Signs/Marker:

Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date:

Overall Good:

Spills:

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

Type			corrective date
Type: Bradenhead	# 1		
Comment:	Valve is accessible. Gauge installed.		
Corrective Action:		Date:	
Type: Deadman # & Marked	# 1		
Comment:			
Corrective Action:		Date:	
Type: Submersible Pump	# 1		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 3		
Comment:	Chemical tanks on containments		
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 288281 Type: WELL API Number: 103-10961 Status: PR Insp. Status: PR

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment:

Corrective Action: Date: _____

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
				Material Handling And Spill Prevention		
		Ditches				
Berms						
		Gravel				

Comment: Insufficient BMPs to control vehicle tracking.

Corrective Action: Provide proper Stormwater BMPs for vehicle tracking to control potential sediment discharges from operational roads, well pads, and other unpaved surfaces.

Date: 06/03/2023

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
702501258	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6103595