

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/02/2023

Submitted Date:

05/05/2023

Document Number:

708300372

FIELD INSPECTION FORMLoc ID 324233 Inspector Name: Morris, Matthew On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 10456

Name of Operator: CAERUS PICEANCE LLC

Address: 1001 17TH STREET #1600

City: DENVER State: CO Zip: 80202

Status Summary:☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

14 Number of Comments

2 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, CAERUS		COGCC.inspections@caerus oilandgas.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
268056	WELL	SI	02/01/2023	GW	045-09241	GASAWAY 6233	PR

General Comment:**COGCC Inspection Report Summary**

On 5/2/2023 at approximately 12:10, Compliance Inspector Matthew Morris conducted an on-site inspection at CAERUS PICEANCE LLC, GASAWAY66S99W/20NESE at Location ID #324233 in Garfield County, Colorado.

Normal production operations were observed.

During the inspection, the following compliance issues were observed:

- 1) Unused equipment stored on location
- 2) Stormwater; refer to Stormwater section

A follow-up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

This location is within or in close proximity to, a CPW Density/High Priority Habitat, Black Bear, NSO Habitat, and/or Wildlife Management area.

LocationOverall Good: ☐**Signs/Marker:**

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	OTHER		
Comment:	Separator units include attached storage tanks. The sight glass on the side of the unit indicates the storage tank contains an unknown fluid. No form of labeling or markers is present to identify a potential hazard or the contents of the storage tank.		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 911/(970) 285-2615

Corrective Action:

Date: _____

Good Housekeeping:

Type	STORAGE OF SUPL		
Comment:	Unused equipment stored on location; refer to Photo Log		
Corrective Action:	Remove unused equipment from location to comply with Rule 606	Date:	05/12/2023

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type	LOCATION		
Comment:	Barbed wire fencing at location entrance		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Pipe rail fencing		
Corrective Action:		Date:	

Equipment:

Type: Horizontal Heated Separator	# 1		corrective date
Comment:			

Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 1		
Comment:	Well on plunger lift		
Corrective Action:		Date:	
Type: Bird Protectors	# 3		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	No form of pressure monitoring equipment located on Bradenheads. All Bradenhead valves are accessible.		
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
METHANOL	1	<50 BBLs	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	2	300 BBLs	HEATED STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance

Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate	
Comment:	Centralized containment				
Corrective Action:				Date:	

Venting:					
Yes/No	NO				
Comment:					
Corrective Action:				Date:	

Flaring:					
Type					
Comment:					
Corrective Action:				Date:	

Inspected Facilities									
Facility ID:	268056	Type:	WELL	API Number:	045-09241	Status:	SI	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:				Date:					

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Seeding						
Compaction	Fail					Location lacks stabilization
		Other	Fail			Insufficient vehicle tracking BMPs
Berms						
Other	Fail					Insufficient vehicle tracking BMPs

Comment: 1) Location lacks stabilization in muddy conditions with insufficient vehicle tracking BMPs in place to minimize transportation of sediment
 2) Insufficient vehicle tracking BMPs in place at location entrance to minimize transportation of sediment

Corrective Action: Oil and gas operators shall implement and maintain Best Management Practices (BMPs) at all oil and gas locations to comply with Rule 1002

Date: 05/20/2023

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
708300373	Photo Log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6105428