

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

403395726

Date Received:

05/05/2023

FIR RESOLUTION FORM

Overall Status:

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10518

Name of Operator: CONFLUENCE DJ LLC

Address: 1125 17TH STREET #1550

City: DENVER State: CO Zip: 80202

Contact Name and Telephone:

Name: _____

Phone: () Fax: ()

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

ROTHE, BRITTANY

(303) 226-9519

taylor.hukari@state.co.us

brothe@confluencelp.com

shannon.kime@state.co.us

Wold, Reed

reed.wold@state.co.us

COGCC INSPECTION SUMMARY:

FIR Document Number: 697504563

Inspection Date: 03/09/2023

FIR Submit Date: 03/15/2023

FIR Status: _____

Inspected Operator Information:

Company Name: CONFLUENCE DJ LLC

Company Number: 10518

Address: 1125 17TH STREET #1550

City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 458676

Location Name: Silverton Number: 4 North County: _____

Qtrqr: SWN Sec: 4 Twp: 4N Range: 63W Meridian: 6
W

Latitude: 40.341730 Longitude: -104.451510

FACILITY - API Number: 05-123-00 Facility ID: 458676

Facility Name: Silverton Number: 4 North

Qtrqr: SWN Sec: 4 Twp: 4N Range: 63W Meridian: 6
W

Latitude: 40.341730 Longitude: -104.451510

CORRECTIVE ACTIONS:

1 CA# 168158

Corrective Action:

Date: 05/01/2023

Comply with Rule 606.c. to keep the location free of all undesirable plant species. Note- it is COGCC's expectation that some of these areas will be reseeded with perennial vegetation that would out compete the weeds and it also serves to stabilize the soils. Since reseeding is a potential option, COGCC is allowing for favorable environmental conditions to reseed but it shall be completed as soon as possible but no later than May 1, 2023.

Response: CA COMPLETED

Date of Completion: 04/29/2023

Operator Comment: The Silverton 4 North location was interim reclaimed from 4/10 - 4/28/2023. While performing interim reclamation, the entire perimeter of the location, including the topsoil pile, was mowed, reseeded, and crimped with straw. The attached pictures taken 4/29/2023 detail this work.

COGCC Decision: _____

COGCC Representative: _____

OPERATOR COMMENT AND SUBMITTAL

Comment: Thank you! Please let me know if there are any questions.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Brittany Rothe

Signed: _____

Title: Engineering Manager

Date: 5/5/2023 4:01:22 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

Document Number	Description
403395735	On Topsoil Pile Looking N
403395736	On Topsoil Pile Looking NE
403395737	SW Corner Looking to NW Corner
403395741	SW-Side Looking NW
403395745	NW-Side Looking E
403395746	NW-Side Looking NE
403395747	NW Side Looking @ NW Corner
403395749	NW Corner Looking S
403395750	NW Corner Looking SE
403395751	NW Corner Looking NE
403395752	NW Corner Looking E
403395753	NW Corner Looking E #2
403395755	North-Center Looking E
403395756	NE Corner Looking NE
403395757	NE Corner Looking W
403395758	NE Corner Looking SW
403395759	NE Corner Looking S
403395760	NE Looking S fm Access Rd
403395761	Access Rd Entrance Looking NE
403395762	S Tip Looking to NE Corner
403395763	S Tip Looking N to Topsoil Pile

Total Attach: 21 Files