



Location			
Overall Good: <input checked="" type="checkbox"/>			
<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:			Date:
Emergency Contact Number:			
Comment:	<input style="width: 100%;" type="text"/>		
Corrective Action:	<input style="width: 100%;" type="text"/>		Date: _____
<b>Good Housekeeping:</b>			
Type	OTHER		
Comment:	Stained Soil at Hardline to Temp Tank and Engine Exhaust; see photos		
Corrective Action:	For localized stained soils or oily waste - "Properly dispose of oily waste in accordance with 905.e."		Date: <u>05/24/2023</u>
Overall Good: <input type="checkbox"/>			
<b>Spills:</b>			
Type	Area	Volume	
In Containment: No			
Comment:	<input style="width: 100%;" type="text"/>		
<input type="checkbox"/> Multiple Spills and Releases?			
<b>Equipment:</b>			
Type: Bradenhead	# 1		corrective date
Comment:	Appears to be plumbed to surface		
Corrective Action:			Date:
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:			Date:
Type: Pump Jack	# 1		
Comment:			
Corrective Action:			Date:
<b>Venting:</b>			
Yes/No			
Comment:			
Corrective Action:			Date:
<b>Flaring:</b>			
Type			
Comment:			
Corrective Action:			Date:

**Inspected Facilities**

Facility ID: 248821 Type: WELL API Number: 123-16623 Status: PR Insp. Status: PR

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment: SI - Well Shut-In at the time of this Inspection. Wellhead is connected to Hardline to Temp Tank. No Tank Battery to Produced into

Corrective Action:  Date: \_\_\_\_\_

**COGCC Comments**

Comment	User	Date
<a href="#">Routine Field Inspection. Stained Soil at Hardline and Exhaust</a>	petrie	05/10/2023

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696304871	Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6110702">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6110702</a>