

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

403406680

Date Received:

05/18/2023

FIR RESOLUTION FORM

Overall Status:

CA Summary:

3 of 3 CAs from the FIR responded to on this Form

3 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10705

Name of Operator: EVERGREEN NATURAL RESOURCES LLC

Address: 1875 LAWRENCE ST STE 1150

City: DENVER State: CO Zip: 80202

Contact Name and Telephone:

Name: _____

Phone: () Fax: ()

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Distribution, Evergreen

719-846-7898

cogcc.evergreen@enrllc.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 695107382

Inspection Date: 01/26/2023

FIR Submit Date: 01/26/2023

FIR Status: _____

Inspected Operator Information:

Company Name: EVERGREEN NATURAL RESOURCES LLC

Company Number: 10705

Address: 1875 LAWRENCE ST STE 1150

City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 308648

Location Name: CLUCK-632S67W Number: 25NENW County: LAS ANIMAS

Qtrqr: NENW Sec: 25 Twp: 32S Range: 67W Meridian: 6

Latitude: 37.236460 Longitude: -104.841570

FACILITY - API Number: 05-071- -00 Facility ID: 277928

Facility Name: CLUCK Number: 21-25

Qtrqr: NENW Sec: 25 Twp: 32S Range: 67W Meridian: 6

Latitude: 37.236460 Longitude: -104.841570

CORRECTIVE ACTIONS:

1 CA# 167182

Corrective Action: Conduct maintenance on equipment, cleanup stained material and review self inspection processes. COMPLY WITH RULE 1002,(2).D.

Date: 02/07/2023

Response: CA COMPLETED

Date of Completion: 05/17/2023

Operator Comment: Cleaned stained material to comply with rule 1002(2).D

COGCC Decision: _____

Corrective Action:	Securely fasten all valves, pipes, fittings, and Production Facilities to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 608.e.
--------------------	--

Date: 02/26/2023

Date of Completion: 05/17/2023

Operator Comment:	Tightened fittings and cleaned stained materials per rule 1002(2).D
-------------------	---

COGCC Decision:

COGCC
Representative:

Corrective Action:	Lower fluid level so at least two feet of freeboard exists per Rule 909.c.
--------------------	--

Date: 01/27/2023

Date of Completion: 05/17/2023

Operator Comment:	Lowered fluid level below freeboard per rule 909.c
-------------------	--

COGCC Decision:

COGCC
Representative:

Comment:	
----------	--

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Tracy Dyke

Title: Production Technician Date: 5/18/2023 10:14:44 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
403406749	Clean up and freeboard photos

Total Attach: 1 Files