

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

403406680

Date Received:

05/18/2023

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

3 of 3 CAs from the FIR responded to on this Form

3 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10705
Name of Operator: EVERGREEN NATURAL RESOURCES LLC
Address: 1875 LAWRENCE ST STE 1150
City: DENVER State: CO Zip: 80202
Contact Name and Telephone:
Name: _____
Phone: () _____ Fax: () _____
Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
<u>Distribution, Evergreen</u>	<u>719-846-7898</u>	<u>cogcc.evergreen@enrllc.com</u>

COGCC INSPECTION SUMMARY:

FIR Document Number: 695107382
Inspection Date: 01/26/2023 FIR Submit Date: 01/26/2023 FIR Status: _____

Inspected Operator Information:

Company Name: EVERGREEN NATURAL RESOURCES LLC Company Number: 10705
Address: 1875 LAWRENCE ST STE 1150
City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 308648

Location Name: CLUCK-632S67W Number: 25NENW County: LAS ANIMAS
Qtrqtr: NENW Sec: 25 Twp: 32S Range: 67W Meridian: 6
Latitude: 37.236460 Longitude: -104.841570

FACILITY - API Number: 05-071-00 Facility ID: 277928

Facility Name: CLUCK Number: 21-25
Qtrqtr: NENW Sec: 25 Twp: 32S Range: 67W Meridian: 6
Latitude: 37.236460 Longitude: -104.841570

CORRECTIVE ACTIONS:

1 CA# 167182

Corrective Action: Conduct maintenance on equipment, cleanup stained material and review self inspection processes. COMPLY WITH RULE 1002,(2).D. Date: 02/07/2023

Response: CA COMPLETED Date of Completion: 05/17/2023

Operator Comment: Cleaned stained material to comply with rule 1002(2).D

COGCC Decision: Approved via an AMI

COGCC
Representative:

2 CA# 167183

Corrective Action: Securely fasten all valves, pipes, fittings, and Production Facilities to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 608.e.

Date: 02/26/2023

Response: CA COMPLETED

Date of Completion: 05/17/2023

Operator
Comment:

Tightened fittings and cleaned stained materials per rule 1002(2).D

COGCC Decision: Approved via an AMI

COGCC
Representative:

3 CA# 167184

Corrective Action: Lower fluid level so at least two feet of freeboard exists per Rule 909.c.

Date: 01/27/2023

Response: CA COMPLETED

Date of Completion: 05/17/2023

Operator
Comment:

Lowered fluid level below freeboard per rule 909.c

COGCC Decision: Approved via an AMI

COGCC
Representative:

NOTE THE PHOTOS DO NOT SHOW A GOOD IMAGE OF LOWERED FLUID LEVEL IN PIT. PLEASE PROVIDE CLEARER PHOTOS OF CA'S BEING ADDRESSED IN THE FUTURE.

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Tracy Dyke

Signed: _____

Title: Production Technician

Date: 5/18/2023 10:14:44 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
403406680	FIR RESOLUTION SUBMITTED
403406749	Clean up and freeboard photos

Total Attach: 2 Files