

**Storm Water Management and Erosion control**  
**Location Name: TEP ROCKY MOUNTAIN LLC SPECIALTY RESTAURANTS SG 33-32**  
**Location ID: 413524**



**Location Overview: Location is approximately 100 yards from  
a creek that contributes to the Colorado River &  
approximately 655 yards from the Colorado River itself  
Section/Township/Range: 32 7S96W**

## Storm water Management and Erosion control

Location Name: TEP ROCKY MOUNTAIN LLC SPECIALTY RESTAURANTS SG 33-32

Location ID: 413524



North West corner of location.



North East corner of location.



South West corner of location.



South East corner of location.