

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

403417493

Date Received:

05/31/2023

FIR RESOLUTION FORM

Overall Status:

CA Summary:

1 of 2 CAs from the FIR responded to on this Form

1 CA Completed  
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10779

Name of Operator: SCOUT ENERGY MANAGEMENT LLC

Address: 13800 MONTFORT DRIVE SUITE 100

City: DALLAS State: TX Zip: 75240

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) Fax: ( )

Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name	Phone	Email
Kellerby, Shaun	(970) 712-1248	shaun.kellerby@state.co.us
Patterson, Chris		Chris.Patterson@scoutep.com
Johnson, Mike		Mike.Johnson@scoutep.com
Sanford, Anita	(970) 551-8313	Anita.Sanford@scoutep.com
Regulatory, Rangely		RangelyRegulatory@scoutep.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 702501252

Inspection Date: 05/03/2023

FIR Submit Date: 05/03/2023

FIR Status: \_\_\_\_\_

Inspected Operator Information:

Company Name: CHEVRON USA INC

Company Number: 16700

Address: 760 HORIZON DRIVE STE 401

City: GRAND JUNCTION State: CO Zip: 81506

LOCATION - Location ID: 314616

Location Name: U P-62N102W Number: 27SWSE County: RIO BLANCO

Qtrqr: SWSE Sec: 27 Twp: 2N Range: 102W Meridian: 6

Latitude: 40.108590 Longitude: -108.827030

FACILITY - API Number: 05-103-00 Facility ID: 229131

Facility Name: UNION PACIFIC Number: 17-27

Qtrqr: SWSE Sec: 27 Twp: 2N Range: 102W Meridian: 6

Latitude: 40.108590 Longitude: -108.827030

CORRECTIVE ACTIONS:

2 CA# 170490

Corrective Action: Provide proper Stormwater BMPs to control runoff in a manner that minimizes erosion, transport of sediment offsite, and site degradation. Vehicle tracking BMPs to control potential sediment discharges from operational roads, well pads, and other unpaved surfaces.

Date: 06/03/2023

Response: CA COMPLETED

Date of Completion: 05/30/2023

Operator  
Comment:

Tracking pad BMP installed to prevent sediment migration from location and lease road. See attached pictures.

COGCC Decision:

COGCC  
Representative:

#### OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Anita Sanford

Signed: \_\_\_\_\_

Title: Regulatory Analyst

Date: 5/31/2023 7:03:03 AM

### ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

403417494	pictures
-----------	----------

Total Attach: 1 Files