

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
403420376

Date Received:
06/01/2023

FIR RESOLUTION FORM

Overall Status:

CA Summary:

3 of 5 CAs from the FIR responded to on this Form

3 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10651
Name of Operator: VERDAD RESOURCES LLC
Address: 1125 17TH STREET SUITE 550
City: DENVER State: CO Zip: 80202
Contact Name and Telephone:
Name: _____
Phone: () _____ Fax: () _____
Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
<u>Michael Cugnetti</u>	<u>7208456901</u>	<u>mcugnetti@verdadresources.com</u>

COGCC INSPECTION SUMMARY:

FIR Document Number: 708200267
Inspection Date: 05/17/2023 FIR Submit Date: 05/23/2023 FIR Status: _____

Inspected Operator Information:

Company Name: VERDAD RESOURCES LLC Company Number: 10651
Address: 1125 17TH STREET SUITE 550
City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 456879

Location Name: Timbro 9-59 Number: 8B County: _____
Qtrqr: W2S Sec: 8 Twp: 9N Range: 59W Meridian: 6
W
Latitude: 40.761695 Longitude: -104.009524

FACILITY - API Number: 05-123-00 Facility ID: 456879

Facility Name: Timbro 9-59 Number: 8B
Qtrqr: W2S Sec: 8 Twp: 9N Range: 59W Meridian: 6
W
Latitude: 40.761695 Longitude: -104.009524

CORRECTIVE ACTIONS:

1 CA# 171320

Corrective Action: Comply with Rule 606. Date: 05/31/2023

Response: CA COMPLETED Date of Completion: 05/26/2023

Operator Comment: Pipe removed from SW ditch. see attachments for corrective action photo documentation.

COGCC Decision: _____

COGCC
Representative:

3 CA# 171322

Corrective Action: Comply with Rule 606.

Date: 05/31/2023

Response: CA COMPLETED

Date of Completion: 05/26/2023

Operator Comment: All trash was removed from location. see attachments for corrective action photo documentation.

COGCC Decision:

COGCC
Representative:

5 CA# 171324

Corrective Action: Comply with Rule 1002.f.(2) to install BMPs in accordance with good engineering practices.

Date: 05/25/2023

Response: CA COMPLETED

Date of Completion: 05/26/2023

Operator Comment: All rill erosion and BMPs have been repaired and improved. see attachments for corrective action photo documentation.

COGCC Decision:

COGCC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Michael Cugnetti

Signed:

Title: Director of EHS&R

Date: 6/1/2023 2:51:45 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
403420407	Corrective Action Photo Documentation
403420408	Corrective Action Photo Documentation
403420409	Corrective Action Photo Documentation
403420410	Corrective Action Photo Documentation
403420411	Corrective Action Photo Documentation

Total Attach: 5 Files