

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
403420435

Date Received:
06/01/2023

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

2 of 3 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10651

Name of Operator: VERDAD RESOURCES LLC

Address: 1125 17TH STREET SUITE 550

City: DENVER State: CO Zip: 80202

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Michael Cugnetti

Phone

7208456901

Email

mcugnetti@verdadresources.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 708200269

Inspection Date: 05/17/2023

FIR Submit Date: 05/23/2023

FIR Status: _____

Inspected Operator Information:

Company Name: VERDAD RESOURCES LLC

Company Number: 10651

Address: 1125 17TH STREET SUITE 550

City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 456563

Location Name: Timbro 9-59 Number: 8A County: _____

Qtrqr: SWN Sec: 8 Twp: 9N Range: 59W Meridian: 6
W

Latitude: 40.767703 Longitude: -104.010021

FACILITY - API Number: 05-123- -00 Facility ID: 456563

Facility Name: Timbro 9-59 Number: 8A

Qtrqr: SWN Sec: 8 Twp: 9N Range: 59W Meridian: 6
W

Latitude: 40.767703 Longitude: -104.010021

CORRECTIVE ACTIONS:

1 ☒ CA# 171325

Corrective Action: Properly dispose of oily waste in accordance with 905.e.

Date: 06/07/2023

Response: CA COMPLETED

Date of Completion: 05/25/2023

Operator Comment: Leak repaired and impacted soil was removed and properly disposed of. See attachments for corrective action photo documentation.

COGCC Decision: Approved pending re-inspection

COGCC Representative: Approved pending re-inspection. Based on photo documentation provided, work to address the corrective action appears to have been performed. A field inspection will be conducted at a future date to evaluate compliance with COGCC rules.

3 ☒ CA# 171327

Corrective Action: Comply with Rule 1002.f.(2) to install BMPs in accordance with good engineering practices.

Date: 05/25/2023

Response: CA COMPLETED

Date of Completion: 05/25/2023

Operator Comment: Rills and BMPs were repaired and improved. See attachments for corrective action photo documentation.

COGCC Decision: Approved pending re-inspection

COGCC Representative: Approved pending re-inspection. Based on photo documentation provided, work to address the corrective action appears to have been performed. A field inspection will be conducted at a future date to evaluate compliance with COGCC rules.

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Michael Cugnetti

Signed:

Title: Director of EHS&R

Date: 6/1/2023 3:00:34 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
403420435	FIR RESOLUTION SUBMITTED
403420443	Corrective Action Photo Documentation
403420444	Corrective Action Photo Documentation
403420445	Corrective Action Photo Documentation

Total Attach: 4 Files