

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/30/2023

Submitted Date:

05/31/2023

Document Number:

702501392

**FIELD INSPECTION FORM**

Loc ID 312916	Inspector Name: Burchett, Kirby	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____	<b>Status Summary:</b> <input type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input checked="" type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED
<b>Operator Information:</b> OGCC Operator Number: 10409 Name of Operator: PEAKVIEW OPERATING COMPANY LLC Address: 2427 WEST KETTLE CIRCLE City: LITTLETON State: CO Zip: 80120				<b>Findings:</b> 10 Number of Comments 5 Number of Corrective Actions <input checked="" type="checkbox"/> Corrective Action Response Requested
				<b>ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE</b>

**Contact Information:**

Contact Name	Phone	Email	Comment
Kellerby, Shaun	(970) 712-1248	shaun.kellerby@state.co.us	
Walters, Steve	(720) 402-3081	swalters@peakviewenergy.com	
Wise, Wayne	(405) 826-7013	wise@peakviewenergy.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
222829	WELL	PR	05/17/1973	OW	081-06189	VOLOSHIN-MORTON 1 (-8)	PR

**General Comment:****COGCC Inspection Report Summary**

On Wednesday, 03/31/2023, Inspector Kirby Burchett, conducted a routine field inspection at Peakview Operating Company LLC on the Voloshin-Morton 1-8 well, Location #312916, in Moffat County, Colorado.

This location is within or in close proximity to a CPW District with High Priority, NSO, Density, and Other Consultation Habitat Regulations. Public Water System (PWS) Rules also apply.

Any Corrective Actions from previous Inspections are still applicable.

While there during normal operations the following compliance issues were found:

1. Debris.
2. Stained soils.
3. Unused equipment.
4. Equipment open to wildlife.
5. Insufficient Stormwater BMPs.

Refer to attached photographs for Corrective Action.

A follow up on this site inspection will be conducted to ensure all compliance issues have been corrected to comply with COGCC rules.

**Location**Overall Good: ☐**Signs/Marker:**

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	

**Emergency Contact Number:**

Comment: 303-881-1130 or 911 / 720-402-3080

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type	DEBRIS		
Comment:	Random debris		
Corrective Action:	All trash, rubbish, and other waste material will be properly contained until removed from the Oil and Gas Location. At no time will trash, debris, or rubbish be placed or remain on the ground.	Date:	06/07/2023
Type	OTHER		
Comment:	Stained soils around tank battery, separator and various spots around location		
Corrective Action:	Control and contain spills/releases. Clean up and properly dispose of oily waste.	Date:	06/15/2023
Type	UNUSED EQUIPMENT		
Comment:	Separator appears to have been bypassed and is no longer in service.		
Corrective Action:	Unnecessary equipment must be removed from location.	Date:	06/30/2023

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

Type: Vertical Separator	# 1		corrective date
Comment:	Out of Service?		
Corrective Action:		Date:	
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:		Date:	

Type: Bradenhead	# 1	
Comment:		
Corrective Action:		Date:
Type: Pump Jack	# 1	
Comment:		
Corrective Action:		Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	2	400 BBLs	STEEL AST		,
Comment:	Loadline and tank valves capped or plugged. Only 1 tank in service at this time. Line disconnected on top of tank open to wildlife.				
Corrective Action:	All stacks, vents, or other openings will be equipped with screens or other appropriate equipment to prevent entry by wildlife, including birds and bats.				Date: 06/07/2023

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:	Unlined			
Corrective Action:				Date:

**Venting:**

Yes/No	NO	
Comment:		
Corrective Action:		Date:

**Flaring:**

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities									
Facility ID:	222829	Type:	WELL	API Number:	081-06189	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Rod pump								
Corrective Action:						Date:			

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Ditches						
Berms						

Comment: Stormwater BMPs need implementation and maintenance.

Corrective Action: Provide proper Stormwater BMPs to control runoff in a manner that minimizes erosion, transport of sediment offsite, and site degradation. Vehicle tracking BMPs to control potential sediment discharges from operational roads, well pads, and other unpaved surfaces.

Date: 06/15/2023

Pits: ☒ NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403418982	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6131510">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6131510</a>
702501399	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6131506">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6131506</a>