

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

403430858

Date Received:

06/12/2023

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

2 of 4 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10651

Name of Operator: VERDAD RESOURCES LLC

Address: 1125 17TH STREET SUITE 550

City: DENVER State: CO Zip: 80202

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Michael Cugnetti

Phone

720-845-6901

Email

mcugnetti@verdadresources.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 708200282

Inspection Date: 05/26/2023

FIR Submit Date: 05/31/2023

FIR Status: _____

Inspected Operator Information:

Company Name: VERDAD RESOURCES LLC

Company Number: 10651

Address: 1125 17TH STREET SUITE 550

City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 432694

Location Name: Shull Number: 1-35-9-60 County: _____
PAD

Qtrqtr: NENE Sec: 35 Twp: 9N Range: 60W Meridian: 6

Latitude: 40.713140 Longitude: -104.054300

FACILITY - API Number: 05-123- -00 Facility ID: 432694

Facility Name: Shull Number: 1-35-9-60
PAD

Qtrqtr: NENE Sec: 35 Twp: 9N Range: 60W Meridian: 6

Latitude: 40.713140 Longitude: -104.054300

CORRECTIVE ACTIONS:

1 ☒ CA# 171638

Corrective Action: Comply with Rule 606. Corrective action date is the date the location was observed out of compliance.

Date: 05/26/2023

Response: CA COMPLETED

Date of Completion: 06/03/2023

Operator
Comment:

All equipment from the adjacent frac job was moved off of location.

COGCC Decision: Approved pending re-inspection

COGCC Representative: Approved pending re-inspection of this FIR resolution acknowledges the document was received. It is not an acknowledgement that the corrective action has been passed. A field inspection will be conducted at a future date to evaluate compliance with COGCC rules.

4  CA# 171641

Corrective Action: Install or repair required BMPs per Rule 1002.f.(2)C. Corrective action date is the date the location was observed out of compliance.

Date: 05/26/2023

Response: CA COMPLETED

Date of Completion: 06/01/2023

Operator Comment: BMPs have been repaired. stained soil has been removed an properly disposed of.

COGCC Decision: Approved pending re-inspection

COGCC Representative: Approved pending re-inspection. Based on photo documentation provided, work to address the corrective action appears to have been performed. A field inspection will be conducted at a future date to evaluate compliance with COGCC rules.

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Michael Cugnetti

Signed: _____

Title: Director of EHS&R

Date: 6/12/2023 3:38:33 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
403430858	FIR RESOLUTION SUBMITTED
403430897	corrective action photo documentation
403430898	corrective action photo documentation
403430900	corrective action photo documentation
403430901	corrective action photo documentation

Total Attach: 5 Files