

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/27/2023

Submitted Date:

06/28/2023

Document Number:

710300062**FIELD INSPECTION FORM**Loc ID 303295 Inspector Name: Wolfe, Stephen On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10699Name of Operator: OWN RESOURCES OPERATING LLCAddress: 305 S RIDGE STREET #6279City: BRECKENRIDGE State: CO Zip: 80424**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:1 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
McCoy, Diane		diane.mccoy@state.co.us	
Welsh, Brian		brian.welsh@state.co.us	
Burn, Diana		diana.burn@state.co.us	

General Comment:

6/27/23
P&A
Engineering witness
CP=0, BH=0 psi - no tbg in the well
Set CIBP @ 1377', dump bail 2 sx of cement
Run CBL from 1330-0', TOC=600'. COGCC approval to move planned CIBP from 550' to 630'.
Set CIBP @ 630', dump bail 2 sx of cement.
Shoot squeeze holes at 316'.
Pump truck lost hydraulics and had to go back to shop for repairs.
SWFN.

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
710300065	Photo	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6163175
710300066	Photo	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6163176