

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/29/2023

Submitted Date:

06/30/2023

Document Number:

690204389

FIELD INSPECTION FORMLoc ID 324831 Inspector Name: COSTA, RYAN On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 83130

Name of Operator: STRACHAN EXPLORATION INC

Address: 383 INVERNESS PKWY, STE 360

City: ENGLEWOOD State: CO Zip: 80112

Status Summary:☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

5 Number of Comments

4 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
HARMS JASON		jason@strachanexploration.com	
BEAR STACY		stacy@strachanexploration.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
213004	WELL	PR	06/01/2022	OW	061-06365	FRAZEE 2-6	RI

General Comment:On 6/29/2023, Ryan Costa conducted a location inspection.
See attached photos and additional details within this report.

LocationOverall Good: ☐

Signs/Marker:			
Type	TANK LABELS/PLACARDS		
Comment:	The labeling on the tanks is faded and/or missing. Corrective action is the day of inspection and the location will remain out of compliance until completed.		
Corrective Action:	Install sign to comply with Rule 605.h.	Date:	06/29/2023

Emergency Contact Number:

Comment:		Date: _____
Corrective Action:		

Overall Good: ☐

Spills:				
Type	Area	Volume		
Crude Oil	Pump Jack			
Comment:	There is oily sludge that has spilled onto the ground that needs to be cleaned up. Operator was notified the day of inspection for immediate clean up.			
Corrective Action:	Control and contain spills/releases and clean up per Rule 912.a.			Date: 06/29/2023

In Containment: No

Comment: ☐ Multiple Spills and Releases?

Fencing/:			
Type	TANK BATTERY		
Comment:	The fence around the tanks and production equipment is inadequate to prevent livestock entry. Corrective action is the day of inspection and the location will remain out of compliance until completed.		
Corrective Action:	Comply with the fencing requirements per the 1002a rules		
		Date:	06/29/2023

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
OTHER	2		STEEL AST		,
Comment:					
Corrective Action:					
				Date:	

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:	There are two large volume tanks with no labeling and no secondary containment. Corrective action is the day of inspection and the location will remain out of compliance until completed.			

Inspector Name: COSTA, RYAN

Corrective Action:	Repair or install berms or other secondary containment devices per Rule 603.o.	Date:	06/29/2023
--------------------	--------------------------------------------------------------------------------	-------	------------

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
690204390	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6166820