

## Tiffany 5-2 and 5-3 COGCC Inspection # 690203356 and 690204125



Measuring approx. 3.51 acres disturbed, an average of 6-inches of topsoil removed at the start of wellsite construction resulted in over 2800 cu. yds of topsoil stored at the location. No additional topsoil imported to the location as amounts satisfies estimated amounts. Topsoil areas are labeled with signage to designate it as separate from the normal operating pad. Areas are stabilized with hydromulched seed.