



00197258

Rule 1004

COLORADO OIL & GAS CONSERVATION COMMISSION

FIELD INSPECTION REPORT

☐ NOTICE OF UNSATISFACTORY INSPECTION

☐ NOTICE OF SATISFACTORY INSPECTION

1120 Lincoln Street, Suite 801
Denver, CO 80203
(303)894-2100

API No. 05- <u>123</u> - ¹³⁶⁴² 60029	LEASE NAME: <u>Long #2</u>
LOCATION: <u>SUNB-509-25 GN-6W</u>	OPERATOR: <u>Haber Corp Nautilus</u>
DATE: <u>4/4/97</u>	INSPECTOR: <u>Paul Ke</u>
Insp. Type: <u>SR</u>	Insp. Status: <u>PA</u> PA: Y <u>(N)</u> Pass/Fail: P <u>(F)</u> Viol.: Y <u>(N)</u> NOV: Y <u>(N)</u>

INSPECTION ITEM	COMMENTS	INPUT
Well ID Signs (Rule 210, 604.c(4))	<u>Culvert needs removed -</u>	
Pits (Reserve/Production) (Rule 902, 903, 904, 905)	<u>ripped gravel -</u>	
Fences (Rule 603.b.7, 604.C.(3), 1002.A)	<u>can be hauled &</u>	
Tank Battery Equipment (Rule 603.b.3, 604)	<u>dumped on road -</u>	
Fire Walls/Berms/Dikes (Rule 603.b.12, 604)	<u>tank battery location</u>	
General Housekeeping (Rule 603)	<u>need gravel & trash</u>	
Spills (Oil/Water) (Rule 907)	<u>removed, ripped</u>	
Bradenhead (Rule 207.b)	<u>no top soil</u>	
Drilling Well/Workover (Rule 317)	<u>road to well head</u>	
Surface Rehabilitation (Rule 1002, 1003, 1004, 1103)	<u>needs ripped & junk</u>	
Miscellaneous	<u>removed</u>	

CORRECTIVE ACTION REQUIRED:

Can landowner do work instead of contractor

Date Corrective Action Required By:

Date Remedied:

This report is a Notice of Inspection. The Commission requires that you correct any deficiencies shown on this report in a timely manner. Failure to comply may result in enforcement action by the Commission.

Recommend for ERF

White - File Canary - Operator Pink - Well Site

APR - 9 1997