

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/07/2023

Submitted Date:

07/07/2023

Document Number:

702402050**FIELD INSPECTION FORM**Loc ID 317748 Inspector Name: Revas, Robbie On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 46290Name of Operator: KP KAUFFMAN COMPANY INCAddress: 1700 LINCOLN ST STE 4550City: DENVER State: CO Zip: 80203**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:5 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		rwatzman@kpk.com	All Inspections
Silver, Randy		randy.silver@state.co.us	
,		cogcc@kpk.com	All Inspections
Adamczyk, Megan		megan.adamczyk@state.co.us	complaint inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
239912	WELL	PR	12/07/2001	OW	123-07700	MCCRUMB 1	SI
470370	TANK BATTERY	AC	12/20/2019		-	McCrumb 1 & 2 battery	AC

General Comment:

Inspected Facilities

Facility ID: 239912 Type: WELL API Number: 123-07700 Status: PR Insp. Status: SI

Complaint

Comment: Inspection in response to complaint.
 Compliance Specialist Assigned: Robbie Revas
 Complaint Received
 Date: 7-6-2023
 Complaint Contacted: No
 Date: Time:
 API # 05-123-07700 & Location ID: 317748
 Location name: McCrumb #1 & McCrumb 1&2 Battery
 Inspection Document # 702402044
 Complaint inspection document # 702402050
 Complaint Document form 18 # 403452996
 Nature of Complaint: Spills/Soil contamination leaking wellhead.
 Field Inspector Actions:
 On 7-6-2023, I Robbie Revas area Compliance Specialist was assigned a complaint received by
 COGCC staff in reference to Spills/Soil Contamination. The complainant stated the issues were at the well location.
 The complainant's detailed description of the issues are in the form 18.
 On 7-6-23, I performed a complete site inspection of the well location & tank battery.
 At time of inspection, I did not see the WH actively leaking (passed a spray bottle bubble test) or soil contamination at the base of the WH. I did write up compliance issues, you can find them in my prior inspection document, above on the COGCC website.
 Weather Conditions: Cloudy & warm.
 Location: Muddy
 Violations of COGCC rules were observed at the time of the inspection.
 All information has been reviewed and site inspection information has been submitted to the COGCC for further review.

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 01/16/2023 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

Facility ID: 470370 Type: TANK API Number: - Status: AC Insp. Status: AC

COGCC Comments

Comment	User	Date
Inspection due to a complaint Form 18 Doc # 403452996	revasr	07/07/2023

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
702402051	location pics	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6173499