

FORM
INSPRev
X/20

State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/29/2023

Submitted Date:

07/05/2023

Document Number:

694100112

FIELD INSPECTION FORM

Loc ID 336708 Inspector Name: Robinson, Taylor On-Site Inspection 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 16700
Name of Operator: CHEVRON USA INC
Address: 760 HORIZON DRIVE STE 401
City: GRAND JUNCTION State: CO Zip: 81506

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:

- 7 Number of Comments
4 Number of Corrective Actions
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
, PDC		cogccinspection@pdce.com	All Inspections
Liesenfeld, Zack		Zack.Liesenfeld@pdce.com	
,		COGCCInspection@pdce.com	All Inspections

General Comment:

This is an environmental inspection for Spill ID 483346 Stroh O 13-21D. Any corrective actions from previous inspections that have not been addressed are still applicable. There were no operator or contract environmental personnel on location at the time of this field inspection. Photos attached to document site conditions.

This is actually a PDC location. Operator number 69175.

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type

Comment: Weeds present at several locations throughout site. See photos.

Corrective Action: Weeds need to be removed/cleared. Statewide unnecessary equipment, weeds, waste, and trash requirements. Comply with Rule 606.

Date: 07/12/2023

Overall Good:

Spills:

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

Venting:

Yes/No

Comment:

Corrective Action:

Date:

Flaring:

Type

Comment:

Corrective Action:

Date:

Location Construction

Location ID: 301509 CDP: _____

Comment: _____

Corrective Action: _____

Date: _____

Form 2A COAs:

Comment: _____

Corrective Action: _____

Date: _____

Wildlife BMPs:

Comment: Catch basin holding solar panel and associated battery is not covered. Fluid inside needs to be drained and/or covered with netting to keep wildlife out.

Corrective Action: Netting on open top tanks inadequate. Install or repair wildlife protection equipment.

Date: 07/12/2023

Comment: Multiple rills and ruts forming near entrance of location.

Corrective Action: Regrading is needed. Install or repair required BMPs per Rule 1002.f.(2)C.

Date: 07/12/2023

On Site Inspection (305):

Surface Owner Contact Information:

Name: _____ Address: _____

Phone Number: _____ Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____ Phone Number: _____

Date Onsite Request Received: _____ Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Environmental

Spills/Releases:

Type of Spill: _____ Estimated Spill Volume: _____

Comment: Slight leaking of oily substance at waht appears to be a small vru near the white vertical separator.

Corrective Action: "For localized stained soils or oily waste - ""Properly dispose of oily waste in accordance with 905.e."" For larger instances: ""Properly dispose of oily waste in accordance with Rule 905.e and contact area COGCC EPS""" Date: 07/12/2023

Reportable: _____ GPS: Lat _____ Long _____

Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well Complaint:

Lat _____ Long _____

DWR Receipt Num: _____ Owner Name: _____ GPS : _____

Field Parameters:

Sample Location: _____ Comment: _____

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403453876	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6169947
694100113	Photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6169929