

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 (303) 894-2100 Fax: (303) 854-2109



FOR OGCC USE ONLY

RECEIVED

AUG - 1 00

COGCC

Bm

WELL ABANDONMENT REPORT

Submit original plus one copy. This form is to be submitted as an intent whenever a plugging is planned on a borehole. The approved intent shall be valid for six months after the approval date; after that period a new intent will be required. After the plugging is complete, this form and one copy shall again be submitted as a subsequent report of the work as actually completed.

OGCC Operator Number: 94090

Name of Operator: Walsh Production, Inc.

Address: P. O. Box 30

City: Sterling State: CO Zip: 80751

Contact Name and Telephone

Bill Walsh

No: (970) 522-1839

Fax: (970) 522-2535

24 hour notice required, contact:

Tel:

API Number: 05-075-05295

OGCC Lease No.: 27322

Other wells this lease? ☒ Y ☐ N

Well Name: State A

Well Number: #3

Location (Qtr, Sec, Twp, Rng, Meridian): SWSESE Sec. 20-T7N-R53W

County: Logan

Federal, Indian or State Lease Number: 70/8163-I

Field Name: Atwood

Field Number: 03700

Complete the Attachment Checklist

	Oper	OGCC
Wellbore Diagram		
Cement Job Summary		
Wireline Job Summary		

☐ Notice of Intent to Abandon

☒ Subsequent Report of Abandonment

Only Complete the Following Background Information for Intent to Abandon

Reason for Abandonment: ☐ Dry ☐ Production Sub-Economic ☐ Mechanical Problems ☐ Other  
Casing to be Pulled: ☐ Yes ☐ No Top of Casing Cement: \_\_\_\_\_  
Fish in Hole: ☐ Yes ☐ No If yes, explain details below: \_\_\_\_\_  
Wellbore has Uncemented Casing Leaks: ☐ Yes ☐ No If yes, explain details below: \_\_\_\_\_  
Details: \_\_\_\_\_



Current and Previously Abandoned Zones

Formation	Perforations - Top	Perforations - Bottom	Date Abandoned	Method of Isolation (None, Squeezed, BP, Cement, etc.)	Plug Depth

Casing History

Casing String	Casing Size	Casing Depth	Cement Top	Stage Cement Top

Plugging Procedure for Intent and Subsequent Report

CIBP #1: Depth 4600 with 2 sacks cmt on top. CIBP #2: Depth \_\_\_\_\_ with \_\_\_\_\_ sacks cmt on top.

NOTE: Two (2) sacks cement required on all CIBPs.

Set \_\_\_\_\_ sks cmt from \_\_\_\_\_ ft. to \_\_\_\_\_ ft. in ☐ Casing ☐ Open Hole ☐ Annulus  
Set \_\_\_\_\_ sks cmt from \_\_\_\_\_ ft. to \_\_\_\_\_ ft. in ☐ Casing ☐ Open Hole ☐ Annulus  
Set \_\_\_\_\_ sks cmt from \_\_\_\_\_ ft. to \_\_\_\_\_ ft. in ☐ Casing ☐ Open Hole ☐ Annulus  
Set \_\_\_\_\_ sks cmt from \_\_\_\_\_ ft. to \_\_\_\_\_ ft. in ☐ Casing ☐ Open Hole ☐ Annulus  
Set \_\_\_\_\_ sks cmt from \_\_\_\_\_ ft. to \_\_\_\_\_ ft. in ☐ Casing ☐ Open Hole ☐ Annulus

Perforate and squeeze at \_\_\_\_\_ ft. with \_\_\_\_\_ sacks Leave at least 100 ft. in casing

Perforate and squeeze at \_\_\_\_\_ ft. with \_\_\_\_\_ sacks Leave at least 100 ft. in casing

Perforate and squeeze at \_\_\_\_\_ ft. with \_\_\_\_\_ sacks Leave at least 100 ft. in casing

Set 50 sacks half in, half out surface casing from 275 ft. to 150 ft.

Set 10 sacks at surface

Cut four feet below ground level, weld on plate

Dry-Hole Marker: ☐ Yes ☒ No

Set \_\_\_\_\_ sacks in rat hole Set \_\_\_\_\_ sacks in mouse hole

Additional Plugging Information for Subsequent Report Only

Casing Recovered: 2850 ft. of 7 1/2 inch casing.

Plugging Date: 7-19-00

\*Wireline Contractor:

\*Cementing Contractor: Howard's Casing Pulling Sterling, CO 80751

Type of Cement and Additives Used:

\*Attach Job Summaries.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: William M. Walsh

Signed:

Title: President

Date: 7-31-00

OGCC Approved:

Title:

Date: 8/25/00

CONDITIONS OF APPROVAL, IF ANY:



HOWARD'S  
CASING PULLING, LLC



20617 County Rd. 48  
Sterling, Colorado 80751  
(970) 522-8291

RECEIVED  
AUG-1-00  
COGCC

# INVOICE

DATE	INVOICE #
7-27-00	#118

BILL TO: Walsh Production, Inc.

ADDRESS P.O. Box 30  
Sterling, CO. 80751  
WELL: State A # 3

DESCRIPTION OF WORK	RATE	AMOUNT
7-11-00 Moved rig on well, raised mast.		
7-12-00 Set in junk rack and pumps. Dug out dead men and reset them. 7 hr Hooked up lines. Filled cellar in for jacks.	7 hr	
7-13-00 Set in jacks and worked to 25". Shot at 3000'.	8 hr	
7-14-00 Worked pipe to 28". Shot at 2850', worked loose and pulled 3 joints.	9 hr	
7-17-00 Pulled on 7", and got out 40 joints. Pipe was tight.	8 hr	
7-18-00 Pulled out 7", 95 in all. Ran 1" tubing to 275'.	7 hr	
7-19-00 Took up 60 sacks of cement. 8 hr Pumped 50 sacks of cement out at 275'. Pumped 10 sacks of cement out in top of 10 3/4". Loaded junk rack, lowered poles. Well complete.		
Pulling unit and crew.		\$4700.00
Truck to pick up and deliver cement.		100.00
Pumps.		500.00
Water truck.		63.00
Shots, 2		600.00
Cement 60 sacks.		479.00
<div style="text-align: right;"> H085 775 53801   <i>Plug &amp; Abandon</i>  #3 </div>		
THANK YOU:	TOTAL	\$6442.00

All open accounts are due by the 10th of the month following purchase. All amounts 30 days past due will be assessed a Finance Charge at 1 1/2% per month or an Annual Percentage Rate of 18% on the balance.

RECEIVED  
AUG -1 00  
COGCC

# Logan County Lumber Company

502 S. 11TH AVENUE  
STERLING, COLORADO 80751  
(970) 522-0329

SOLD TO

SHIP TO

HOWARD'S CASING PULLING, LLC  
20617 CTV RD 48

Walsh Production  
State R, Well #3

STERLING, CO 80751

522-8291

522-8291

TERMS: 1.5% PER MONTH (18% ANNUAL FINANCE CHARGE)  
(50¢ MINIMUM) WILL BE ADDED TO PAST DUE BALANCES.

Shipment #: 1

ACCOUNT #	CUSTOMER P.O. #	TERMS	ORDER #	ORDER DATE	SLSMN	INVOICE #	INVOICE DATE
11010954		NET 10TH PROJ	11002327	07/19/00	BA9	11002327	07/19/00

ORDERED	BACK ORDERED	SHIPPED	U/M	DESCRIPTION	PRICE	AMOUNT
60	0	60	EA	PORTLAND CEMENT TYPE 1 940- PCI	7.480	448.80
2	0	2	EA	pallet deposit M13	12.000	24.00

July 19, 2000 08:35:17 OT:BA9				FILLED BY	CHKD BY	DRIVER	MERCHANDISE	472.80
SHIP VIA							OTHER	0.00
***** * INVOICE * *****							TAX 7.920%	37.73
PAGE 1 OF 1							FREIGHT	0.00
							TOTAL	