



✓

# COLORADO OIL & GAS CONSERVATION COMMISSION FIELD INSPECTION REPORT



<input type="checkbox"/> NOTICE OF UNSATISFACTORY INSPECTION		1120 Lincoln Street, Suite 801	
<input type="checkbox"/> NOTICE OF SATISFACTORY INSPECTION		Denver, CO 80203	
		(303)894-2100	
API No. 05- 075 - 9307		LEASE NAME: Gheryl Lynn 1	
LOCATION: C-NP NW 21-7N-53W		OPERATOR: Crown Retro.	
DATE: 2-11-97 8pm		INSPECTOR: EBB	
Insp. Type: —	Insp. Status: DA	PA: Y N	Pass/Fail: P F
		Viol.: Y N	NOV: Y N

INSPECTION ITEM	COMMENTS	INPUT
<b>Well ID Signs</b> (Rule 210, 604.c(4))		
<b>Pits (Reserve/Production)</b> (Rule 902, 903, 904, 905)		
<b>Fences</b> (Rule 603.b.7, 604.C.(3), 1002.A)	1 AM 2-12-97 pump 40 5x Cement @ 15ND Top 4700'	
<b>Tank Battery Equipment</b> (Rule 603.b.3, 604)	pump 40 5x Cement @ 350' (5623)	
<b>Fire Walls/Berms/Dikes</b> (Rule 603.b.12, 604)	pump 10 5x @ 35' for top plug.	
<b>General Housekeeping</b> (Rule 603)		
<b>Spills (Oil/Water)</b> (Rule 907)	Cur	
<b>Bradenhead</b> (Rule 207.b)		
<b>Drilling Well/Workover</b> (Rule 317)	Gary, Ashby Dr/g.	
<b>Surface Rehabilitation</b> (Rule 1002, 1003, 1004, 1103)		
<b>Miscellaneous</b>		

<b>CORRECTIVE ACTION REQUIRED:</b>	
Date Corrective Action Required By:	Date Remedied:

This report is a Notice of Inspection. The Commission requires that you correct any deficiencies shown on this report in a timely manner. Failure to comply may result in enforcement action by the Commission.