

Weld OEM Spill Report Form

Submitted on	18 July 2023, 9:46AM
Receipt number	1201
Related form version	17

Company

Company name	Civitas Resources
Address	650 Southgate Drive
City	Windsor
State	Colorado
Zip code	80550

Contact Information

Contact person	Costin McQueen
Contact phone	720-384-6452
Contact email	cmcqueen@civiresources.com

About the Spill

Date incident occurred	07/17/2023
Was 9-1-1 called for this incident	No
Longitude	-105.045103
Latitude	40.126691
Fire depatment/district	Mountain View Fire Protection District
Where did the incident occur?	Oil and gas facility/pipeline

Oil and Gas Incident

Well site name	Regnier Farms 19H-B268
----------------	------------------------

Section	19
Township	2N
Range	68W
Where did the spill occur	Tank battery
Have you submitted a form 19	Yes
Form 19 report number	403467622

Product Spilled

Product spilled	PRODUCED WATER
Number of barrels spilled	1
Emergency precautions taken	N/A
Extremely hazardous substance	No
Acute or chronic health risks	No
Did the spill affect or end near a waterway, irrigation ditch, or a retention pond?	No
What caused the spill/release?	Weld or joint failure

Narrative

Include specific incident information and mitigation actions taken to stop and clean-up the spill/release

A compromised produced water dump line at the Regnier Farms 1J-19H separator resulted in 0.27 bbls of fluid to be spilled to the surface and a currently unknown volume to the subsurface. The impacted soil will be removed following utility locates and hauled for disposal. Confirmation soil samples will be collected in compliance with COGCC Table 915-1. Additionally, a waste characterization sample from the source area will be collected and submitted for analysis of COGCC Table 915-1 constituents.

Acknowledgement

I acknowledge that a written follow-up notice must be submitted to Weld County OEM/LEPC as soon as practicable after the release. The follow-up notice must update information included in the initial notice and provide information on actual response actions taken and advice regarding medical attention necessary for citizens exposed.