

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

403472130

Date Received:

07/20/2023

FIR RESOLUTION FORM

Overall Status:

CA Summary:

4 of 4 CAs from the FIR responded to on this Form

4 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 69175

Name of Operator: PDC ENERGY INC

Address: 1099 18TH STREET SUITE 1500

City: DENVER State: CO Zip: 80202

Contact Name and Telephone:

Name:

Phone: () Fax: ()

Email:

Additional Operator Contact:

Contact Name

Phone

Email

Tyranny Bergin

970-313-5547

EHSCOGCCInspections@pdce.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 694100112

Inspection Date: 06/29/2023

FIR Submit Date: 07/05/2023

FIR Status:

Inspected Operator Information:

Company Name: CHEVRON USA INC

Company Number: 16700

Address: 760 HORIZON DRIVE STE 401

City: GRAND JUNCTION State: CO Zip: 81506

LOCATION - Location ID: 336708

Location Name: UPRC-64N67W Number: 13CSW County: WELD

Qtrqtr: NESW Sec: 13 Twp: 4N Range: 67W Meridian: 6

Latitude: 40.310139 Longitude: -104.841447

FACILITY - API Number: 05-123-00 Facility ID: 301509

Facility Name: STROH O Number: 13-21D

Qtrqtr: NESW Sec: 13 Twp: 4N Range: 67W Meridian: 6

Latitude: 40.310139 Longitude: -104.841447

CORRECTIVE ACTIONS:

1 CA# 174612

Corrective Action: Weeds need to be removed/cleared. Statewide unnecessary equipment, weeds, waste, and trash requirements. Comply with Rule 606.

Date: 07/12/2023

Response: CA COMPLETED

Date of Completion: 07/20/2023

Operator Comment: Weeds have been cleared. CA complete.

COGCC Decision: _____

COGCC
Representative:

2 CA# 174613

Corrective Action: Netting on open top tanks inadequate. Install or repair wildlife protection equipment.

Date: 07/12/2023

Response: CA COMPLETED

Date of Completion: 07/20/2023

Operator
Comment: Netting repaired. CA complete.

COGCC Decision: _____

COGCC
Representative:

3 CA# 174614

Corrective Action: Regrading is needed. Install or repair required BMPs per Rule 1002.f.(2)C.

Date: 07/12/2023

Response: CA COMPLETED

Date of Completion: 07/20/2023

Operator
Comment: Rills and ruts are repaired. CA complete.

COGCC Decision: _____

COGCC
Representative:

4 CA# 174615

Corrective Action: "For localized stained soils or oily waste - ""Properly dispose of oily waste in accordance with 905.e.""

Date: 07/12/2023

For larger instances: ""Properly dispose of oily waste in accordance with Rule 905.e and contact area COGCC EPS""

Response: CA COMPLETED

Date of Completion: 07/20/2023

Operator
Comment: Leak has been cleaned up and repaired. CA complete.

COGCC Decision: _____

COGCC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: Weeds have been cleared. Netting repaired. Rills and ruts are repaired. Leak has been cleaned up and repaired. CA's complete.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Tyranny Bergin

Signed: _____

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>

Total Attach: 0 Files