

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/27/2023

Submitted Date:

07/27/2023

Document Number:

699107018**FIELD INSPECTION FORM**Loc ID 422860 Inspector Name: Burns, Adam On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 100322

Name of Operator: NOBLE ENERGY INC

Address: 2001 16TH STREET SUITE 900

City: DENVER State: CO Zip: 80202

**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

7 Number of Comments

2 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		rbucogccinspectionreports@c hevron.onmicrosoft.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
422860	LOCATION	AC			-	STOCKLEY C15-79HN	AC

**General Comment:**[This is an inspection on the Tank Battery](#)

**Location**Overall Good: ☒**Signs/Marker:**

Type	TANK LABELS/PLACARDS		
Comment:	Pit sign for middle pit is unreadable. See attached photo.		
Corrective Action:	Install sign to comply with Rule 605.g.	Date:	09/08/2023

**Emergency Contact Number:**

Comment:	Adequate		
Corrective Action:		Date:	

**Good Housekeeping:**

Type	UNUSED EQUIPMENT		
Comment:	Unused equipment in multiple spots needs to be removed for good housekeeping. See attached photos.		
Corrective Action:	Comply with Rule 606	Date:	09/08/2023

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Equipment:**

				corrective date
Type: Gas Meter Run	# 3			
Comment:				
Corrective Action:			Date:	
Type: Horizontal Heated Separator	# 5			
Comment:				
Corrective Action:			Date:	
Type: Bird Protectors	# 8			
Comment:				
Corrective Action:			Date:	
Type: Emission Control Device	# 3			
Comment:				
Corrective Action:			Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	OTHER	PBV CONCRETE		,	
Comment:						
Corrective Action:					Date:	

**Paint**

Condition	
Other (Content)	
Other (Capacity)	48 BBLs
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	2	OTHER	PBV CONCRETE		,
Comment:					
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	60 BBLs
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	7	300 BBLs	STEEL AST		40.306000,-104.545900
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO
Comment:	

Corrective Action:		Date:	
<b>Flaring:</b>			
Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 422860 Type: LOCATION API Number: - Status: AC Insp. Status: AC

**Producing Well**

Comment: Active Tank Battery

Corrective Action:

Date:

**COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary</p> <p>On Thursday 7/27/23 at approximately 0824hrs I, Inspector Adam Burns, Conducted an on-site inspection at Stockley C15-79HN Tank Battery of Chevron. Location ID #422860 in Weld County, Colorado.</p> <p>During this inspection the following possible compliance issues were observed:</p> <p>Pit sign for middle pit is unreadable. Install sign to comply with Rule 605.g. With a Corrective Action date of 9/8/23</p> <p>Unused equipment in multiple spots needs to be removed for good housekeeping. Comply with Rule 606. With a Corrective Action date of 9/8/23</p> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.</p> <p>This is a summary of the inspection report.</p>	burnsa	07/27/2023

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699107019	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6197677">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6197677</a>