

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

07/28/2023

Submitted Date:

07/28/2023

Document Number:

696305171

FIELD INSPECTION FORM

Loc ID 428699 Inspector Name: PETRIE, ERICA On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10671
Name of Operator: EDGE ENERGY II LLC
Address: 600 12TH STREET SUITE 115
City: GOLDEN State: CO Zip: 80401

Findings:

- 12 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Turner, Ben		bturner@edgeenergy1.com	ALL INSPECTIONS
Larsen, Erik		elarsen@edgeenergy1.com	ALL INSPECTIONS
Welch, Kelsi		Kelsi.welch@iptwell.com	ALL INSPECTIONS

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
428700	WELL	SI	02/01/2022	OW	123-35475	WASHBURN GX 15-62HN	SI

General Comment:

[Follow-Up Inspection to FIR 696305077 dated 07.06.2023 and in response to FIRR 403469479 dated 07.19.2023](#)

Location

Overall Good:

Signs/Marker:

Type	BATTERY		
Comment:	Adequate		
Corrective Action:			Date:
Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:			Date:
Type	TANK LABELS/PLACARDS		
Comment:	Adequate - 300 BBIs Produced Water Tank now has Adequate Capacity Label		
Corrective Action:			Date:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type	UNUSED EQUIPMENT		
Comment:	Riser at ECD has been marked		
Corrective Action:			Date:
Type	WEEDS		
Comment:	Tumbleweed Debris at South Separator and East of Separators - NOTE ALL TUMBLEWEED DEBRIS MUST BE REMOVED FROM ENTIRE LOCATION. CHECK AT REGULAR INTERVALS TO INSURE TUMBLEWEED DEBRIS DOES NOT ACCUMULATE. See Photos		
Corrective Action:	Comply with Rule 606		Date: 08/11/2023
Type	WEEDS		
Comment:	Weeds REMAIN at ECD and East of ECD Overhead Line - NOTE ALL WEEDS MUST BE CUT DOWN OR REMOVE ON ENTIRE LOCATION. See photos		
Corrective Action:	Comply with Rule 606		Date: 08/11/2023

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

--

Multiple Spills and Releases?

Venting:

Yes/No			
Comment:			
Corrective Action:			Date:

Flaring:

Type		
------	--	--

Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 428700 Type: WELL API Number: 123-35475 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment:

Corrective Action: Date: _____

COGCC Comments

Comment	User	Date
Routine Field Follow-Up Inspection. Tumbleweeds at South Separator and East of Separator Berm. Weeds STILL REMAIN at ECD and East of ECD Overhead Line. * NOTE ALL WEEDS MUST BE CUT DOWN OR REMOVE ON ENTIRE LOCATION * NOTE ALL TUMBLEWEED DEBRIS MUST BE REMOVED FROM ENTIRE LOCATION. CHECK AT REGULAR INTERVALS TO INSURE TUMBLEWEED DEBRIS DOES NOT ACCUMULATE	petrie	07/28/2023

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696305172	Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6198362