

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/13/2023

Submitted Date:

08/01/2023

Document Number:

694100132

FIELD INSPECTION FORMLoc ID 327014 Inspector Name: Robinson, Taylor On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 16700

Name of Operator: CHEVRON USA INC

Address: 760 HORIZON DRIVE STE 401

City: GRAND JUNCTION State: CO Zip: 81506

Status Summary:☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

5 Number of Comments

2 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Dougherty, Tesla		tesla.dougherty@chevron.com	Regulatory Specialist
,		rbucogccinspectionreports@chevron.onmicrosoft.com	
,		rbucogccinspectionreports@chevron.onmicrosoft.com	All Inspections

General Comment:

This is an environmental inspection for Location ID 327104 Noble Lesser PM J 33-2, 7, 7A. Please note, this is a shut in location. Any corrective actions from previous inspections that have not been addressed are still applicable. There were no operator or contract environmental personnel on location at the time of this field inspection. Photos attached to document site conditions.

LocationOverall Good: ☐

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type

Comment:

Weeds present throughout location. Statewide unnecessary equipment, weeds, waste, and trash requirements.

Corrective Action:

Comply with Rule 606

Date: 08/08/2023

Overall Good: ☐**Spills:**

Type

Area

Volume

In Containment: No

Comment:

No indication of spills during this inspection.

☐ Multiple Spills and Releases?**Venting:**

Yes/No

Comment:

Corrective Action:

Date:

Flaring:

Type

Comment:

Corrective Action:

Date:

Location Construction

Location ID: 327014 CDP: _____

Comment: _____

Corrective Action: _____

Date: _____

Form 2A COAs:**Comment:** _____

Corrective Action: _____

Date: _____

Wildlife BMPs:**Comment:** _____

Corrective Action: _____

Date: _____

Comment: Large washout and rills. Sediment traveling off location. Stormwater management Erosion Control needed.**Corrective Action:** Needs to be filled in, regraded and off location sediment needs to be cleaned up and retained on site. Install or repair required BMPs per Rule 1002.f.(2)C.

Date: 08/15/2023

On Site Inspection (305):Surface Owner Contact Information:

Name: _____

Address: _____

Phone Number: _____

Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____

Phone Number: _____

Date Onsite Request Received: _____

Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____

Phone Number: _____

Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
694100133	Photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6201427