

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/19/2023

Submitted Date:

07/27/2023

Document Number:

697602145

FIELD INSPECTION FORMLoc ID 332971 Inspector Name: Ahmadian, Alexander On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 46290

Name of Operator: KP KAUFFMAN COMPANY INC

Address: 1700 LINCOLN ST STE 4550

City: DENVER State: CO Zip: 80203

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

9 Number of Comments

4 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Graber, Nikki		nikki.graber@state.co.us	
, KPK		cogcc@kpk.com	All Inspections
Watzman, Ross	(303) 825-4822	rwatzman@kpk.com	all inspections.
Anderson, Laurel		laurel.anderson@state.co.us	
Brown, Kari		kari.oakman@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
239987	WELL	SI	11/01/2021	OW	123-07775	HLADKY-O'GORMAN 3	EI

General Comment:

This is an environmental inspection for Facility ID 239987. Any corrective actions from previous inspections that have not been addressed are still applicable.

There were no operator or contract environmental personnel on location at the time of this field inspection. The landowner met me onsite to discuss the spill and other related matters.

Photos attached to document site conditions.

LocationOverall Good: ☐

Emergency Contact Number:

Comment: Corrective Action: Date: **Good Housekeeping:**

Type	TRASH		
Comment:	Orange construction fencing has completely torn and is on the ground as trash.		
Corrective Action:	Comply with housekeeping Rule 606.		Date: 08/03/2023
Type	WEEDS		
Comment:	Weeds are overgrown around the wellhead.		
Corrective Action:	Comply with Rule 606.		Date: 08/11/2023

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Fencing/:**

Type	WELLHEAD		
Comment:	Orange fencing surrounding the wellhead has completely torn and the spill is exposed.		
Corrective Action:	Fencing is not in compliance. The operator is to maintain best management practices to control and contain all spills/releases of E&P waste to protect the environment, public health, safety and welfare and the environment as required by rule 913.b(5)B.i which requires that Operators will fence or cover open remediation excavations to prevent access when sites are not attended.		Date: 08/03/2023

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Environmental**Spill/Remediation:**

Comment: Water has pooled around the wellhead where the initial spill was located. No sheen was observed on the water. Remediation has not been worked on since initial response.

Corrective Action: In accordance with 913.d.(1) Operator will investigate impacts to soil, Groundwater, and surface water as soon as the impacts are discovered.

Date: 07/31/2023

Emission Control Burner (ECB):

Comment:

Pilot: Wildlife Protection Devices (fired vessels):

COGCC Comments

Comment	User	Date
Site conditions are very poor. Immediate response is needed by the Operator.	ahmadiiaa	07/27/2023

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403479342	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6197546
697602146	Photolog	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6197540